

Inspector: Harding, Rich
 Inspection Date: 11/28/2023

Structure Number: 8504598
 Facility Carried: SR 241

Ohio Bridge Inspection Summary Report

WAY-00241-0436 (8504598)

2: District 59556 - PAINT TWP (WAY county)
 District 03

5A: Inventory Route 1 00241

21: Major Maint A/B 01 - State Highway Agency /
 225 Routine Main A/B 01 - State Highway Agency /
 221 Inspection A/B 01 - State Highway Agency /
 220: Inv. Location DISTRICT 03

7: Facility On SR 241
 6: Feature Ints TRIB OF N FORK CREEK
 9: Location 2.81 MILES S OF STARK CO
 Lat, Lon 40.707609 , -81.682951

Condition	
58: Deck	N - Not Applicable
58.01 Wearing Surface	N - Not Applicable
58.02 Joint	N - Not Applicable
59: Superstructure	N - Not Applicable
59.01 Paint & PCS	N - Not Applicable
60: Substructure	N - Not Applicable
61: Channel	4
61.01 Scour	7 - Good
62: Culverts	5 - Moderate to major deterioration
67.01 GA	5

Structure Type	
43: Bridge Type	3 - Steel
	19 - Culvert (includes frame culverts)
	N - Not Applicable
45: Spans Main / Approach	1 / 0
107: Deck Type	N - Not Applicable
408: Composite Deck	X - Not Applicable
414A Joint Type 1	N - None
414B: Joint Type 2	N - None
108A: Wearing Surface	N - NA
	N - Not Applicable
422: WS Date	07/01/2018
423: WS Thick (in)	0.0
482: Protective Coating	N - None or Not Applicable
483: PCS Date	
453: Bearing Type 1	N - None
455: Bearing Type 2	N - None
528: Foundn: Abut Fwd	N - None (Such as most Culverts)
533: Foundn: Abut Rear	N - None (such as most Culverts)
536: Foundn: Pier 1	N - None (Such as most Culverts)
539: Foundn: Pier 2	N - None (Such as most Culverts)

Appraisal	
Sufficiency Rating	87.1 SD/FO 0 - ND
36: Rail, Tr, Gd, Term Std	N N 1 1
72: Approach Alignment	6 - Equal to present minimum criteria
113: Scour Critical	8 - Stable for scour conditions
71: Waterway Adequacy	7 - Slight Chance of Overtopping Bridge

Geometric	
48: Max Span Length (ft)	13.0
49: Structure Length (ft)	14.0
52: Deck Width, Out-To-Out (ft)	0.0
424: Deck Area (sf)	476
32: Appr Roadway Width (ft)	34.0
51: Road Width, Curb-Curb (ft)	0.0
50A: Curb/SW Width: Left (ft)	0
50A: Curb/SW Width: Right (ft)	0
34: Skew (deg)	40
33: Bridge Median	0 - No median
54B: Min Vert Underclearance (ft)	0
336A: Min Vert Clrnce IR Cardinal (ft)	99
336B: Min V Clr IR Non-Cardinal (ft)	0
578: Culvert Length (ft)	69

Age and Service	
27: Year Built/ 106 Rehab	1964 / 0000
42A: Service On	1 - Highway
42B: Service Under	5 - Waterway
28A: Lanes on	02
28B: Lanes Under	00
19: Bypass Length	7
29: ADT	3141
109: % Trucks (%)	11

Load Posting	
41: Op/Post/Closed	A - Open
70: Posting	5 - Equal to or above legal loads
70.01: Date	
70.02: Sign Type	
734: Percent Legal (%)	150
704: Analysis Date	07/01/2002
63: Analysis Method	6 - Load Factor (LF) rating reported by rating factor (RF) method using MS18 loading.

Inspections		
	Months	
90: Routine Insp.	12	11/28/2023
92A: FCM Insp.	N	0
92B: Dive Insp.	N	0
92C: Special Insp.	N	0
92D: UBIT Insp.	N	0
92E: Drone Insp.	N	0

Inspector Harding, Rich

Inspector: Harding, Rich
 Inspection Date: 11/28/2023

Structure Number: 8504598
 Facility Carried: SR 241

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
240-Steel Culvert	3 - Mod.	69	ft.	0	34	35	0
	CS2-2020 Both fwd. & rear: Additional approx. 1' interior face of pipe above radius bolt lines exposed full length due to high water event (previously buried w/ creek gravel build-up) CS3-2022 Moderate to heavy flaky rust full length (bottom radius bolt lines not visible due to gavel build-up);						
835-Culvert End Treatment	3 - Mod.	4	each	3	1	0	0
	CS2-2020 Fwd. lt.: minor deterioration @ jct. w/ pipe; all others not visible - covered w/ embankment material						
845-Roadway Over Structure	3 - Mod.	1	each	1	0	0	0

Inspector: Harding, Rich

Structure Number: 8504598

Inspection Date: 11/28/2023

Facility Carried: SR 241

ODOT District: District 03

WAY-00241-0436 _(8504598)

Date Built: 07/01/1964

Major Maint: 01 - State Highway Agency

Facility Carried: SR 241

Traffic On: 1 - Highway

Rehab Date:

Routine Maint: 01 - State Highway Agency

Feature Inters: TRIB OF N FORK CREEK

Traffic Under: 5 - Waterway

Insp. 01 - State Highway Agency

FIPS Code: 59556 - PAINT TWP (WAY county)

Location: DISTRICT 03

2.81 MILES S OF STARK CO

Resp A:

Inspector

Harding, Rich

Inspection Date 11/28/2023

Reviewer Kapustar, Kent

Insp

Resp B:

Inspector Comments - Deck and Approach

Deck

Approach

Approach Wearing Surface (EA)

2018 New asphalt resurfacing w/ Proj.#583(17) - Previously some scattered cracks (trans. & along edges - some w/ large crack width); 2008 new asphalt resurfacing w/ proj.#477(07) - some rutting in wheel tracks & along edge of pavt. & berm material.

Approach Embankment (EA)

Fwd. lt.: some minor slumping; fwd. rt. near pipe minor erosion

Approach Guardrail (EA)

2018 Several new posts & a couple new panels w/ Proj.; 2014-2015 Repaired - Previously rear lt. end assembly w/ collision damage; fwd. lt.: leaning outward slightly plus some previous & current collision damage.

Inspector Comments - General Appraisal

Superstructure

Utilities (LF)

Rt.side under pipe @ inlet: Buried underground telephone cable (Warning sign visible).

Substructure

Culvert

Culvert General (LF)

Culvert Alignment (LF)

Culvert Shape (LF)

Some minor flattening in top w/ minor cusping (possibly "as built").

Inspector: Harding, Rich

Structure Number: 8504598

Inspection Date: 11/28/2023

Facility Carried: SR 241

Culvert Seams (EA)

Top 3 seams w/ areas of leakage & some scattered bolts w/ flaky rust.

Culvert Headwall/Endwall (EA)

Inspector Comments - Waterway

Waterway Adequacy

Channel Hydraulic Opening (EA)

2019 Some reduction of interior build-up due to high water event - Previously some channel debris inside pipe; Sand / gravel bars @ inlet / outlet w/ vegetation (previously trees & brush removed); previously 3'+/- of gravel build-up full length of pipe - 40% reduced capacity - build-up now reduced; inlet: wire farm panel across channel approx. 20' upstream from pipe.

Channel

Channel Alignment (LF)

Large sweeping curve in upstream alignment w/ erosion of fwd. embankment (alignment beyond pipe opening) - approx. 45 degree angle back toward pipe then 45 degree angle @ entry into pipe - flow directed @ rear rt. & along rear face then splitting half way through & flowing along both fwd. & rear face.

Channel Protection (LF)

Moderate to severe erosion of upstream embankment. 2019 Downstream channel outside R/W cleaned / material removed.

Scour Critical

Inspector: Rich Harding

Structure Number: 8504598

Inspection Date: 11/28/2023

Facility Carried: SR 241

Bridge Inspection Report

Pictures