

Design Exception Request

FAY-435/VAR-1.52/VAR

PID: 117955; Request 01

Letting Type: ODOT-Let

Design Designation

FAY-435; 2.2-2.4

Current ADT (2024)	15,780	Td	0
Design Year ADT (2044)	27,300	Design Speed	60
Design Hourly Volume (2044)	3,270	Legal Speed	55
Directional Distribution	67%	Design Functional Class	5 - Major Collector Roads
Trucks (24hr B&C)	17%	Functional Class Area Type	Rural
		NHS Project	No




Submitted By:

Jeff Hipp
(Engineer of Record)

Approved by:

Timothy Keller

Approval Date: 12/22/2022



Engineer of Record Seal

Design Exception Request

FAY-435/VAR-1.52/VAR

PID: 117955; Request 01

Controlling Criteria Identification

Section: FAY-435; 2.2-2.4

Controlling Criteria	Standard	Existing (a.)	Proposed
Lane Width			
Shoulder Width			
Horizontal Curve Radius			
Maximum Grade			
SSD (Horizontal & Crest Vertical)			
Pavement Cross Slope			
Superelevation Rate			
Vertical Clearance			
Design Loading Structural Capacity	Inventory > 1.00 for HL-93 Design Loading	Existing Inventory 1.099	Existing bridge will have new overlay shifting the crown to center of the bridge to accommodate 4 lanes of traffic. New overlay thickness was modeled in BrR and updated BR100 is attached. New inventory rating for HL-93 is 0.969 and operating 2.309. All legal and permit vehicles Operating Factors exceed 1.00.

(a.) "Existing" may be N/A (i.e. New alignment or new ramp)

Project Description

0

Section Description

See Project Description

Proposed Mitigation

None

Support for Deviation (Benefit-cost, R/W, Environmental, Constructability, Coordination with Other Projects, Relationship between any crash patterns and proposed design exception, etc.):

The district explored the option of maintaining the existing crown across the bridge; however, Green Book 4.2.2.1 states that trucks with high centers of gravity crossing over the crown line may sway from side to side when traveling high speed making it more difficult to maintain control. Additionally, L&D 301.1.5 states that undivided pavement sections are to be crowned at the middle when the number of lanes is even. Due to the relatively simple nature and cost to adjust the crown on the superstructure of a semi integral bridge, we feel this shift in crown is appropriate.

Does the requested Design Exception location fall within a Safety Integrated Project (SIP) Map Location?

No

Does the crash analysis (GCAT and CAM Tool) show any patterns that would be adversely impacted by the proposed Design Exception?

#N/A