



UNDERWATER BRIDGE INSPECTION REPORT

STRUCTURE NO. 3502384 (HEN-108-1561)
SR 108 OVER MAUMEE RIVER
HENRY COUNTY, OH
DISTRICT 2

April 2020

Prepared for:



10/09/2020

Prepared by:

COLLINS
ENGINEERS INC.

124 Venture Court, Suite 10

Lexington, Kentucky 40511

859.367.0097 • www.collinsengr.com



TABLE OF CONTENTS

EXECUTIVE SUMMARY

1.0 INTRODUCTION 1

 1.1 Purpose and Scope 1

 1.2 General Description of the Structure 1

 1.3 Method of Investigation 1

2.0 EXISTING CONDITIONS 2

 2.1 General Conditions 2

 2.2 Substructure Conditions 3

 2.2.1 Pier 1 3

 2.2.2 Pier 2 3

 2.2.3 Pier 3 3

 2.2.4 Pier 4 4

 2.2.5 Pier 5 4

 2.2.6 Pier 6 4

3.0 EVALUATION AND RECOMMENDATIONS 5

EXHIBIT 1 – FIGURES 6

 LOCATION MAP

 SOUNDING PLAN

 CHANNEL CROSS SECTIONS - UPSTREAM

 CHANNEL CROSS SECTIONS - CENTERLINE

 CHANNEL CROSS SECTIONS - DOWNSTREAM

 PIER 1

 PIER 2

 PIER 3

 PIER 4

 PIER 5

 PIER 6

EXHIBIT 2 – INSPECTION PHOTOGRAPHS 18

 Photograph No. 1: Overall View of Structure No. 3502384 (HEN-108-1561), Looking East.

 Photograph No. 2: Overall View of Structure No. 3502384 (HEN-108-1561), Looking West.

 Photograph No. 3: View of the North Embankment Upstream of the Structure, Looking Northwest.

 Photograph No. 4: View of the North Embankment at the Structure, Looking North.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



-
- Photograph No. 5: View of the North Embankment Downstream of the Structure, Looking Northeast.
 - Photograph No. 6: View of the South Embankment Upstream of the Structure, Looking Southwest.
 - Photograph No. 7: View of the South Embankment at the Structure, Looking South.
 - Photograph No. 8: View of the South Embankment Downstream of the Structure, Looking Southeast.
 - Photograph No. 9: View of the North Face of Pier 1, Looking Southwest.
 - Photograph No. 10: View of the South Face of Pier 1, Looking Northeast.
 - Photograph No. 11: View of the North Face of Pier 2, Looking Southwest.
 - Photograph No. 12: View of the South Face of Pier 2, Looking Northeast.
 - Photograph No. 13: View of the North Face of Pier 3, Looking Southwest.
 - Photograph No. 14: View of the South Face of Pier 3, Looking Northeast.
 - Photograph No. 15: View of the Spall on the Uptream Nose of Pier 3, Looking East.
 - Photograph No. 16: View of the North Face of Pier 4, Looking Southwest.
 - Photograph No. 17: View of the South Face of Pier 4, Looking Northeast.
 - Photograph No. 18: View of the North Face of Pier 5, Looking Southwest.
 - Photograph No. 19: View of the South Face of Pier 5, Looking Northeast.
 - Photograph No. 20: View of the North Face of Pier 6, Looking Southwest.
 - Photograph No. 21: View of the South Face of Pier 6, Looking Northeast.
 - Photograph No. 22: View of the Typical Concrete and Steel Condition at the Waterline on the Upstream Nose of Pier 6, Looking East.

EXHIBIT 3 – UNDERWATER DIVE INSPECTION PROCEDURE CHECKLIST30

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)
Henry County, OH • April 2020



EXECUTIVE SUMMARY

Project:	ODOT District 2 Underwater Bridge Inspections - 2020		
Purpose of Project:	To perform a detailed visual and tactile underwater investigation of bridges for District 2 of the Ohio Department of Transportation.		
Inspection Team:	Team Leader – Joshua Johnson, P.E. – Collins Engineers, Inc. Team Member – Matthew Rogers, E.I.T. – Collins Engineers, Inc. Team Member – Nicholas Lane – Collins Engineers, Inc.		
Inspection Date(s):	April 25, 2020		
Water Visibility:	<1 ft	Water Velocity:	<1 ft/s
Water Temperature:	53 °F	Weather:	Overcast – 45 °F
Waterline Elevation:	638.5 ft	Type of Boat:	23 ft Carolina Skiff
Coordinates:	41.387614°N, 84.122462°W		
Access Location:	Ritter Park Public Boat Ramp		
Dive Mode:	Surface Supplied Air		
Waterline Reference:	17.8 ft below the top of cap at the downstream nose of Pier 4.		
Maximum Depth at SSU:	10.0 ft – Southeast corner of Pier 5		
Shoreline Conditions:	The north and south shorelines consisted of moderately vegetated mild slopes that were well protected with no signs of erosion.		

Summary of Findings:

- **Pier 1:**
 - Channel bottom material consisted of sand, gravel, and scattered rip-rap up to 24 in. diameter with no probe rod penetration.
 - The submerged portions of the pier typically exhibited light scaling up to 1/16 in. deep.
 - Steel ice breaker exhibited light surface corrosion with no measurable loss of section.
 - A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 1 ft vertical by 6 in. horizontal with no exposed steel reinforcement.
 - Area of poorly consolidated concrete was observed at a cold joint on the upstream and downstream nose measuring approximately 3 ft vertical by 18 in. deep with no exposed steel reinforcement.
- **Pier 2:**
 - Channel bottom material consisted of sand, gravel, and scattered rip-rap up to 24 in. diameter with no probe rod penetration.
 - The submerged portions of the pier typically exhibited light scaling up to 1/16 in. deep.
 - Steel ice breaker exhibited light surface corrosion with no measurable loss of section.
 - A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 1 ft vertical by 6 in. horizontal with no exposed steel reinforcement.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



-
- Area of poorly consolidated concrete was observed at a cold joint on the upstream and downstream nose measuring approximately 3 ft vertical by 18 in. deep with no exposed steel reinforcement.
 - **Pier 3:**
 - Channel bottom material consisted of sand, gravel, and scattered rip-rap up to 24 in. diameter with no probe rod penetration.
 - The submerged portions of the pier typically exhibited light scaling up to 1/16 in. deep.
 - Steel ice breaker exhibited light surface corrosion with no measurable loss of section.
 - A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 3 ft vertical by 18 in. horizontal with 3 horizontal and numerous vertical steel reinforcement exposed exhibiting no section loss due to epoxy coating.
 - **Pier 4:**
 - Channel bottom material consisted of sand, gravel, and scattered rip-rap up to 24 in. diameter with no probe rod penetration.
 - The submerged portions of the pier typically exhibited light scaling up to 1/16 in. deep.
 - Steel ice breaker exhibited light surface corrosion with no measurable loss of section.
 - A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 3 ft vertical by 18 in. horizontal with 3 horizontal and numerous vertical steel reinforcement exposed exhibiting no section loss due to epoxy coating.
 - Light timber debris consisting of logs up to 6 in. diameter was observed on the channel bottom at the upstream nose extending up to a 5 ft radius around the nose.
 - **Pier 5:**
 - Channel bottom material consisted of sand, gravel, and scattered rip-rap up to 24 in. diameter with no probe rod penetration.
 - The submerged portions of the pier typically exhibited light scaling up to 1/16 in. deep.
 - Steel ice breaker exhibited light surface corrosion with no measurable loss of section.
 - A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 1 ft vertical by 6 in. horizontal with no exposed steel reinforcement.
 - Area of poorly consolidated concrete was observed at a cold joint on the upstream and downstream nose measuring approximately 3 ft vertical by 18 in. deep with no exposed steel reinforcement.
 - **Pier 6:**
 - Channel bottom material consisted of sand, gravel, and scattered rip-rap up to 24 in. diameter with no probe rod penetration.
 - The submerged portions of the pier typically exhibited light scaling up to 1/16 in. deep.
 - Steel ice breaker exhibited light surface corrosion with no measurable loss of section.
 - A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 1 ft vertical by 6 in. horizontal with no exposed steel reinforcement.
-

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



-
- Area of poorly consolidated concrete was observed at a cold joint on the upstream and downstream nose measuring approximately 3 ft vertical by 18 in. deep with no exposed steel reinforcement.

Summary of Recommendations:

- Monitor timber debris accumulation at Pier 4.
- Repair areas of poor concrete consolidation at all piers.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



Underwater Inspection Coding:

NBI Ratings:

Item	Description	Coding	Condition
60	Substructure	7 – Good Condition	Spall, Poor Concrete Consolidation, Light Concrete Scaling
61	Channel	7 – Good Condition	Minor Timber Debris Accumulation
62	Culvert	N/A	
92B	UW Insp. Frequency	60 Months	
93B	Previous Insp. Date	4/25/2020	
113	Scour Critical Bridges	5 – Within Foundation Limits	Stable (Inspector Recommended)

AASHTO National Bridge Element (NBE) Ratings:

Element #	Description	Units	Total	Condition State			
				1	2	3	4
210	Reinforced Concrete Pier Wall	LF	450	0	450	0	0
220	Reinforced Concrete Pile Cap / Footing	LF	450	450	0	0	0

Note: Ratings were developed using the FHWA Recording and Coding Guide for the Structure Inventory and Appraisal of the Nation's Bridges. The recommended ratings consider inspected elements located within the waterway and conditions existing below the water surface only. Additional consideration is necessary for the assignment of overall condition ratings for this bridge.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)
Henry County, OH • April 2020



1.0 INTRODUCTION

1.1 Purpose and Scope

This report consists of the results of a detailed underwater investigation performed at the SR 108 Bridge over Maumee River in Henry County, OH. Collins Engineers, Inc. (Collins) conducted the underwater investigation for District 2 of the Ohio Department of Transportation (ODOT) on April 25, 2020. The primary purpose of the investigation was as follows:

- Determine the condition of the substructure components located in the water at the time of the inspection from the waterline to the channel bottom.
- Obtain channel bottom depth measurements along the bridge fascias, upstream and downstream of the bridge, and around the submerged substructure units.
- Obtain channel profile cross sections at the upstream and downstream fascias.
- Determine the condition of the shorelines in the vicinity of the structure.
- Obtain photographs of the bridge and any significant defects.

In addition, a brief inspection was made of areas that could be submerged during periods of high water. The following report includes a description of the structure, the method of investigation, a description of existing conditions, an evaluation and recommendations based on the conditions, inspection figures, and photographs.

1.2 General Description of the Structure

Structure No. 3502384 (HEN-108-1561) spans 700 ft, carrying SR 108 over Maumee River and is approximately 26.5 ft wide. The bridge superstructure is constructed of seven prestressed concrete girder spans. The roadway orientation of the longitudinal axis of the bridge is south to north. The substructure units are labeled as Abutments 1 and 2 and Piers 1 through 6. Existing design drawings were not available at the time of the inspection. Refer to Figure 1 in Exhibit 1 for a Location Map of the bridge. Refer to Photographs 1 and 2 in Exhibit 2 for overall views of the bridge.

1.3 Method of Investigation

A detailed field inspection was conducted to determine the physical condition of the submerged bridge substructure units from the waterline to the channel bottom. A brief visual examination of the substructure units above the waterline was also made.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)
Henry County, OH • April 2020



A three-person team consisting of a professional engineer-diver and team leader (Joshua Johnson, P.E.) an engineer diver (Matthew Rogers, E.I.T.) and an engineer-technician (Nicholas Lane) conducted the underwater inspection. The inspection was conducted using surface supplied air diving equipment. During the inspection, the inspectors worked from a boat and a note taker in the boat recorded the inspection notes.

The underwater inspection consisted of a visual and tactile examination of the accessible surfaces of the substructure units from the waterline to the channel bottom with particular attention given to any observed areas of deterioration or apparent distress. Approximately 10 percent of the total area on the underwater surfaces of the substructure units was cleaned so that the condition could be more closely examined. Photographs were taken to document the general conditions and observed deficiencies. Underwater photographs could not be obtained due to poor water conditions. The type of channel bottom material, the presence or extent of scour, the presence or extent of riprap, the presence or extent of drift and debris, and the location of any foundation exposure or undermining were noted.

Channel bottom soundings were performed utilizing a telescoping survey rod, digital fathometer, and pneumofathometer. Soundings were collected at quarter points along the bridge centerline as well as at quarter points along the upstream and downstream fascias and 50 ft fascias. Additional soundings were collected adjacent to Piers 1 through 6 and at 10 foot intervals in-line with the piers, upstream and downstream, and the waterline was referenced to a known elevation on the bridge. A sounding plan was developed using the soundings and approximate location of the shorelines. Refer to Figures 2 through 5 in Exhibit 1 for the sounding plan and channel cross sections that show the channel limits and water depths around the structure.

2.0 EXISTING CONDITIONS

2.1 General Conditions

At the time of the inspection, the waterline of 3502384 (HEN-108-1561) was located approximately 17.8 ft below the top of cap at the downstream nose of Pier 4, which corresponds to a waterline elevation of 638.5 ft. During the inspection, the waterway was flowing at approximately <1 ft per second. The bridge pier skew was consistent with the channel alignment and does not require attention at this time. The north and south shorelines consisted of moderately vegetated mild slopes that were well protected with no signs of erosion. Refer to Photographs 3 through 8 in Exhibit 2 for views of the shorelines near the structure.



2.2 Substructure Conditions

2.2.1 *Pier 1*

The channel bottom material consisted of sand, gravel, and scattered rip-rap up to 24 in. diameter with no probe rod penetration. The submerged portions of the pier typically exhibited light scaling up to 1/16 in. deep. Steel ice breaker exhibited light surface corrosion with no measurable loss of section. A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 1 ft vertical by 6 in. horizontal with no exposed steel reinforcement. Area of poorly consolidated concrete was observed at a cold joint on the upstream and downstream nose measuring approximately 3 ft vertical by 18 in. deep with no exposed steel reinforcement. Refer to Figure 6 in Exhibit 1 for detailed inspection notes of Pier 1. Refer to Photographs 9 and 10 in Exhibit 2 for views of Pier 1.

2.2.2 *Pier 2*

The channel bottom material consisted of sand, gravel, and scattered rip-rap up to 24 in. diameter with no probe rod penetration. The submerged portions of the pier typically exhibited light scaling up to 1/16 in. deep. Steel ice breaker exhibited light surface corrosion with no measurable loss of section. A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 1 ft vertical by 6 in. horizontal with no exposed steel reinforcement. Area of poorly consolidated concrete was observed at a cold joint on the upstream and downstream nose measuring approximately 3 ft vertical by 18 in. deep with no exposed steel reinforcement. Refer to Figure 7 in Exhibit 1 for detailed inspection notes of Pier 2. Refer to Photographs 11 and 12 in Exhibit 2 for views of Pier 2.

2.2.3 *Pier 3*

The channel bottom material consisted of sand, gravel, and scattered rip-rap up to 24 in. diameter with no probe rod penetration. The submerged portions of the pier typically exhibited light scaling up to 1/16 in. deep. Steel ice breaker exhibited light surface corrosion with no measurable loss of section. A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 3 ft vertical by 18 in. horizontal with 3 horizontal and numerous vertical steel reinforcement exposed exhibiting no section loss due to epoxy coating. Refer to Figure 8 in Exhibit 1 for detailed inspection notes of Pier 3. Refer to Photographs 13 through 15 in Exhibit 2 for views of Pier 3.



2.2.4 Pier 4

The channel bottom material consisted of sand, gravel, and scattered rip-rap up to 24 in. diameter with no probe rod penetration. The submerged portions of the pier typically exhibited light scaling up to 1/16 in. deep. Steel ice breaker exhibited light surface corrosion with no measurable loss of section. A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 3 ft vertical by 18 in. horizontal with 3 horizontal and numerous vertical steel reinforcement exposed exhibiting no section loss due to epoxy coating. Light timber debris consisting of logs up to 6 in. diameter was observed on the channel bottom at the upstream nose extending up to a 5 ft radius around the nose. Refer to Figure 9 in Exhibit 1 for detailed inspection notes of Pier 4. Refer to Photographs 16 and 17 in Exhibit 2 for views of Pier 4.

2.2.5 Pier 5

The channel bottom material consisted of sand, gravel, and scattered rip-rap up to 24 in. diameter with no probe rod penetration. The submerged portions of the pier typically exhibited light scaling up to 1/16 in. deep. Steel ice breaker exhibited light surface corrosion with no measurable loss of section. A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 1 ft vertical by 6 in. horizontal with no exposed steel reinforcement. Area of poorly consolidated concrete was observed at a cold joint on the upstream and downstream nose measuring approximately 3 ft vertical by 18 in. deep with no exposed steel reinforcement. Refer to Figure 10 in Exhibit 1 for detailed inspection notes of Pier 5. Refer to Photographs 18 and 19 in Exhibit 2 for views of Pier 5.

2.2.6 Pier 6

The channel bottom material consisted of sand, gravel, and scattered rip-rap up to 24 in. diameter with no probe rod penetration. The submerged portions of the pier typically exhibited light scaling up to 1/16 in. deep. Steel ice breaker exhibited light surface corrosion with no measurable loss of section. A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 1 ft vertical by 6 in. horizontal with no exposed steel reinforcement. Area of poorly consolidated concrete was observed at a cold joint on the upstream and downstream nose measuring approximately 3 ft vertical by 18 in. deep with no exposed steel reinforcement. Refer to Figure 11 in Exhibit 1 for detailed inspection notes of Pier 6. Refer to Photographs 20 through 22 in Exhibit 2 for views of Pier 6 and typical concrete condition at the waterline.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



3.0 EVALUATION AND RECOMMENDATIONS

Overall, the inspected substructure units of Structure No. 3502384 (HEN-108-1561) were in good condition. A comparison of the soundings recorded during the previous inspection on June 24, 2015 and the soundings taken during this inspection revealed no significant change in the channel bottom profile in the vicinity of the structure. **The spalls and areas of poor concrete consolidation at Piers 1 through 6 should be repaired at this time.** The repairs should include removal of unsound concrete to a minimum of 1 inch behind the reinforcing steel, cleaning and replacing reinforcing steel as required, and placing concrete designed to provide high durability with low permeability.

The timber debris accumulation at Pier 4 did not significantly affect the channel flow, and as a result, does not require removal at this time. If the debris accumulation increases in size or density, it may be necessary to remove the debris to reduce excessive lateral loads on the pier, limit further debris accumulation, and reduce the likelihood of channel bottom degradation resulting from obstructed flow.

It is recommended that the submerged substructure units of Structure No. 3502384 (HEN-108-1561) be next inspected underwater at an interval not to exceed 60 months, no later than April 25, 2025.

Respectfully Submitted,
COLLINS ENGINEERS, INC.

A handwritten signature in black ink, appearing to read "J. Johnson".

Joshua Johnson, P.E.
Project Manager

Originated by:
Kevin Mitchell, E.I.T.


UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



EXHIBIT 1 – FIGURES



**COLLINS
ENGINEERS**

124 Venture Court, Ste 10
Lexington, KY 40511
Phone: 859-367-0097
Fax: 859-367-0140



Ohio Department of
Transportation, District 2
317 East Poe Rd.
Bowling Green, OH 45601
Phone: 419-353-8131

SR-108 OVER MAUMEE RIVER
STRUCTURE NO. 3502384
(HEN-108-1561)
LOCATION MAP
HENRY COUNTY, OHIO

INSPECTED BY:
MOR

CEI PROJECT:
55-12239.00

DRAWN BY:
MOR

DATE:
21 APR 2020

CHECKED BY:
JMJ

SHEET NO:
1

50 ft Upstream

10 ft Upstream

Upstream Fascia

To Holgate, OH

Bridge


Downstream Fascia

10 ft Downstream

50 ft Downstream

Abutment 1
(Rear Abutment)

Abutment 2
(Forward Abutment)



SOUNDING PLAN

GENERAL NOTES:

1. Piers 1 through 6 were inspected underwater. Substructure units are labeled according to available record drawings.
2. At the time of inspection on April 21, 2020, the waterline was located approximately 17.8 ft below top of cap at downstream nose of Pier 4 (EL. +638.5 ft). This corresponds with a waterline elevation of +620.7 ft.
3. Soundings indicate the water depth at the time of inspection and are measured in feet.
4. Soundings were taken parallel to the bridge at the upstream and downstream fascias, at 10 ft intervals between the substructure units, and at 10 ft intervals in-line with the piers upstream and downstream up to 50 ft.

LEGEND

- 2.7 Sounding Depth from Waterline (ft)
- Timber Debris

COLLINS ENGINEERS
 124 Venture Court, Ste 10
 Lexington, KY 40511
 Phone: 859-367-0097
 Fax: 859-367-0140

Ohio Department of Transportation, District 2
 317 East Poe Rd.
 Bowling Green, OH 45601
 Phone: 419-353-8131



SR-108 OVER MAUMEE RIVER
 STRUCTURE NO. 3502384 (HEN-108-1561)
 SOUNDING PLAN
 HENRY COUNTY, OHIO

CEI PROJECT
 55-12239.00
 INSPECTED BY:
 MOR
 DRAWN BY:
 MOR
 CHECKED BY:
 JMJ
 DATE:
 APR 2020
 SHEET NO:
 2

UPSTREAM FASCIA
LOOKING DOWNSTREAM

Location	Y(ft)*
A2	24.7
1/4	30.0
1/2	35.2
3/4	40.4
P6	38.3
1/4	42.9
1/2	42.2
3/4	44.1
P5	39.5
1/4	46.6
1/2	46.9
3/4	47.6
P4	39.8
1/4	46.4
1/2	47.7
3/4	45.2
P3	43.5
1/4	47.6
1/2	45.7
3/4	45.5
P2	42.0
1/4	43.8
1/2	43.6
3/4	45.2
P1	40.3
1/4	39.8
1/2	37.0
3/4	33.9
A1	28.9

*Profile taken from top of deck to channel bottom



Note:

Footing elevations unknown due to unavailable design drawings.

LEGEND

- Approximate Channel Bottom - April 2020
- - - Approximate Channel Bottom - June 2015
- - - Approximate Channel Bottom - (No Data)
- Timber Debris
- Water Surface
- +450 Elevation (ft)


COLLINS ENGINEERS
124 Venture Court, Ste 10
Lexington, KY 40511
Phone: 859-367-0097
Fax: 859-367-0140



Ohio Department of Transportation, District 2
317 East Poe Rd.
Bowling Green, OH 45601
Phone: 419-353-8131

SR-108 OVER MAUMEE RIVER
STRUCTURE NO. 3502384 (HEN-108-1561)
CROSS SECTIONS - UPSTREAM
HENRY COUNTY, OHIO

CEI PROJECT
55-12239.00
INSPECTED BY:
MOR
DRAWN BY:
MOR
CHECKED BY:
JMJ
DATE:
APR 2020
SHEET NO:
3



CHANNEL CROSS SECTION
 STRUCTURE CENTERLINE
 (LOOKING DOWNSTREAM)

LEGEND


- Approximate Channel Bottom - April 2020
- - - Approximate Channel Bottom - June 2015
- - - Approximate Channel Bottom - (No Data)
- Timber Debris
- Water Surface
- +450 Elevation (ft)

Note:
 Footing elevations unknown due to unavailable design drawings.


**DOWNSTREAM FASCIA
LOOKING DOWNSTREAM**

Location	Y(ft)*
A2	27.0
1/4	30.0
1/2	33.5
3/4	39.8
P6	35.9
1/4	43.8
1/2	42.6
3/4	44.5
P5	37.9
1/4	41.5
1/2	43.4
3/4	44.8
P4	40.6
1/4	46.0
1/2	46.7
3/4	46.1
P3	39.6
1/4	44.7
1/2	46.1
3/4	46.6
P2	39.3
1/4	42.9
1/2	42.7
3/4	42.4
P1	36.8
1/4	39.4
1/2	32.7
3/4	34.4
A1	28.7

*Profile taken from top of deck to channel bottom



**CHANNEL CROSS SECTION
DOWNSTREAM FASCIA
(LOOKING DOWNSTREAM)**



**CHANNEL CROSS SECTION
50 FT DOWNSTREAM
(LOOKING DOWNSTREAM)**

LEGEND

- Approximate Channel Bottom – April 2020
- - - Approximate Channel Bottom – June 2015
- - - Approximate Channel Bottom – (No Data)
- Timber Debris
- Water Surface
- +450 Elevation (ft)

Note:


Footing elevations unknown due to unavailable design drawings.

**COLLINS
ENGINEERS^{PC}**
124 Venture Court, Ste 10
Lexington, KY 40511
Phone: 859-367-0097
Fax: 859-367-0140


Ohio Department of Transportation, District 2
317 East Poe Rd.
Bowling Green, OH 43401
Phone: 419-353-8131

**SR-108 OVER MAUMEE RIVER
STRUCTURE NO. 3502384 (HEN-108-1561)
CROSS SECTIONS - DOWNSTREAM
HENRY COUNTY, OHIO**


**CEI PROJECT
55-12239.00
INSPECTED BY:
MOR
DRAWN BY:
MOR
CHECKED BY:
JMJ
DATE:
APR 2020
SHEET NO:
5**




NORTH ELEVATION
(LOOKING SOUTH)



SOUTH ELEVATION
(LOOKING NORTH)



PLAN



INSPECTION NOTES:

- ① The channel bottom material consisted of sand, gravel, and scattered rip-rap measuring up to 24 in. diameter with no probe rod penetration.
- ② The submerged portions of the pier exhibited light scaling up measuring up to 1/16 in. deep.
- ③ Steel ice breaker exhibited light surface corrosion with no measurable loss of section.
- ④ A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 1 ft vertical by 6 in. horizontal with no exposed steel reinforcement.
- ⑤ Area of poorly consolidated concrete was observed as a cold joint on the upstream and downstream nose measuring approximately 3 ft vertical by 18 in. deep with no exposed steel reinforcement.

LEGEND


- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom - April 2020
- ⊗ Timber Debris
- ∇— Water Surface

COLLINS ENGINEERS
 124 Venture Court, Ste 10
 Lexington, KY 40511
 Phone: 859-367-0097
 Fax: 859-367-0140


Ohio Department of Transportation, District 2
 317 East Poe Rd.
 Bowling Green, OH 45601
 Phone: 419-353-8131

SR-108 OVER MAUMEE RIVER
 STRUCTURE NO. 3502384 (HEN-108-1561)
 PIER 1
 HENRY COUNTY, OHIO


CEI PROJECT
 55-12239.00
 INSPECTED BY:
 MOR
 DRAWN BY:
 MOR
 CHECKED BY:
 JMJ
 DATE:
 APR 2020
 SHEET NO:
 6




NORTH ELEVATION
(LOOKING SOUTH)



SOUTH ELEVATION
(LOOKING NORTH)



PLAN



INSPECTION NOTES:

- ① The channel bottom material consisted of sand, gravel, and scattered rip-rap measuring up to 24 in. diameter with no probe rod penetration.
- ② The submerged portions of the pier exhibited light scaling up measuring up to 1/16 in. deep.
- ③ Steel ice breaker exhibited light surface corrosion with no measurable loss of section.
- ④ A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 1 ft vertical by 6 in. horizontal with no exposed steel reinforcement.
- ⑤ Area of poorly consolidated concrete was observed as a cold joint on the upstream and downstream nose measuring approximately 3 ft vertical by 18 in. deep with no exposed steel reinforcement.

LEGEND


- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom - April 2020
- ⊘ Timber Debris
- ▽ Water Surface

COLLINS ENGINEERS
124 Venture Court, Ste 10
Lexington, KY 40511
Phone: 859-367-0097
Fax: 859-367-0140


Ohio Department of Transportation, District 2
317 East Poe Rd.
Bowling Green, OH 45601
Phone: 419-353-8131

SR-108 OVER MAUMEE RIVER
STRUCTURE NO. 3502384 (HEN-108-1561)
PIER 2
HENRY COUNTY, OHIO


CEI PROJECT
55-12239.00
INSPECTED BY:
MOR
DRAWN BY:
MOR
CHECKED BY:
JMJ
DATE:
APR 2020
SHEET NO:
7




NORTH ELEVATION
(LOOKING SOUTH)



SOUTH ELEVATION
(LOOKING NORTH)



PLAN



INSPECTION NOTES:

- ① The channel bottom material consisted of sand, gravel, and scattered rip-rap measuring up to 24 in. diameter with no probe rod penetration.
- ② The submerged portions of the pier exhibited light scaling up measuring up to 1/16 in. deep.
- ③ Steel ice breaker exhibited light surface corrosion with no measurable loss of section.
- ④ A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 1 ft vertical by 6 in. horizontal with no exposed steel reinforcement.

LEGEND


- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom - April 2020
- ⊗ Timber Debris
- ▽ Water Surface

COLLINS ENGINEERS
 124 Venture Court, Ste 10
 Lexington, KY 40511
 Phone: 859-367-0097
 Fax: 859-367-0140


Ohio Department of Transportation, District 2
 317 East Poe Rd.
 Bowling Green, OH 45601
 Phone: 419-353-8131

SR-108 OVER MAUMEE RIVER
 STRUCTURE NO. 3502384 (HEN-108-1561)
 PIER 3
 HENRY COUNTY, OHIO


CEI PROJECT
 55-12239.00
 INSPECTED BY:
 MOR
 DRAWN BY:
 MOR
 CHECKED BY:
 JMJ
 DATE:
 APR 2020
 SHEET NO:
 8




NORTH ELEVATION
(LOOKING SOUTH)



SOUTH ELEVATION
(LOOKING NORTH)



PLAN



INSPECTION NOTES:

- ① The channel bottom material consisted of sand, gravel, and scattered rip-rap measuring up to 24 in. diameter with no probe rod penetration.
- ② The submerged portions of the pier exhibited light scaling up measuring up to 1/16 in. deep.
- ③ Steel ice breaker exhibited light surface corrosion with no measurable loss of section.
- ④ A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 1 ft vertical by 6 in. horizontal with no exposed steel reinforcement.
- ⑤ Area of poorly consolidated concrete was observed as a cold joint on the upstream and downstream nose measuring approximately 3 ft vertical by 18 in. deep with no exposed steel reinforcement.
- ⑥ Light timber debris consisting of logs up to 6 in. diameter was observed on the channel bottom extending up to a 5 ft radius around the nose.

LEGEND

- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom - April 2020
- ⊗ Timber Debris
- ▽ Water Surface


COLLINS ENGINEERS
 124 Venture Court, Ste 10
 Lexington, KY 40511
 Phone: 859-367-0097
 Fax: 859-367-0140




Ohio Department of Transportation, District 2
 317 East Poe Rd.
 Bowling Green, OH 43601
 Phone: 419-353-8131

SR-108 OVER MAUMEE RIVER
 STRUCTURE NO. 3502384 (HEN-108-1561)
 PIER 4
 HENRY COUNTY, OHIO


CEI PROJECT
 55-12239.00
 INSPECTED BY:
 MOR
 DRAWN BY:
 MOR
 CHECKED BY:
 JMJ
 DATE:
 APR 2020
 SHEET NO:
 9




NORTH ELEVATION
(LOOKING SOUTH)



SOUTH ELEVATION
(LOOKING NORTH)



PLAN



INSPECTION NOTES:

- ① The channel bottom material consisted of sand, gravel, and scattered rip-rap measuring up to 24 in. diameter with no probe rod penetration.
- ② The submerged portions of the pier exhibited light scaling up measuring up to 1/16 in. deep.
- ③ Steel ice breaker exhibited light surface corrosion with no measurable loss of section.
- ④ A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 1 ft vertical by 6 in. horizontal with no exposed steel reinforcement.
- ⑤ Area of poorly consolidated concrete was observed as a cold joint on the upstream and downstream nose measuring approximately 3 ft vertical by 18 in. deep with no exposed steel reinforcement.

LEGEND

- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom – April 2020
- ⊘ Timber Debris
- ∇— Water Surface

COLLINS ENGINEERS
 124 Venture Court, Ste 10
 Lexington, KY 40511
 Phone: 859-367-0097
 Fax: 859-367-0140



Ohio Department of Transportation, District 2
 317 East Poe Rd.
 Bowling Green, OH 45601
 Phone: 419-353-8131

SR-108 OVER MAUMEE RIVER
 STRUCTURE NO. 3502384 (HEN-108-1561)
 PIER 5
 HENRY COUNTY, OHIO

CEI PROJECT
 55-12239.00


INSPECTED BY:
 MOR

DRAWN BY:
 MOR


CHECKED BY:
 JMJ

DATE:
 APR 2020


SHEET NO:
 10




NORTH ELEVATION
(LOOKING SOUTH)



SOUTH ELEVATION
(LOOKING NORTH)



PLAN



INSPECTION NOTES:

- ① The channel bottom material consisted of sand, gravel, and scattered rip-rap measuring up to 24 in. diameter with no probe rod penetration.
- ② The submerged portions of the pier exhibited light scaling up measuring up to 1/16 in. deep.
- ③ Steel ice breaker exhibited light surface corrosion with no measurable loss of section.
- ④ A band of poorly consolidated concrete was observed at the cold joint between the new pier wall and the original footing. The band extends around the perimeter of the pier and typically measures 1 ft vertical by 6 in. horizontal with no exposed steel reinforcement.
- ⑤ Area of poorly consolidated concrete was observed as a cold joint on the upstream and downstream nose measuring approximately 3 ft vertical by 18 in. deep with no exposed steel reinforcement.

LEGEND

- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom - April 2020
- ⊘ Timber Debris
- ∇— Water Surface

COLLINS ENGINEERS
 124 Venture Court, Ste 10
 Lexington, KY 40511
 Phone: 859-367-0097
 Fax: 859-367-0140



Ohio Department of Transportation, District 2
 317 East Poe Rd.
 Bowling Green, OH 45601
 Phone: 419-353-8131

SR-108 OVER MAUMEE RIVER
 STRUCTURE NO. 3502384 (HEN-108-1561)

PIER 6

HENRY COUNTY, OHIO

CEI PROJECT
 55-12239.00

INSPECTED BY:
 MOR

DRAWN BY:
 MOR

CHECKED BY:
 JMJ

DATE:
 APR 2020

SHEET NO:
 11

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



EXHIBIT 2 – INSPECTION PHOTOGRAPHS

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



Photograph No. 1: Overall View of Structure No. 3502384 (HEN-108-1561), Looking East.



Photograph No. 2: Overall View of Structure No. 3502384 (HEN-108-1561), Looking West.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



Photograph No. 3: View of the North Embankment Upstream of the Structure, Looking Northwest.



Photograph No. 4: View of the North Embankment at the Structure, Looking North.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



Photograph No. 5: View of the North Embankment Downstream of the Structure, Looking Northeast.



Photograph No. 6: View of the South Embankment Upstream of the Structure, Looking Southwest.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



Photograph No. 7: View of the South Embankment at the Structure, Looking South.



Photograph No. 8: View of the South Embankment Downstream of the Structure, Looking Southeast.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



Photograph No. 9: View of the North Face of Pier 1, Looking Southwest.



Photograph No. 10: View of the South Face of Pier 1, Looking Northeast.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



Photograph No. 11: View of the North Face of Pier 2, Looking Southwest.



Photograph No. 12: View of the South Face of Pier 2, Looking Northeast.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



Photograph No. 13: View of the North Face of Pier 3, Looking Southwest.



Photograph No. 14: View of the South Face of Pier 3, Looking Northeast.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



Photograph No. 15: View of the Spall on the Upstream Nose of Pier 3, Looking East.



Photograph No. 16: View of the North Face of Pier 4, Looking Southwest.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



Photograph No. 17: View of the South Face of Pier 4, Looking Northeast.



Photograph No. 18: View of the North Face of Pier 5, Looking Southwest.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



Photograph No. 19: View of the South Face of Pier 5, Looking Northeast.



Photograph No. 20: View of the North Face of Pier 6, Looking Southwest.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



Photograph No. 21: View of the South Face of Pier 6, Looking Northeast.



Photograph No. 22: View of the Typical Concrete and Steel Condition at the Waterline on the Upstream Nose of Pier 6, Looking East.

UNDERWATER INSPECTION

SR 108 over Maumee River • Structure No. 3502384 (HEN-108-1561)

Henry County, OH • April 2020



**EXHIBIT 3 – UNDERWATER DIVE INSPECTION PROCEDURE
CHECKLIST**

Underwater Dive Inspection Procedure Checklist

Acceptable written procedures communicate to the next dive team what is necessary to ensure a safe and successful inspection. Each bridge requiring underwater dive techniques must have a unique written inspection procedure. The prior inspection report does not suffice for the required procedures. It is valuable to review the last inspection notes, but they do not serve the same purpose as a stand-alone inspection procedure.

This document shall be completed for all underwater dive inspections. This document shall be reviewed prior to performing the field work and it shall be updated when necessary.

I. Bridge Identification

a. Agency with Inspection Responsibility: ODOT DISTRICT 2

Dive Frequency: 60 months

SFN: 3502384 Bridge Number (County-Route-SLM-SD): HEN-108-1561

Superstructure Type Main Span Type: REINFORCED CONCRETE ARCH

Approach Span: REINFORCED CONCRETE ARCH

Substructure Type Abutment Type: REINFORCED CONCRETE

Pier Type: REINFORCED CONCRETE

Total Pier Count: 6

Total Pier Count in water: 6

Foundations: SPREAD FOOTINGS

Feature Intersected MAUMEE RIVER

b. Photographs

Endview



Elevation



Underside

II. Office and Field Assessment

Prior to the inspection, obtain and review copies of the previous underwater inspection reports, routine inspection reports, scour and hydraulic information, and design plans in preparation of the inspection.

Divers should pay particular attention given to any observed areas of deterioration, the channel conditions and factors that may accelerate material deterioration. Changes shall be noted in the inspection procedure. Site conditions should be reviewed prior to diving.

a. Channel Conditions

- Waterway features
- Rapid stream flows,
- Significant debris accumulation
- Constricted waterway openings
- Soft or unstable streambeds
- Meandering channels
- Other which may promote scour and undermining of substructure elements
- Navigable Waterway
- Flow Controls

b. Anticipated Water conditions which may affect the inspection

- Cold Water (Apprx. Temp___)
- Black water
- Rapid stream flows
- Near military facility
- Tribal fishing
- Water quality
- History of Log jams

c. Identify factors that may accelerate the deterioration of the bridge elements:

- Highly corrosive water
- Unprotected steel members
- Other

Risk Factor Narrative:

III. Contacts Prior to Work

District 2 Bridge Engineer: David Geckle, P.E.

Email: david.geckle@dot.ohio.gov – Phone: 419-373-4377

Point of contact for immediate action such as closing the bridge due to findings)

Contact Bridge Owner 14 (number) days before the proposed underwater inspection.

Special contracting and scheduling procedures prior to inspection, include recommended lead time

Entity	Contact Name and Title	Contact Phone	Lead Time
Coast Guard			
Property Owner			
Access Equipment			
Lake or River draw-down			
Canal dry time			
Tree removal			
Other:			
Other:			

IV. **Dive Team Shall Include the Following:**

Dive Team Narrative:

The dive team consisted of one Team Leader (NBIS, P.E., ADCI) and two Team Members (NBIS, UW, ADCI).

Example: The Bridge shall be investigated using a three-member dive team: one supervisor to monitor rack box and take notes, one diver, and one tender/standby diver. There shall be one NBIS Team Leader onsite at all times.

V. **Site Information**

Navigable waterway:	Y / <u>N</u>	Anticipated current	<u><1</u> ft
If Yes, waterway river point	<u>N/A</u>	Scour Critical (item 113):	<u>5</u>
Anticipated water visibility depth	<u>0</u> ft	POA in place:	Y/ <u>N</u>
Anticipated Dive depth	<u>10</u> ft	Scour Monitoring devices present:	Y/ <u>N</u>

Verify the Scope of Services when work is contracted for the procedure for underwater elements that are not in water during an inspection.

Site Information Narrative:

The underwater inspection consists of a visual and tactile examination of the accessible surfaces of the substructure items in water. Additional items should reference the scope of services in the contract.

For reference the following items are in water:

Item	Number of Units	Level of Inspection (1, 2 or 3) with Commentary
Piers and Number of Columns	6	100 % LEVEL 1 10% LEVEL II
Abutment		
Culvert		
Scour Countermeasures		
Fenders or Dolphins		

Photographs should be taken, if water clarity permits, for typical conditions, conditions that have changed since last inspection and significant or noteworthy deficiencies. The type of channel bottom material, the presence or extent of scour, the presence or extent of riprap, the presence or extent of drift and debris, and the location of any foundation exposure or undermining shall be quantified. Include depth, length, height and location of deficiencies.

VI. Equipment and Field Logistics

a. The inspection should be conducted

using:

Chest waders

Hip waders

Diving equipment

SCUBA (Note that ADCI Consensus Standards require communication systems be employed for both SCUBA and Surface-Supplied (whether air or mixed-gas) dive modes)

SCUBA with communication

Surface Supplied with

communication

b. The channel bottom should be sounded

utilizing

Digital fathometer

Telescoping survey rod

acoustic imaging

c. During the inspection, the divers should

work from

Shore

Boat

Either

The note taker should work alongside the dive team.

d. Access to the waterway should be obtained from the shore (north bank, southwest quadrant, driveway 30 yards north etc.)

RITTER PARK PUBLIC BOAT RAMP

e. The maximum depth of the channel is typically measured 10 feet from

SOUTHEAST CORNER OF PIER 5

Reference Datum: TOP OF CAP AT

DOWNSTREAM NOSE OF PIER 4

Soundings should be dictated by the scope of work. When not detailed in the scope they should be repeated from the previous soundings. If neither exist then they need to be taken in a grid pattern between substructure units 100' upstream and 100' downstream.

VII. Inspection Procedure History

Created: COLLINS ENGINEERS Date: 09/25/2020

Updated By: _____ Date: _____

Updated By: _____ Date: _____

Updated By: _____ Date: _____

Updated By: _____ Date: _____

Updated By: _____ Date: _____

VIII. Other Narrative Not Included In Previous Sections