



# UNDERWATER BRIDGE INSPECTION REPORT

STRUCTURE NO. 6200885 (OTT-19-0323)  
SR 19 OVER PORTAGE RIVER  
OTTAWA COUNTY, OH  
DISTRICT 2

May 2020

*Prepared for:*



10/9/2020

*Prepared by:*

**COLLINS**  
**ENGINEERS** INC.

124 Venture Court, Suite 10

Lexington, Kentucky 40511

859.367.0097 • [www.collinsengr.com](http://www.collinsengr.com)

**UNDERWATER INSPECTION**

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)

Ottawa County, OH • May 2020



---

**TABLE OF CONTENTS**

**EXECUTIVE SUMMARY**

1.0	INTRODUCTION .....	1
1.1	Purpose and Scope .....	1
1.2	General Description of the Structure .....	1
1.3	Method of Investigation.....	1
2.0	EXISTING CONDITIONS.....	2
2.1	General Conditions .....	2
2.2	Substructure Conditions.....	3
2.2.1	Pier 1 .....	3
2.2.2	Pier 2.....	3
2.2.3	Pier 3.....	3
2.2.4	Pier 4.....	3
3.0	EVALUATION AND RECOMMENDATIONS .....	4
	EXHIBIT 1 – FIGURES .....	5
	LOCATION MAP	
	SOUNDING PLAN	
	TIMBER DEBRIS ACCUMULATION	
	CHANNEL CROSS SECTIONS - UPSTREAM	
	CHANNEL CROSS SECTIONS - CENTERLINE	
	CHANNEL CROSS SECTIONS - DOWNSTREAM	
	PIER 1	
	PIER 2	
	PIER 3	
	PIER 4	
	EXHIBIT 2 – INSPECTION PHOTOGRAPHS .....	16
	Photograph No. 1: Overall View of Structure No. 6200885 (OTT-19-0323), Looking Southeast.	
	Photograph No. 2: Overall View of Structure No. 6200885 (OTT-19-0323), Looking Northwest.	
	Photograph No. 3: View of the North Embankment Upstream of the Structure, Looking Northeast.	
	Photograph No. 4: View of the North Embankment at the Structure, Looking Northwest.	
	Photograph No. 5: View of the North Embankment Downstream of the Structure, Looking Southwest.	
	Photograph No. 6: View of the South Embankment Upstream of the Structure, Looking Southeast.	
	Photograph No. 7: View of the South Embankment at the Structure, Looking Southeast.	

**UNDERWATER INSPECTION**

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)

Ottawa County, OH • May 2020



- 
- Photograph No. 8: View of the South Embankment Downstream of the Structure, Looking Southwest.
  - Photograph No. 9: View of the North Face of Pier 1, Looking Southeast.
  - Photograph No. 10: View of the South Face of Pier 1, Looking Northwest.
  - Photograph No. 11: View of the North Face of Pier 2, Looking Southeast.
  - Photograph No. 12: View of the South Face of Pier 2, Looking Northwest.
  - Photograph No. 13: View of the North Face of Pier 3, Looking Southeast.
  - Photograph No. 14: View of the South Face of Pier 3, Looking Northwest.
  - Photograph No. 15: View of the North Face of Pier 4, Looking Southeast.
  - Photograph No. 16: View of the South Face of Pier 4, Looking Northwest.
  - Photograph No. 17: View of the Typical Concrete Condition at the Waterline on the South Face of Pier 4.

EXHIBIT 3 – UNDERWATER DIVE INSPECTION PROCEDURE CHECKLIST .....26

## UNDERWATER INSPECTION

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)

Ottawa County, OH • May 2020



---

### EXECUTIVE SUMMARY

<b>Project:</b>	ODOT District 2 Underwater Bridge Inspections - 2020		
<b>Purpose of Project:</b>	To perform a detailed visual and tactile underwater investigation of underwater bridges for District 2 of the Ohio Department of Transportation.		
<b>Inspection Team:</b>	Team Leader – Joshua Johnson, P.E. – Collins Engineers, Inc. Team Member – Matthew Rogers, E.I.T. – Collins Engineers, Inc. Team Member – Phillip Osborn – Collins Engineers, Inc.		
<b>Inspection Date(s):</b>	May 28, 2020		
<b>Water Visibility:</b>	<1 ft	<b>Water Velocity:</b>	<1 ft/s
<b>Water Temperature:</b>	78 °F	<b>Weather:</b>	Cloudy – 87 °F
<b>Waterline Elevation:</b>	576.2 ft	<b>Type of Boat:</b>	Kayak
<b>Coordinates:</b>	41.505001°N, -83.145095°W		
<b>Access Location:</b>	Northwest Embankment		
<b>Dive Mode:</b>	Surface Supplied Air		
<b>Waterline Reference:</b>	4.5 ft below the top of cap at the downstream nose of Pier 4.		
<b>Maximum Depth at SSU:</b>	18.9 ft – South Corner of the Downstream Nose of Pier 3		
<b>Shoreline Conditions:</b>	The north and south shorelines consisted of well-protected, well-vegetated, mild slopes with minor erosion.		

#### Summary of Findings:

- **Pier 1:**
  - The channel bottom material consisted of timber and silt overlay with approximately 6 in. probe rod penetration.
  - The submerged portions of the pier were sound and smooth with no defects observed.
  - Heavy timber debris consisting of logs up to 2 ft diameter were observed extending up to a 50 ft radius from the upstream nose from channel bottom to 1 ft above the waterline.
- **Pier 2:**
  - The channel bottom material consisted of timber and silt overlay with approximately 6 in. probe rod penetration.
  - The submerged portions of the pier were sound and smooth with no defects observed.
  - Heavy timber debris consisting of logs up to 2 ft diameter were observed extending up to a 20 ft radius from the upstream nose from channel bottom to 1 ft above the waterline.
- **Pier 3:**
  - The channel bottom material consisted of timber and silt overlay with approximately 6 in. probe rod penetration.
  - The submerged portions of the pier were sound and smooth with no defects observed.
  - The top of footing was observed at 17.2 ft below the waterline extending from the midpoint along the north face around the downstream nose to the downstream quarter point of the south face with a maximum vertical exposure of 1.7 ft at the southeast corner.

## UNDERWATER INSPECTION

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)

Ottawa County, OH • May 2020



- 
- Heavy timber debris consisting of logs up to 2 ft diameter were observed extending up to a 30 ft radius from the upstream nose from channel bottom to 1 ft above the waterline.
  - **Pier 4:**
    - The channel bottom material consisted of timber and silt overlay with approximately 6 in. probe rod penetration.
    - The submerged portions of the pier were sound and smooth with no defects observed.
    - Heavy timber debris consisting of logs up to 2 ft diameter were observed extending up to a 40 ft radius from the upstream nose from channel bottom to 2 ft above the waterline.

### *Summary of Recommendations:*

- Remove timber debris at Piers 1 through 4
- Monitor footing exposure at Pier 3.

## UNDERWATER INSPECTION

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)

Ottawa County, OH • May 2020



### *Underwater Inspection Coding:*

#### **NBI Ratings:**

<b>Item</b>	<b>Description</b>	<b>Coding</b>	<b>Condition</b>
60	Substructure	8 – Very Good Condition	No Defects Observed
61	Channel	5 – Fair Condition	Minor Erosion, Timber Debris Accumulation, Footing Exposure
62	Culvert	N/A	
92B	UW Insp. Frequency	60 Months	
93B	Insp. Date	05 28 20	
113	Scour Critical Bridges	5 – Within Foundation Limits	Stable (Inspector Recommended)

#### **AASHTO National Bridge Element (NBE) Ratings:**

<b>Element #</b>	<b>Description</b>	<b>Units</b>	<b>Total</b>	<b>Condition State</b>			
				<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>
210	Reinforced Concrete Pier Wall	LF	120	120	0	0	0
220	Reinforced Concrete Pile Cap / Footing	LF	15	15	0	0	0

Note: Ratings were developed using the FHWA Recording and Coding Guide for the Structure Inventory and Appraisal of the Nation's Bridges. The recommended ratings consider inspected elements located within the waterway and conditions existing below the water surface only. Additional consideration is necessary for the assignment of overall condition ratings for this bridge.



## UNDERWATER INSPECTION

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)  
Ottawa County, OH • May 2020



---

### 1.0 INTRODUCTION

#### 1.1 Purpose and Scope

This report consists of the results of a detailed underwater investigation performed at the SR 19 Bridge over Portage River in Ottawa County, OH. Collins Engineers, Inc. (Collins) conducted the underwater investigation for District 2 of the Ohio Department of Transportation (ODOT) on May 28, 2020. The primary purpose of the investigation was as follows:

- Determine the condition of the substructure components located in the water at the time of the inspection from the waterline to the channel bottom.
- Obtain channel bottom depth measurements along the bridge fascias, upstream and downstream of the bridge, and around the submerged substructure units.
- Obtain channel profile cross sections at the upstream and downstream fascias.
- Determine the condition of the shorelines in the vicinity of the structure.
- Obtain photographs of the bridge and any significant defects.

In addition, a brief inspection was made of areas that could be submerged during periods of high water. The following report includes a description of the structure, the method of investigation, a description of existing conditions, an evaluation and recommendations based on the conditions, inspection figures, and photographs.

#### 1.2 General Description of the Structure

Structure No. 6200885 (OTT-19-0323) spans 332.3 ft, carrying SR 19 over Portage River and is approximately 60 ft wide. The bridge superstructure is constructed of five continuous steel girder spans. The roadway orientation of the longitudinal axis of the bridge is south to north. The substructure units are labeled as Abutments 1 and 2 and Piers 1 through 4. Existing record drawings were available at the time of the inspection. Refer to Figure 1 in Exhibit 1 for a Location Map of the bridge. Refer to Photographs 1 and 2 in Exhibit 2 for overall views of the bridge.

#### 1.3 Method of Investigation

A detailed field inspection was conducted to determine the physical condition of the submerged bridge substructure units from the waterline to the channel bottom. A brief visual examination of the substructure units above the waterline was also made.

## UNDERWATER INSPECTION

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)  
Ottawa County, OH • May 2020

---



A three-person team consisting of a professional engineer-diver and team leader (Joshua Johnson, P.E.) and two engineer divers (Matthew Rogers, E.I.T. and Phillip Osborn, E.I.T.) conducted the underwater inspection. The inspection was conducted using surface supplied air diving equipment. During the inspection, the inspectors worked from a kayak and a note taker from the shore recorded the inspection notes.

The underwater inspection consisted of a visual and tactile examination of the accessible surfaces of the substructure units from the waterline to the channel bottom with particular attention given to any observed areas of deterioration or apparent distress. Approximately 10 percent of the total area on the underwater surfaces of the substructure units was cleaned so that the condition could be more closely examined. Photographs were taken to document the general conditions and observed deficiencies. Underwater photographs could not be obtained due to poor water conditions. The type of channel bottom material, the presence or extent of scour, the presence or extent of riprap, the presence or extent of drift and debris, and the location of any foundation exposure or undermining were noted.

Channel bottom soundings were performed utilizing a telescoping survey rod, digital fathometer, and pneumofathometer. Soundings were collected at quarter points along the bridge centerline as well as at quarter points along the upstream and downstream fascias and 50 ft fascias. Additional soundings were collected adjacent to Piers 1 through 4 and at 10 foot intervals in-line with the piers, upstream and downstream, and the waterline was referenced to a known elevation on the bridge. A sounding plan was developed using the soundings and approximate location of the shorelines. Refer to Figures 2 through 6 in Exhibit 1 for the sounding plan and channel cross sections that show the channel limits, extents of timber debris accumulation, and water depths around the structure.

## 2.0 EXISTING CONDITIONS

### 2.1 General Conditions

At the time of the inspection, the waterline of 6200885 (OTT-19-0323) was located approximately 4.5 ft below the top of cap at the downstream nose of Pier 4, which corresponds to a waterline elevation of 576.2 ft. During the inspection, the waterway was flowing at approximately <1 ft per second. The bridge pier skew was consistent with the channel alignment and does not require attention at this time. The north and south shorelines consisted of well-protected, well-vegetated, mild slopes with signs minor erosion. Refer to Photographs 3 through 8 in Exhibit 2 for views of the shorelines near the structure.



## UNDERWATER INSPECTION

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)  
Ottawa County, OH • May 2020

---



### 2.2 Substructure Conditions

#### 2.2.1 *Pier 1*

The channel bottom material consisted of timber and silt overlay with approximately 6 in. probe rod penetration. The submerged portions of the pier were sound and smooth with no defects observed. Heavy timber debris consisting of logs up to 2 ft diameter were observed extending up to a 50 ft radius from the upstream nose from channel bottom to 1 ft above the waterline. Refer to Figure 7 in Exhibit 1 for detailed inspection notes of Pier 1. Refer to Photographs 9 and 10 in Exhibit 2 for views of Pier 1.

#### 2.2.2 *Pier 2*

The channel bottom material consisted of timber and silt overlay with approximately 6 in. probe rod penetration. The submerged portions of the pier were sound and smooth with no defects observed. Heavy timber debris consisting of logs up to 2 ft diameter were observed extending up to a 20 ft radius from the upstream nose from channel bottom to 1 ft above the waterline. Refer to Figure 8 in Exhibit 1 for detailed inspection notes of Pier 2. Refer to Photographs 11 and 12 in Exhibit 2 for views of Pier 2.

#### 2.2.3 *Pier 3*

The channel bottom material consisted of timber and silt overlay with approximately 6 in. probe rod penetration. The submerged portions of the pier were sound and smooth with no defects observed. The top of footing was observed at 17.2 ft below the waterline extending from the midpoint along the north face around the downstream nose to the downstream quarter point of the south face with a maximum vertical exposure of 1.7 ft at the southeast corner. Heavy timber debris consisting of logs up to 2 ft diameter were observed extending up to a 30 ft radius from the upstream nose from channel bottom to 1 ft above the waterline. Refer to Figure 9 in Exhibit 1 for detailed inspection notes of Pier 3. Refer to Photographs 13 and 14 in Exhibit 2 for views of Pier 3.

#### 2.2.4 *Pier 4*

The channel bottom material consisted of timber and silt overlay with approximately 6 in. probe rod penetration. The submerged portions of the pier were sound and smooth with no defects observed. Heavy timber debris consisting of logs up to 2 ft diameter were observed extending up to a 40 ft radius from the upstream nose from channel bottom to 2 ft above the waterline. Refer to Figure 10 in Exhibit 1 for detailed inspection notes of Pier 4. Refer to Photographs 15 through 17 in Exhibit 2 for views of Pier 4 and typical concrete condition at the waterline.

## UNDERWATER INSPECTION

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)  
Ottawa County, OH • May 2020



---

### 3.0 EVALUATION AND RECOMMENDATIONS

Overall, the inspected substructure units of Structure No. 6200885 (OTT-19-0323) were in very good condition. A comparison of the soundings recorded during the previous inspection on June 23, 2015 and the soundings taken during this inspection revealed no significant change in the channel bottom profile in the vicinity of the structure. Since no design or as-built plans were available for the bridge, the amount of embedment of the footings in the channel bottom is unknown. As a result, the channel bottom configuration should continue to be monitored during future underwater inspections to verify that localized scour or overall channel degradation is not occurring and that both pier footings remain adequately embedded in the channel bottom. Design or as-built drawings for the bridge should be obtained and reviewed, if possible, prior to the next underwater inspection to determine the exact construction of the piers and their foundations.

The timber debris accumulations at Piers 1 through 4 is obstructing channel flow and the cause of footing exposure and should be removed at this time. Removal of the timber debris will reduce excessive lateral loads on the pier, limit further debris accumulation, and reduce the likelihood of channel bottom degradation resulting from obstructed flow.

It is recommended that the submerged substructure units of Structure No. 6200885 (OTT-19-0323) be next inspected underwater at an interval not to exceed 60 months, no later than May 28, 2025.

Respectfully Submitted,  
COLLINS ENGINEERS, INC.


A handwritten signature in black ink, appearing to read "Joshua Johnson".

Joshua Johnson, P.E.  
Project Manager

Originated by:  
Kevin Mitchell, E.I.T.



## EXHIBIT 1 – FIGURES



LAT: +41.505001  
 LONG: -83.145095


1 mi

**COLLINS ENGINEERS**  
 124 Venture Court, Ste 10  
 Lexington, KY 40511  
 Phone: 859-367-0097  
 Fax: 859-367-0140

  
 Ohio Department of  
 Transportation, District 2  
 317 East Poe Rd.  
 Bowling Green, OH 45601  
 Phone: 419-353-8131

**SR-19 OVER PORTAGE RIVER  
 STRUCTURE NO. 6200885  
 (OTT-19-0323)  
 LOCATION MAP  
 OTTAWA COUNTY, OHIO**

INSPECTED BY: JMJ	CEI PROJECT: 55-12239.00
DRAWN BY: BBM	DATE: 28 MAY 2020
CHECKED BY: JMJ	SHEET NO: <b>1</b>




**GENERAL NOTES:**

1. Piers 1 through 4 were inspected underwater. Substructure units are labeled according to available record drawings.
2. At the time of inspection on May 28, 2020, the waterline was located approximately 4.5 ft below Top of Cap at downstream nose of Pier 4 (EL. +580.7 ft). This corresponds with a waterline elevation of +575.2 ft.
3. Soundings indicate the water depth at the time of inspection and are measured in feet.
4. Soundings were taken parallel to the bridge at the upstream and downstream fascias, at 10 ft intervals between the substructure units, and at 10 ft intervals in-line with the piers upstream and downstream up to 50 ft.
5. Footing not shown for clarity.

**LEGEND**

- 2.7 Sounding Depth from Waterline (ft)
- X Timber Debris



TIMBER DEBRIS  
ACCUMULATION PLAN

GENERAL NOTES:

1. Piers 1 through 4 were inspected underwater. Substructure units are labeled according to available record drawings.
2. At the time of inspection on May 28, 2020, the waterline was located approximately 4.5 ft below Top of Cap at downstream nose of Pier 4 (EL. +580.7 ft). This corresponds with a waterline elevation of +575.2 ft.
3. Soundings indicate the water depth at the time of inspection and are measured in feet.
4. Soundings were taken parallel to the bridge at the upstream and downstream fascias, at 10 ft intervals between the substructure units, and at 10 ft intervals in-line with the piers upstream and downstream up to 50 ft.
5. Footing not shown for clarity.

LEGEND

- 2.7 Sounding Depth from Waterline (ft)
- ⊗ Timber Debris

**COLLINS ENGINEERS**  
124 Venture Court, Ste 10  
Lexington, KY 40511  
Phone: 859-367-0097  
Fax: 859-367-0140

Ohio Department of Transportation, District 2  
317 East Poe Rd.  
Bowling Green, OH 45601  
Phone: 419-353-8131



SR-19 OVER PORTAGE RIVER  
STRUCTURE NO. 6200885 (OTT-19-0323)  
TIMBER DEBRIS ACCUMULATION  
OTTAWA COUNTY, OHIO

CEI PROJECT  
55-12239.00  
INSPECTED BY:  
JMJ  
DRAWN BY:  
BBM  
CHECKED BY:  
JMJ  
DATE:  
MAY 2020  
SHEET NO:  
**3**



UPSTREAM FASCIA LOOKING DOWNSTREAM	
Location	Y(ft)*
A2	13.0
1/4	16.8
1/2	17.4
3/4	18.0
P4	TIMB
1/4	24.2
1/2	24.9
3/4	27.5
P3	28.7
1/4	26.6
1/2	26.3
3/4	27.0
P2	26.0
1/4	25.2
1/2	25.3
3/4	24.0
P1	23.3
1/4	TIMB
1/2	TIMB
3/4	TIMB
A1	11.9

\*Profile taken from top of deck to channel bottom




LEGEND

- Approximate Channel Bottom - May 2020
- - - Approximate Channel Bottom - June 2015
- - - Approximate Channel Bottom - (No Data)
- Timber Debris
- Water Surface
- +450 Elevation (ft)

Note:

Footing elevations unknown due to unavailable design drawings.



**LEGEND**



- Approximate Channel Bottom - May 2020
- Approximate Channel Bottom - (No Data)
- Approximate Channel Bottom - (No Data)
- Timber Debris
- Water Surface
- +450      Elevation (ft)

Note:

Footing elevations unknown due to unavailable design drawings.

DOWNSTREAM FASCIA LOOKING DOWNSTREAM	
Location	Y(ft)*
A2	8.0
1/4	TIMB
1/2	TIMB
3/4	18.5
P4	22.2
1/4	22.7
1/2	23.5
3/4	26.3
P3	30.2
1/4	26.4
1/2	24.8
3/4	25.2
P2	26.1
1/4	25.7
1/2	25.1
3/4	24.4
P1	27.9
1/4	24.0
1/2	22.3
3/4	18.9
A1	8.2

\*Profile taken from top of deck to channel bottom



LEGEND

- Approximate Channel Bottom - May 2020
- - - Approximate Channel Bottom - June 2015
- - - Approximate Channel Bottom - (No Data)
- Timber Debris
- Water Surface
- +450 Elevation (ft)

Note:

Footing elevations unknown due to unavailable design drawings.



**COLLINS ENGINEERS**  
124 Venture Court, Ste 10  
Lexington, KY 40511  
Phone: 859-367-0097  
Fax: 859-367-0140



Ohio Department of Transportation, District 2  
317 East Poe Rd.  
Bowling Green, OH 45601  
Phone: 419-353-8131

SR-19 OVER PORTAGE RIVER  
STRUCTURE NO. 6200885 (OTT-19-0323)  
CROSS SECTIONS - DOWNSTREAM  
OTTAWA COUNTY, OHIO

CEI PROJECT  
55-12239.00  
INSPECTED BY:  
JMJ  
DRAWN BY:  
BBM  
CHECKED BY:  
JMJ  
DATE:  
MAY 2020  
SHEET NO:  
**6**




**LEGEND**

- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom - April 2020
- ⊗ Timber Debris
- ∇ Water Surface

**INSPECTION NOTES:**

- ① The channel bottom material consisted of timber and silt overlay with approximately 6 in. probe rod penetration.
- ② The submerged portions of the pier were sound and smooth with no defects observed.
- ③ Heavy timber debris consisting of logs up to 2 ft diameter were observed extending up to a 50 ft radius from the upstream nose from channel bottom to 1 ft above the waterline.




INSPECTION NOTES:

- ① The channel bottom material consisted of timber and silt overlay with approximately 6 in. probe rod penetration.
- ② The submerged portions of the pier were sound and smooth with no defects observed.
- ③ Heavy timber debris consisting of logs up to 2 ft diameter were observed extending up to a 20 ft radius from the upstream nose from channel bottom to 1 ft above the waterline.

LEGEND

- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom — April 2020
- ⊗ Timber Debris
- ▽ Water Surface






**INSPECTION NOTES:**

- ① The channel bottom material consisted of timber and silt overlay with approximately 6 in. probe rod penetration.
- ② The submerged portions of the pier were sound and smooth with no defects observed.
- ③ The top of footing was observed at 17.2 ft below the waterline extending from the midpoint along the north face around the downstream nose to the downstream quarter point of the south face with a maximum vertical exposure of 1.7 ft at the southeast corner.
- ④ Heavy timber debris consisting of logs up to 2 ft diameter were observed extending up to a 30 ft radius from the upstream nose from channel bottom to 1 ft above the waterline.

**LEGEND**

- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom - April 2020
- ⊗ Timber Debris
- ▽ Water Surface





- INSPECTION NOTES:**
- ① The channel bottom material consisted of timber and silt overlay with approximately 6 in. probe rod penetration.
  - ② The submerged portions of the pier were sound and smooth with no defects observed.
  - ③ Heavy timber debris consisting of logs up to 2 ft diameter were observed extending up to a 40 ft radius from the upstream nose from channel bottom to 2 ft above the waterline.

**LEGEND**

-2.7	Sounding Depth from Waterline (ft)
—	Approximate Channel Bottom - April 2020
⌘	Timber Debris
▽	Water Surface



## EXHIBIT 2 – INSPECTION PHOTOGRAPHS

**UNDERWATER INSPECTION**

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)

Ottawa County, OH • May 2020



Photograph No. 1: Overall View of Structure No. 6200885 (OTT-19-0323), Looking Southeast.



Photograph No. 2: Overall View of Structure No. 6200885 (OTT-19-0323), Looking Northwest.



**UNDERWATER INSPECTION**

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)

Ottawa County, OH • May 2020



Photograph No. 3: View of the North Embankment Upstream of the Structure, Looking Northeast.



Photograph No. 4: View of the North Embankment at the Structure, Looking Northwest.



**UNDERWATER INSPECTION**

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)

Ottawa County, OH • May 2020



Photograph No. 5: View of the North Embankment Downstream of the Structure, Looking Southwest.



Photograph No. 6: View of the South Embankment Upstream of the Structure, Looking Southeast.



**UNDERWATER INSPECTION**

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)

Ottawa County, OH • May 2020



Photograph No. 7: View of the South Embankment at the Structure, Looking Southeast.



Photograph No. 8: View of the South Embankment Downstream of the Structure, Looking Southwest.



**UNDERWATER INSPECTION**

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)

Ottawa County, OH • May 2020



Photograph No. 9: View of the North Face of Pier 1, Looking Southeast.



Photograph No. 10: View of the South Face of Pier 1, Looking Northwest.

**UNDERWATER INSPECTION**

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)

Ottawa County, OH • May 2020



Photograph No. 11: View of the North Face of Pier 2, Looking Southeast.



Photograph No. 12: View of the South Face of Pier 2, Looking Northwest.



**UNDERWATER INSPECTION**

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)

Ottawa County, OH • May 2020



Photograph No. 13: View of the North Face of Pier 3, Looking Southeast.



Photograph No. 14: View of the South Face of Pier 3, Looking Northwest.

**UNDERWATER INSPECTION**

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)

Ottawa County, OH • May 2020



Photograph No. 15: View of the North Face of Pier 4, Looking Southeast.



Photograph No. 16: View of the South Face of Pier 4, Looking Northwest.



**UNDERWATER INSPECTION**

SR 19 over Portage River • Structure No. 6200885 (OTT-19-0323)

Ottawa County, OH • May 2020



Photograph No. 17: View of the Typical Concrete Condition at the Waterline on the South Face of Pier 4.



## EXHIBIT 3 – UNDERWATER DIVE INSPECTION PROCEDURE CHECKLIST





**b. Photographs**

Endview



Elevation



Underside

**II. Office and Field Assessment**

Prior to the inspection, obtain and review copies of the previous underwater inspection reports, routine inspection reports, scour and hydraulic information, and design plans in preparation of the inspection.

Divers should pay particular attention given to any observed areas of deterioration, the channel conditions and factors that may accelerate material deterioration. Changes shall be noted in the inspection procedure. Site conditions should be reviewed prior to diving.

a. Channel Conditions

- Waterway features
- Rapid stream flows,
- Significant debris accumulation
- Constricted waterway openings
- Soft or unstable streambeds
- Meandering channels
- Other which may promote scour and undermining of substructure elements
- Navigable Waterway
- Flow Controls

b. Anticipated Water conditions which

may affect the inspection

- Cold Water (Apprx. Temp )
- Black water
- Rapid stream flows
- Near military facility
- Tribal fishing
- Water quality
- History of Log jams

c. Identify factors that may accelerate the deterioration of the bridge elements:

- Highly corrosive water
- Unprotected steel members
- Other

Risk Factor Narrative:

III. **Contacts Prior to Work**

District 2 Bridge Engineer: David Geckle, P.E.

Email: [david.geckle@dot.ohio.gov](mailto:david.geckle@dot.ohio.gov) – Phone: 419-373-4377

Point of contact for immediate action such as closing the bridge due to findings

Contact Bridge Owner 14 (number) days before the proposed underwater inspection.

Special contracting and scheduling procedures prior to inspection, include recommended lead time

Entity	Contact Name and Title	Contact Phone	Lead Time
Coast Guard			
Property Owner			
Access Equipment			
Lake or River draw-down			
Canal dry time			
Tree removal			
Other:			
Other:			

IV. **Dive Team Shall Include the Following:**

Dive Team Narrative:

The dive team consisted of one Team Leader (NBIS, P.E., ADCI) and two Team Members (NBIS, UW, ADCI)

*Example: The Bridge shall be investigated using a three-member dive team: one supervisor to monitor rack box and take notes, one diver, and one tender/standby diver. There shall be one NBIS Team Leader onsite at all times.*

V. **Site Information**

Navigable waterway:	Y / <u>N</u>	Anticipated current	<u>&lt;1</u> ft
If Yes, waterway river point	<u>N/A</u>	Scour Critical (item 113):	<u>5</u>
Anticipated water visibility depth	<u>&lt;1</u> ft	POA in place:	Y/ <u>N</u>
Anticipated Dive depth	<u>19</u> ft	Scour Monitoring devices present:	Y/ <u>N</u>

Verify the Scope of Services when work is contracted for the procedure for underwater elements that are not in water during an inspection.

Site Information Narrative:



The underwater inspection consists of a visual and tactile examination of the accessible surfaces of the substructure items in water. Additional items should reference the scope of services in the contract.

For reference the following items are in water:

<b>Item</b>	<b>Number of Units</b>	<b>Level of Inspection (1, 2 or 3) with Commentary</b>
Piers and Number of Columns	4	100% LEVEL I 10% LEVEL II
Abutment	N/A	
Culvert	N/A	
Scour Countermeasures	N/A	
Fenders or Dolphins	N/A	

Photographs should be taken, if water clarity permits, for typical conditions, conditions that have changed since last inspection and significant or noteworthy deficiencies. The type of channel bottom material, the presence or extent of scour, the presence or extent of riprap, the presence or extent of drift and debris, and the location of any foundation exposure or undermining shall be quantified. Include depth, length, height and location of deficiencies.

VI. Equipment and Field Logistics

a. The inspection should be conducted

using:

Chest waders

Hip waders

Diving equipment

SCUBA (Note that ADCI Consensus Standards require communication systems be employed for both SCUBA and Surface-Supplied (whether air or mixed-gas) dive modes)

SCUBA with communication

Surface Supplied with

communication

b. The channel bottom should be sounded

utilizing

Digital fathometer

Telescoping survey rod

acoustic imaging

c. During the inspection, the divers should

work from

Shore

Boat

Either

The note taker should work alongside the dive team.

d. Access to the waterway should be obtained from the shore (north bank, southwest quadrant, driveway 30 yards north etc.)

NORTHWEST EMBANKMENT

e. The maximum depth of the channel is typically measured \_\_\_\_\_ feet from

\_\_\_\_\_

Reference Datum: Top of Cap at the Downstream Nose of Pier 4

Soundings should be dictated by the scope of work. When not detailed in the scope they should be repeated from the previous soundings. If neither exist then they need to be taken in a grid pattern between substructure units 100' upstream and 100' downstream.

**VII. Inspection Procedure History**

Created: COLLINS ENGINEERS, INC. Date: 9/25/2020

Updated By: \_\_\_\_\_ Date: \_\_\_\_\_

Updated By: \_\_\_\_\_ Date: \_\_\_\_\_

Updated By: \_\_\_\_\_ Date: \_\_\_\_\_

Updated By: \_\_\_\_\_ Date: \_\_\_\_\_

Updated By: \_\_\_\_\_ Date: \_\_\_\_\_

**VIII. Other Narrative Not Included In Previous Sections**