



# UNDERWATER BRIDGE INSPECTION REPORT

STRUCTURE NO. 7202431 (SAN-53-1745)  
SR 53 OVER MUDDY CREEK  
SANDUSKY COUNTY, OH  
DISTRICT 2

May 2020

*Prepared for:*



10/9/2020

*Prepared by:*

**COLLINS**  
**ENGINEERS** INC.

124 Venture Court, Suite 10

Lexington, Kentucky 40511

859.367.0097 • [www.collinsengr.com](http://www.collinsengr.com)

**UNDERWATER INSPECTION**

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020



---

**TABLE OF CONTENTS**

**EXECUTIVE SUMMARY**

1.0 INTRODUCTION ..... 1

    1.1 Purpose and Scope ..... 1

    1.2 General Description of the Structure ..... 1

    1.3 Method of Investigation ..... 1

2.0 EXISTING CONDITIONS ..... 2

    2.1 General Conditions ..... 2

    2.2 Substructure Conditions ..... 3

        2.2.1 Bent 1 ..... 3

        2.2.2 Bent 2 ..... 3

        2.2.3 Bent 3 ..... 3

        2.2.4 Bent 4 ..... 3

3.0 EVALUATION AND RECOMMENDATIONS ..... 4

EXHIBIT 1 – FIGURES ..... 5

    LOCATION MAP

    SOUNDING PLAN

    CHANNEL CROSS SECTIONS - UPSTREAM

    CHANNEL CROSS SECTIONS - CENTERLINE

    CHANNEL CROSS SECTIONS - DOWNSTREAM

    BENT 1

    BENT 2

    BENT 3

    BENT 4

EXHIBIT 2 – INSPECTION PHOTOGRAPHS ..... 15

    Photograph No. 1: Overall View of Structure No. 7202431 (SAN-5301745), Looking Southeast.

    Photograph No. 2: Overall View of Structure No. 7202431 (SAN-53-1745), Looking West.

    Photograph No. 3: View of the North Embankment Upstream of the Structure, Looking Northeast.

    Photograph No. 4: View of the North Embankment at the Structure, Looking Northeast.

    Photograph No. 5: View of the North Embankment Downstream of the Structure, Looking Northeast.

    Photograph No. 6: View of the South Embankment Upstream of the Structure, Looking Southeast.

    Photograph No. 7: View of the South Embankment at the Structure, Looking Southeast.

**UNDERWATER INSPECTION**

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020



- 
- Photograph No. 8: View of the South Embankment Downstream of the Structure, Looking Southeast.
  - Photograph No. 9: View of the North Face of Bent 1, Looking Southeast.
  - Photograph No. 10: View of the South Face of Bent 1, Looking Northwest.
  - Photograph No. 11: View of the North Face of Bent 2, Looking Southeast.
  - Photograph No. 12: View of the South Face of Bent 2, Looking Northwest.
  - Photograph No. 13: View of the North Face of Bent 3, Looking Southeast.
  - Photograph No. 14: View of the South Face of Bent 3, Looking Northwest.
  - Photograph No. 15: View of the North Face of Bent 4, Looking Southeast.
  - Photograph No. 16: View of the South Face of Bent 4, Looking Northwest.
  - Photograph No. 17: View of the Typical Steel Condition at the Waterline on the Bent 4, Looking North.
  - Photograph No. 18: View of the Typical Steel Condition at the Waterline on the Upstream Nose of Bent 1, Looking South.

EXHIBIT 3 – UNDERWATER DIVE INSPECTION PROCEDURE CHECKLIST .....25



## UNDERWATER INSPECTION

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)

Sandusky County, OH • April 2020



- 
- The upstream and downstream nose pile exhibited loss of coating with typically 1/32 in. pitting with a maximum of 1/8 in. from channel bottom to bottom of cap.
  - **Bent 4:**
    - The channel bottom material consisted of rip-rap up to 24 in. diameter with no probe rod penetration.
    - The submerged portions of the steel H-piles exhibited light surface corrosion with rust nodules up to 2 in. diameter from channel bottom to -2 ft.
    - The upstream and downstream nose pile exhibited loss of coating with typically 1/32 in. pitting with a maximum of 1/8 in. from channel bottom to bottom of cap.

### *Summary of Recommendations:*

- Monitor light surface corrosion on steel H-piles.

## UNDERWATER INSPECTION

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020



---

### *Underwater Inspection Coding:*

#### **NBI Ratings:**

| <b>Item</b> | <b>Description</b>     | <b>Coding</b>                | <b>Condition</b>               |
|-------------|------------------------|------------------------------|--------------------------------|
| 60          | Substructure           | 7 – Good Condition           | Light Surface Corrosion        |
| 61          | Channel                | 7 – Good Condition           |                                |
| 62          | Culvert                | N/A                          |                                |
| 92B         | UW Insp. Frequency     | 60 Months                    |                                |
| 93B         | Previous Insp. Date    | 05/27/20                     |                                |
| 113         | Scour Critical Bridges | 5 – Within Foundation Limits | Stable (Inspector Recommended) |

#### **AASHTO National Bridge Element (NBE) Ratings:**

| <b>Element #</b> | <b>Description</b> | <b>Units</b> | <b>Total</b> | <b>Condition State</b> |          |          |          |
|------------------|--------------------|--------------|--------------|------------------------|----------|----------|----------|
|                  |                    |              |              | <b>1</b>               | <b>2</b> | <b>3</b> | <b>4</b> |
| 225              | Steel Pile         | EA           | 36           | 24                     | 8        | 0        | 0        |

Note: Ratings were developed using the FHWA Recording and Coding Guide for the Structure Inventory and Appraisal of the Nation's Bridges. The recommended ratings consider inspected elements located within the waterway and conditions existing below the water surface only. Additional consideration is necessary for the assignment of overall condition ratings for this bridge.



# UNDERWATER INSPECTION

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020



---

## 1.0 INTRODUCTION

### 1.1 Purpose and Scope

This report consists of the results of a detailed underwater investigation performed at the SR 53 Bridge over Sandusky River in Sandusky County, OH. Collins Engineers, Inc. (Collins) conducted the underwater investigation for District 2 of the Ohio Department of Transportation (ODOT) on May 27, 2020. The primary purpose of the investigation was as follows:

- Determine the condition of the substructure components located in the water at the time of the inspection from the waterline to the channel bottom.
- Obtain channel bottom depth measurements along the bridge fascias, upstream and downstream of the bridge, and around the submerged substructure units.
- Obtain channel profile cross sections at the upstream and downstream fascias.
- Determine the condition of the shorelines in the vicinity of the structure.
- Obtain photographs of the bridge and any significant defects.

In addition, a brief inspection was made of areas that could be submerged during periods of high water. The following report includes a description of the structure, the method of investigation, a description of existing conditions, an evaluation and recommendations based on the conditions, inspection figures, and photographs.

### 1.2 General Description of the Structure

Structure No. 7202431 (SAN-53-1745) spans 188 ft, carrying SR 53 over Sandusky River and is approximately 25.0 ft wide. The bridge superstructure is constructed of five continuous reinforced concrete spans. The roadway orientation of the longitudinal axis of the bridge is south to north. The substructure units are labeled as Abutments 1 and 2 and Bents 1 through 4. Existing record drawings were available at the time of the inspection. Refer to Figure 1 in Exhibit 1 for a Location Map of the bridge. Refer to Photographs 1 and 2 in Exhibit 2 for overall views of the bridge.

### 1.3 Method of Investigation

A detailed field inspection was conducted to determine the physical condition of the submerged bridge substructure units from the waterline to the channel bottom. A brief visual examination of the substructure units above the waterline was also made.

## UNDERWATER INSPECTION

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020

---



A three-person team consisting of a professional engineer-diver and team leader (Joshua Johnson, P.E.) and two engineer divers (Matthew Rogers, E.I.T. and Phillip Osborn, E.I.T.) conducted the underwater inspection. The inspection was conducted using surface supplied air diving equipment. During the inspection, the inspectors worked from a boat and a note taker in the boat recorded the inspection notes.

The underwater inspection consisted of a visual and tactile examination of the accessible surfaces of the substructure units from the waterline to the channel bottom with particular attention given to any observed areas of deterioration or apparent distress. Approximately 10 percent of the total area on the underwater surfaces of the substructure units was cleaned so that the condition could be more closely examined. Photographs were taken to document the general conditions and observed deficiencies. Underwater photographs could not be obtained due to poor water conditions. The type of channel bottom material, the presence or extent of scour, the presence or extent of riprap, the presence or extent of drift and debris, and the location of any foundation exposure or undermining were noted.

Channel bottom soundings were performed utilizing a telescoping survey rod and digital fathometer. Soundings were collected at quarter points along the bridge centerline as well as at quarter points along the upstream and downstream fascias and 50 ft fascias. Additional soundings were collected adjacent to Bents 1 through 4 and at 10 foot intervals in-line with the bents, upstream and downstream, and the waterline was referenced to a known elevation on the bridge. A sounding plan was developed using the soundings and approximate location of the shorelines. Refer to Figures 2 through 5 in Exhibit 1 for the sounding plan and channel cross sections that show the channel limits and water depths around the structure.

## 2.0 EXISTING CONDITIONS

### 2.1 General Conditions

At the time of the inspection, the waterline of 7202431 (SAN-53-1745) was located approximately 3.3 ft below the top of cap at the upstream nose of Bent 1, which corresponds to a waterline elevation of 572.0 ft. During the inspection, the waterway was flowing at less than 1 ft per second. The bridge bent skew was consistent with the channel alignment and does not require attention at this time. The north and south shorelines consisted of moderately vegetated gentle slopes which were well protected with no signs of erosion. Refer to Photographs 3 through 8 in Exhibit 2 for views of the shorelines near the structure.



## UNDERWATER INSPECTION

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020



---

### 2.2 Substructure Conditions

#### 2.2.1 *Bent 1*

The channel bottom material consisted of rip-rap up to 24 in. diameter with no probe rod penetration. The submerged portions of the steel H-piles exhibited light surface corrosion with rust nodules up to 2 in. diameter from channel bottom to -2 ft. The upstream and downstream nose pile exhibited loss of coating with typically 1/32 in. pitting with a maximum of 1/8 in. from channel bottom to bottom of cap. Refer to Figure 6 in Exhibit 1 for detailed inspection notes of Bent 1. Refer to Photographs 9 and 10 in Exhibit 2 for views of Bent 1.

#### 2.2.2 *Bent 2*

The channel bottom material consisted of rip-rap up to 24 in. diameter with no probe rod penetration. The submerged portions of the steel H-piles exhibited light surface corrosion with rust nodules up to 2 in. diameter from channel bottom to -2 ft. The upstream and downstream nose pile exhibited loss of coating with typically 1/32 in. pitting with a maximum of 1/8 in. from channel bottom to bottom of cap. Refer to Figure 7 in Exhibit 1 for detailed inspection notes of Bent 2. Refer to Photographs 11 and 12 in Exhibit 2 for views of Bent 2.

#### 2.2.3 *Bent 3*

The channel bottom material consisted of rip-rap up to 24 in. diameter with no probe rod penetration. The submerged portions of the steel H-piles exhibited light surface corrosion with rust nodules up to 2 in. diameter from channel bottom to -2 ft. The upstream and downstream nose pile exhibited loss of coating with typically 1/32 in. pitting with a maximum of 1/8 in. from channel bottom to bottom of cap. Refer to Figure 8 in Exhibit 1 for detailed inspection notes of Bent 3. Refer to Photographs 13 and 14 in Exhibit 2 for views of Bent 3.

#### 2.2.4 *Bent 4*

The channel bottom material consisted of rip-rap up to 24 in. diameter with no probe rod penetration. The submerged portions of the steel H-piles exhibited light surface corrosion with rust nodules up to 2 in. diameter from channel bottom to -2 ft. The upstream and downstream nose pile exhibited loss of coating with typically 1/32 in. pitting with a maximum of 1/8 in. from channel bottom to bottom of cap. Refer to Figure 9 in Exhibit 1 for detailed inspection notes of Bent 4. Refer to Photographs 15 through 18 in Exhibit 2 for views of Bent 4 and typical steel condition at the waterline.

## UNDERWATER INSPECTION

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020



---

### 3.0 EVALUATION AND RECOMMENDATIONS

Overall, the inspected substructure units of Structure No. 7202431 (SAN-53-1745) were in good condition. A comparison of the soundings recorded during the previous inspection on June 21, 2015 and the soundings taken during this inspection revealed no significant change in the channel bottom profile in the vicinity of the structure. Although no channel deficiencies were observed, the channel bottom should continue to be monitored during future underwater inspections to verify that localized scour or overall channel degradation is not occurring and that the bent footings remain adequately embedded in the channel bottom. The corrosion on the upstream and downstream piles of Bents 1 through 4 is not a structural concern at this time, and as a result, no repairs are recommended.

It is recommended that the submerged substructure units of Structure No. 7202431 (SAN-53-1745) be next inspected underwater at an interval not to exceed 60 months, no later than May 27, 2025.

Respectfully Submitted,  
COLLINS ENGINEERS, INC.

A handwritten signature in black ink, appearing to read "Joshua Johnson".

Joshua Johnson, P.E.  
Project Manager

Originated by:  
Kevin Mitchell, E.I.T.

**UNDERWATER INSPECTION**


SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)

Sandusky County, OH • April 2020

---



**EXHIBIT 1 – FIGURES**



**COLLINS ENGINEERS**


124 Venture Court, Ste 10  
Lexington, KY 40511  
Phone: 859-367-0097  
Fax: 859-367-0140



Ohio Department of  
Transportation, District 2  
317 East Poe Rd.  
Bowling Green, OH 45601  
Phone: 419-353-8131

SR-53 OVER MUDDY CREEK  
STRUCTURE NO. 7202431  
(SAN-53-1745)  
LOCATION MAP  
SANDUSKY COUNTY, OHIO

|                      |                             |
|----------------------|-----------------------------|
| INSPECTED BY:<br>MOR | CEI PROJECT:<br>55-12239.00 |
| DRAWN BY:<br>BLV     | DATE:<br>27 MAY 2020        |
| CHECKED BY:<br>JMJ   | SHEET NO:<br><b>1</b>       |



SOUNDING PLAN

GENERAL NOTES:

1. Bents 1 through 4 were inspected underwater. Substructure units are labeled according to available record drawings.
2. At the time of inspection on May 27, 2020, the waterline was located approximately 3.3 ft below Top of Cap at upstream nose of Bent 1 (EL. +572.0 ft). This corresponds with a waterline elevation of +568.7 ft.
3. Soundings indicate the water depth at the time of inspection and are measured in feet.
4. Soundings were taken parallel to the bridge at the upstream and downstream fascias, at 10 ft intervals between the substructure units, and at 10 ft intervals in-line with the piers upstream and downstream up to 50 ft.

LEGEND

- 2.7 Sounding Depth from Waterline (ft)
- Timber Debris

**COLLINS ENGINEERS**  
 124 Venture Court, Ste 10  
 Lexington, KY 40511  
 Phone: 859-367-0097  
 Fax: 859-367-0140


Ohio Department of Transportation, District 2  
 317 East Poe Rd.  
 Bowling Green, OH 45601  
 Phone: 419-353-8131

SR-53 OVER MUDDY CREEK  
 STRUCTURE NO. 7202431 (SAN-53-1745)  
**SOUNDING PLAN**  
 SANDUSKY COUNTY, OHIO


CEI PROJECT  
 55-12239.00  
 INSPECTED BY:  
 MOR  
 DRAWN BY:  
 BLV  
 CHECKED BY:  
 JMJ  
 DATE:  
 MAY 2020  
 SHEET NO:  
**2**

| UPSTREAM FASCIA<br>LOOKING DOWNSTREAM |        |
|---------------------------------------|--------|
| Location                              | Y(ft)* |
| A1                                    | 6.2    |
| 1/4                                   | 7.6    |
| 1/2                                   | 7.6    |
| 3/4                                   | 7.6    |
| B1                                    | 7.6    |
| 1/4                                   | 7.6    |
| 1/2                                   | 7.6    |
| 3/4                                   | 7.6    |
| B2                                    | 7.6    |
| 1/4                                   | 7.6    |
| 1/2                                   | 7.6    |
| 3/4                                   | 7.6    |
| A2                                    | 6.2    |

\*Profile taken from top of deck to channel bottom



CHANNEL CROSS SECTION  
UPSTREAM FASCIA  
(LOOKING DOWNSTREAM)



CHANNEL CROSS SECTION  
50 FT UPSTREAM  
(LOOKING DOWNSTREAM)

LEGEND

- Approximate Channel Bottom – May 2020
- - - Approximate Channel Bottom – June 2015 (No Data)
- - - Approximate Channel Bottom – June 2010 (No Data)
- Timber Debris
- Water Surface
- +450 Elevation (ft)

Note:

Footing elevations unknown due to unavailable design drawings.

**COLLINS ENGINEERS**  
124 Venture Court, Ste 10  
Lexington, KY 40511  
Phone: 859-367-0097  
Fax: 859-367-0140



Ohio Department of Transportation, District 2  
317 East Poe Rd.  
Bowling Green, OH 43401  
Phone: 419-353-8131

SR-53 OVER MUDDY CREEK  
STRUCTURE NO. 7202431 (SAN-53-1745)  
CROSS SECTIONS - UPSTREAM  
SANDUSKY COUNTY, OHIO

CEI PROJECT  
55-12239.00

INSPECTED BY:  
MOR


DRAWN BY:  
BLV

CHECKED BY:  
JMJ

DATE:  
MAY 2020

SHEET NO:  
**3**





CHANNEL CROSS SECTION  
 STRUCTURE CENTERLINE  
 (LOOKING DOWNSTREAM)

LEGEND


- Approximate Channel Bottom - May 2020
- - - Approximate Channel Bottom - June 2015 (No Data)
- - - Approximate Channel Bottom - June 2010 (No Data)
- Timber Debris
- Water Surface
- +450 Elevation (ft)

Note:


Footings unknown due to unavailable design drawings.

| DOWNSTREAM FASCIA<br>LOOKING DOWNSTREAM |        |
|---|--------|
| Location                                | Y(ft)* |
| A1                                      | 4.6    |
| 1/4                                     | 6.2    |
| 1/2                                     | 7.6    |
| 3/4                                     | 7.6    |
| B1                                      | 7.6    |
| 1/4                                     | 7.6    |
| 1/2                                     | 7.6    |
| 3/4                                     | 7.6    |
| B2                                      | 7.6    |
| 1/4                                     | 7.6    |
| 1/2                                     | 7.6    |
| 3/4                                     | 7.4    |
| A2                                      | 4.7    |

\*Profile taken from top of deck to channel bottom



CHANNEL CROSS SECTION  
DOWNSTREAM FASCIA  
(LOOKING DOWNSTREAM)



CHANNEL CROSS SECTION  
50 FT DOWNSTREAM  
(LOOKING DOWNSTREAM)

LEGEND

- Approximate Channel Bottom – May 2020
- - - Approximate Channel Bottom – June 2015 (No Data)
- - - Approximate Channel Bottom – June 2010 (No Data)
- Timber Debris
- Water Surface
- +450 Elevation (ft)

Note:

Footing elevations unknown due to unavailable design drawings.

**COLLINS ENGINEERS**  
124 Venture Court, Ste 10  
Lexington, KY 40511  
Phone: 859-367-0097  
Fax: 859-367-0140



Ohio Department of Transportation, District 2  
317 East Poe Rd.  
Bowling Green, OH 43401  
Phone: 419-353-8131

SR-53 OVER MUDDY CREEK  
STRUCTURE NO. 7202431 (SAN-53-1745)  
CROSS SECTIONS - DOWNSTREAM  
SANDUSKY COUNTY, OHIO

CEI PROJECT  
55-12239.00


INSPECTED BY:  
MOR

DRAWN BY:  
BLV

CHECKED BY:  
JMJ


DATE:  
MAY 2020

SHEET NO:  
5




NORTH ELEVATION  
(LOOKING SOUTH)

SOUTH ELEVATION  
(LOOKING NORTH)



PLAN




INSPECTION NOTES:

- ① The channel bottom material consisted of rip-rap up to 24 in. diameter with no probe rod penetration.
- ② The submerged portions of the steel H-Piles exhibited light surface corrosion with rust nodules up to 2 in. diameter from the channel bottom to -2 ft.
- ③ The upstream and downstream nose pile exhibited loss of coating with typically 1/32 in. pitting with a maximum of 1/8 in. from channel bottom to bottom of cap.


LEGEND

- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom - May 2020
- ⊗ Timber Debris
- ∇— Water Surface



NORTH ELEVATION  
 (LOOKING SOUTH)

SOUTH ELEVATION  
 (LOOKING NORTH)




PLAN

LEGEND

- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom - May 2020
- ⊗ Timber Debris
- ∇ Water Surface


INSPECTION NOTES:

- ① The channel bottom material consisted of rip-rap up to 24 in. diameter with no probe rod penetration.
- ② The submerged portions of the steel H-Piles exhibited light surface corrosion with rust nodules up to 2 in. diameter from the channel bottom to -2 ft.
- ③ The upstream and downstream nose pile exhibited loss of coating with typically 1/32 in. pitting with a maximum of 1/8 in. from channel bottom to bottom of cap.



NORTH ELEVATION  
 (LOOKING SOUTH)

SOUTH ELEVATION  
 (LOOKING NORTH)



PLAN


LEGEND

- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom - May 2020
- ⊗ Timber Debris
- ∇ Water Surface

INSPECTION NOTES:


- ① The channel bottom material consisted of rip-rap up to 24 in. diameter with no probe rod penetration.
- ② The submerged portions of the steel H-Piles exhibited light surface corrosion with rust nodules up to 2 in. diameter from the channel bottom to -2 ft.
- ③ The upstream and downstream nose pile exhibited loss of coating with typically 1/32 in. pitting with a maximum of 1/8 in. from channel bottom to bottom of cap.





NORTH ELEVATION  
 (LOOKING SOUTH)

SOUTH ELEVATION  
 (LOOKING NORTH)



PLAN

INSPECTION NOTES:

- ① The channel bottom material consisted of rip-rap up to 24 in. diameter with no probe rod penetration.
- ② The submerged portions of the steel H-Piles exhibited light surface corrosion with rust nodules up to 2 in. diameter from the channel bottom to -2 ft.
- ③ The upstream and downstream nose pile exhibited loss of coating with typically 1/32 in. pitting with a maximum of 1/8 in. from channel bottom to bottom of cap.

LEGEND

- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom - May 2020
- ⊗ Timber Debris
- ∇ Water Surface



**UNDERWATER INSPECTION**

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)

Sandusky County, OH • April 2020

---



**EXHIBIT 2 – INSPECTION PHOTOGRAPHS**

**UNDERWATER INSPECTION**

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020



Photograph No. 1: Overall View of Structure No. 7202431 (SAN-5301745), Looking Southeast.



Photograph No. 2: Overall View of Structure No. 7202431 (SAN-53-1745), Looking West.



**UNDERWATER INSPECTION**

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020



Photograph No. 3: View of the North Embankment Upstream of the Structure, Looking Northeast.



Photograph No. 4: View of the North Embankment at the Structure, Looking Northeast.



**UNDERWATER INSPECTION**

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020



Photograph No. 5: View of the North Embankment Downstream of the Structure, Looking Northeast.



Photograph No. 6: View of the South Embankment Upstream of the Structure, Looking Southeast.



**UNDERWATER INSPECTION**

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020



Photograph No. 7: View of the South Embankment at the Structure, Looking Southeast.



Photograph No. 8: View of the South Embankment Downstream of the Structure, Looking Southeast.



**UNDERWATER INSPECTION**

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020



Photograph No. 9: View of the North Face of Bent 1, Looking Southeast.



Photograph No. 10: View of the South Face of Bent 1, Looking Northwest.



**UNDERWATER INSPECTION**

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020



Photograph No. 11: View of the North Face of Bent 2, Looking Southeast.



Photograph No. 12: View of the South Face of Bent 2, Looking Northwest.

**UNDERWATER INSPECTION**

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020



Photograph No. 13: View of the North Face of Bent 3, Looking Southeast.



Photograph No. 14: View of the South Face of Bent 3, Looking Northwest.



**UNDERWATER INSPECTION**

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020



Photograph No. 15: View of the North Face of Bent 4, Looking Southeast.



Photograph No. 16: View of the South Face of Bent 4, Looking Northwest.



**UNDERWATER INSPECTION**

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)  
Sandusky County, OH • April 2020



Photograph No. 17: View of the Typical Steel Condition at the Waterline on the Bent 4, Looking North.



Photograph No. 18: View of the Typical Steel Condition at the Waterline on the Upstream Nose of Bent 1, Looking South.

**UNDERWATER INSPECTION**

SR 53 over Muddy Creek • Structure No. 7202431 (SAN-53-1745)

Sandusky County, OH • April 2020

---



**EXHIBIT 3 – UNDERWATER DIVE INSPECTION PROCEDURE  
CHECKLIST**





**b. Photographs**

Endview



Elevation



Underside

**II. Office and Field Assessment**

Prior to the inspection, obtain and review copies of the previous underwater inspection reports, routine inspection reports, scour and hydraulic information, and design plans in preparation of the inspection.

Divers should pay particular attention given to any observed areas of deterioration, the channel conditions and factors that may accelerate material deterioration. Changes shall be noted in the inspection procedure. Site conditions should be reviewed prior to diving.

a. Channel Conditions

- Waterway features
- Rapid stream flows,
- Significant debris accumulation
- Constricted waterway openings
- Soft or unstable streambeds
- Meandering channels
- Other which may promote scour and undermining of substructure elements
- Navigable Waterway
- Flow Controls

b. Anticipated Water conditions which may affect the inspection

- Cold Water (Apprx. Temp\_\_\_)
- Black water
- Rapid stream flows
- Near military facility
- Tribal fishing
- Water quality
- History of Log jams

c. Identify factors that may accelerate the deterioration of the bridge elements:

- Highly corrosive water
- Unprotected steel members
- Other

Risk Factor Narrative:

III. **Contacts Prior to Work**

District 2 Bridge Engineer: David Geckle, P.E.

Email: [david.geckle@dot.ohio.gov](mailto:david.geckle@dot.ohio.gov) – Phone: 419-373-4377

Point of contact for immediate action such as closing the bridge due to findings

Contact Bridge Owner 14 (number) days before the proposed underwater inspection.

Special contracting and scheduling procedures prior to inspection, include recommended lead time

| Entity                  | Contact Name and Title | Contact Phone | Lead Time |
|-------------------------|------------------------|---------------|-----------|
| Coast Guard             |                        |               |           |
| Property Owner          |                        |               |           |
| Access Equipment        |                        |               |           |
| Lake or River draw-down |                        |               |           |
| Canal dry time          |                        |               |           |
| Tree removal            |                        |               |           |
| Other:                  |                        |               |           |
| Other:                  |                        |               |           |

IV. **Dive Team Shall Include the Following:**

Dive Team Narrative:

The dive team consisted of one Team Leader (NBIS, P.E., ADCI) and two Team Members (NBIS, UW, ADCI)

*Example: The Bridge shall be investigated using a three-member dive team: one supervisor to monitor rack box and take notes, one diver, and one tender/standby diver. There shall be one NBIS Team Leader onsite at all times.*

V. **Site Information**

|                                    |              |                                   |                 |
|------------------------------------|--------------|-----------------------------------|-----------------|
| Navigable waterway:                | Y / <u>N</u> | Anticipated current               | <u>&lt;1</u> ft |
| If Yes, waterway river point       | <u>N/A</u>   | Scour Critical (item 113):        | <u>5</u>        |
| Anticipated water visibility depth | <u>1</u> ft  | POA in place:                     | Y/ <u>N</u>     |
| Anticipated Dive depth             | <u>15</u> ft | Scour Monitoring devices present: | Y/ <u>N</u>     |

Verify the Scope of Services when work is contracted for the procedure for underwater elements that are not in water during an inspection.

Site Information Narrative:

The underwater inspection consists of a visual and tactile examination of the accessible surfaces of the substructure items in water. Additional items should reference the scope of services in the contract.

For reference the following items are in water:

| <b>Item</b>                 | <b>Number of Units</b> | <b>Level of Inspection (1, 2 or 3) with<br/>Commentary</b> |
|-----------------------------|------------------------|--|
| Piers and Number of Columns | 4                      | 100% LEVEL I<br>10% LEVEL II                               |
| Abutment                    | N/A                    |  |
| Culvert                     | N/A                    |  |
| Scour Countermeasures       | N/A                    |  |
| Fenders or Dolphins         | N/A                    |  |

Photographs should be taken, if water clarity permits, for typical conditions, conditions that have changed since last inspection and significant or noteworthy deficiencies. The type of channel bottom material, the presence or extent of scour, the presence or extent of riprap, the presence or extent of drift and debris, and the location of any foundation exposure or undermining shall be quantified. Include depth, length, height and location of deficiencies.

VI. Equipment and Field Logistics

a. The inspection should be conducted

using:

Chest waders

Hip waders

Diving equipment

SCUBA (Note that ADCI Consensus Standards require communication systems be employed for both SCUBA and Surface-Supplied (whether air or mixed-gas) dive modes)

SCUBA with communication

Surface Supplied with

communication

b. The channel bottom should be sounded

utilizing

Digital fathometer

Telescoping survey rod

acoustic imaging

c. During the inspection, the divers should

work from

Shore

Boat

Either

The note taker should work alongside the dive team.

d. Access to the waterway should be obtained from the shore (north bank, southwest quadrant, driveway 30 yards north etc.)

Riverfront Marina & Campgrounds Public

Boat Ramp

e. The maximum depth of the channel is typically measured \_\_\_\_\_ feet from

The South Quarter Point at the

Structure Centerline Between Bents 2

and 3

Reference Datum: Top of Cap at the Upstream

Nose of Bent 1

Soundings should be dictated by the scope of work. When not detailed in the scope they should be repeated from the previous soundings. If neither exist then they need to be taken in a grid pattern between substructure units 100' upstream and 100' downstream.



**VII. Inspection Procedure History**

Created: COLLINS ENGINEERS, INC Date: 9/25/2020

Updated By: \_\_\_\_\_ Date: \_\_\_\_\_

Updated By: \_\_\_\_\_ Date: \_\_\_\_\_

Updated By: \_\_\_\_\_ Date: \_\_\_\_\_

Updated By: \_\_\_\_\_ Date: \_\_\_\_\_

Updated By: \_\_\_\_\_ Date: \_\_\_\_\_

**VIII. Other Narrative Not Included In Previous Sections**