



# UNDERWATER BRIDGE INSPECTION REPORT

STRUCTURE NO. 7402910 (SEN-224-1207)  
US-224 OVER SANDUSKY RIVER  
SENECA COUNTY, OH  
DISTRICT 2

May 2020

*Prepared for:*



10/9/2020

*Prepared by:*

**COLLINS**  
**ENGINEERS** INC.

124 Venture Court, Suite 10

Lexington, Kentucky 40511

859.367.0097 • [www.collinsengr.com](http://www.collinsengr.com)



TABLE OF CONTENTS

EXECUTIVE SUMMARY

1.0 INTRODUCTION ..... 1

    1.1 Purpose and Scope ..... 1

    1.2 General Description of the Structure ..... 1

    1.3 Method of Investigation ..... 1

2.0 EXISTING CONDITIONS ..... 2

    2.1 General Conditions ..... 2

    2.2 Substructure Conditions ..... 3

        2.2.1 Pier 1 ..... 3

        2.2.2 Pier 2 ..... 3

        2.2.3 Pier 3 ..... 3

        2.2.4 Pier 4 ..... 3

3.0 EVALUATION AND RECOMMENDATIONS ..... 4

EXHIBIT 1 – FIGURES ..... 5

LOCATION MAP

SOUNDING PLAN

CHANNEL CROSS SECTIONS - UPSTREAM

CHANNEL CROSS SECTIONS - CENTERLINE

CHANNEL CROSS SECTIONS - DOWNSTREAM

PIER 1

PIER 2

PIER 3

PIER 4

EXHIBIT 2 – INSPECTION PHOTOGRAPHS ..... 15

- Photograph No. 1: Overall View of Structure No. 7402910 (SEN-224-1207), Looking North.
- Photograph No. 2: Overall View of Structure No. 7402910 (SEN-224-1207), Looking South.
- Photograph No. 3: View of the West Embankment Upstream of the Structure, Looking Southwest.
- Photograph No. 4: View of the West Embankment at the Structure, Looking West.
- Photograph No. 5: View of the West Embankment Downstream of the Structure, Looking Northwest.
- Photograph No. 6: View of the East Embankment Upstream of the Structure, Looking Southeast.
- Photograph No. 7: View of the East Embankment at the Structure, Looking East.
- Photograph No. 8: View of the East Embankment Downstream of the Structure, Looking Northeast.

**UNDERWATER INSPECTION**

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)  
Seneca County, OH • May 2020



- 
- Photograph No. 9: View of the East Face of Pier 1, Looking Southwest.
  - Photograph No. 10: View of the West Face of Pier 1, Looking Northeast.
  - Photograph No. 11: View of the West Face of Pier 2, Looking Southwest.
  - Photograph No. 12: View of the East Face of Pier 2, Looking Northeast.
  - Photograph No. 13: View of the East Face of Pier 3, Looking Southwest.
  - Photograph No. 14: View of the West Face of Pier 3, Looking Northeast.
  - Photograph No. 15: View of the East Face of Pier 4, Looking Southwest.
  - Photograph No. 16: View of the West Face of Pier 4, Looking Northeast.
  - Photograph No. 17: View of the Typical Concrete Condition at the Waterline, Looking West.

EXHIBIT 3 – UNDERWATER DIVE INSPECTION PROCEDURE CHECKLIST .....25





## UNDERWATER INSPECTION

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)

Seneca County, OH • May 2020



- 
- **Pier 3:**
    - The channel bottom material around the pier consisted of timber debris with twigs and silt overly with up to 6 in. probe rod penetration.
    - The submerged portions of the pier were smooth and south with no defects noted.
    - Moderate timber debris accumulation consisting of logs up to 1 ft diameter were observed on the upstream nose extending along the north face from the channel bottom to 2 ft about the waterline.
  - **Pier 4:**
    - The channel bottom material around the pier consisted of timber debris with twigs and silt overly with up to 6 in. probe rod penetration.
    - The submerged portions of the pier were smooth and south with no defects noted.
    - Light timber debris accumulation consisting of branches up to 6 in. diameter were observed on the upstream nose extending up to a 5 ft radius around the upstream nose from the channel bottom to 2 ft about the waterline.

### *Summary of Recommendations:*

- Remove timber debris at all Piers.
- Monitor scour during routine underwater inspections.

## UNDERWATER INSPECTION

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)

Seneca County, OH • May 2020



---

### *Underwater Inspection Coding:*

#### **NBI Ratings:**

<b>Item</b>	<b>Description</b>	<b>Coding</b>	<b>Condition</b>
60	Substructure	7 – Good Condition	No Defects Observed
61	Channel	5 – Fair Condition	Minor Scour, Timber Debris Accumulation
62	Culvert	N/A	
92B	UW Insp. Frequency	60 Months	
93B	Insp. Date	05 28 20	
113	Scour Critical Bridges	8 – Above Foundation Limits	Stable (Inspector Recommended)

#### **AASHTO National Bridge Element (NBE) Ratings:**

<b>Element #</b>	<b>Description</b>	<b>Units</b>	<b>Total</b>	<b>Condition State</b>			
				<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>
210	Reinforced Concrete Pier Wall	LF	120	120	0	0	0

Note: Ratings were developed using the FHWA Recording and Coding Guide for the Structure Inventory and Appraisal of the Nation's Bridges. The recommended ratings consider inspected elements located within the waterway and conditions existing below the water surface only. Additional consideration is necessary for the assignment of overall condition ratings for this bridge.

# UNDERWATER INSPECTION

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)  
Seneca County, OH • May 2020



---

## 1.0 INTRODUCTION

### 1.1 Purpose and Scope

This report consists of the results of a detailed underwater investigation performed at the US-224 Bridge over Sandusky River in Seneca County, OH. Collins Engineers, Inc. (Collins) conducted the underwater investigation for District 2 of the Ohio Department of Transportation (ODOT) on May 28, 2020. The primary purpose of the investigation was as follows:

- Determine the condition of the substructure components located in the water at the time of the inspection from the waterline to the channel bottom.
- Obtain channel bottom depth measurements along the bridge fascias, upstream and downstream of the bridge, and around the submerged substructure units.
- Obtain channel profile cross sections at the upstream and downstream fascias.
- Determine the condition of the shorelines in the vicinity of the structure.
- Obtain photographs of the bridge and any significant defects.

In addition, a brief inspection was made of areas that could be submerged during periods of high water. The following report includes a description of the structure, the method of investigation, a description of existing conditions, an evaluation and recommendations based on the conditions, inspection figures, and photographs.

### 1.2 General Description of the Structure

Structure No. 7402910 (SEN-224-1207) spans 806.85 ft, carrying US-224 over Sandusky River and is approximately 95 ft wide. The bridge superstructure is constructed of five steel beam spans. The roadway orientation of the longitudinal axis of the bridge is west to east. The substructure units are labeled as Abutments 1 and 2 and Piers 1 through 4. Existing record drawings were available at the time of the inspection. Refer to Figure 1 in Exhibit 1 for a Location Map of the bridge. Refer to Photographs 1 and 2 in Exhibit 2 for overall views of the bridge.

### 1.3 Method of Investigation

A detailed field inspection was conducted to determine the physical condition of the submerged bridge substructure units from the waterline to the channel bottom. A brief visual examination of the substructure units above the waterline was also made.

## UNDERWATER INSPECTION

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)  
Seneca County, OH • May 2020



A three-person team consisting of a professional engineer-diver and team leader (Joshua Johnson, P.E.) and two engineer divers (Matthew Rogers, E.I.T. and Phillip Osborn, E.I.T.) conducted the underwater inspection. The inspection was conducted using surface supplied air diving equipment. During the inspection, the inspectors worked from a kayak and a note taker on the shore recorded the inspection notes.

The underwater inspection consisted of a visual and tactile examination of the accessible surfaces of the substructure units from the waterline to the channel bottom with particular attention given to any observed areas of deterioration or apparent distress. Approximately 10 percent of the total area on the underwater surfaces of the substructure units was cleaned so that the condition could be more closely examined. Photographs were taken to document the general conditions and observed deficiencies. Underwater photographs could not be obtained due to poor water conditions. The type of channel bottom material, the presence or extent of scour, the presence or extent of riprap, the presence or extent of drift and debris, and the location of any foundation exposure or undermining were noted.

Channel bottom soundings were performed utilizing a telescoping survey rod, digital fathometer, and pneumofathometer. Soundings were collected at quarter points along the bridge centerline as well as at quarter points along the upstream and downstream fascias and 50 ft fascias. Additional soundings were collected adjacent to Piers 1 through 4 and at 10 foot intervals in-line with the piers, upstream and downstream, and the waterline was referenced to a known elevation on the bridge. A sounding plan was developed using the soundings and approximate location of the shorelines. Refer to Figures 2 through 5 in Exhibit 1 for the sounding plan and channel cross sections that show the channel limits and water depths around the structure.

## 2.0 EXISTING CONDITIONS

### 2.1 General Conditions

At the time of the inspection, the waterline of 7402910 (SEN-224-1207) was located approximately 7.5 ft below the top of cap at the downstream nose of Pier 2, which corresponds to a waterline elevation of 734.8 ft. During the inspection, the waterway was flowing at approximately 1 ft per second. The bridge pier skew was consistent with the channel alignment and does not require attention at this time. The east and west shorelines consisted of well protected, well-vegetated, mild slopes with no signs erosion and a steel sheet pile wall on the southwest embankment. Refer to Photographs 3 through 8 in Exhibit 2 for views of the shorelines near the structure.



## 2.2 Substructure Conditions

### 2.2.1 *Pier 1*

The channel bottom material around the pier consisted of timber debris with twigs and silt overly with up to 6 in. probe rod penetration. The submerged portions of the pier were smooth and south with no defects noted. A scour depression measuring approximately 10 ft diameter by 2 ft deep was observed on the southwest corner of the pier just downstream of the timber debris. Severe timber debris accumulation consisting of logs up to 2 ft diameter were observed on the upstream nose extending up to a 15 ft radius around the upstream nose from channel bottom to 4 ft about the waterline. Refer to Figure 6 in Exhibit 1 for detailed inspection notes of Pier 1. Refer to Photographs 9 and 10 in Exhibit 2 for views of Pier 1.

### 2.2.2 *Pier 2*

The channel bottom material around the pier consisted of timber debris with twigs and silt overly with up to 6 in. probe rod penetration. The submerged portions of the pier were smooth and south with no defects noted. A scour depression measuring approximately 10 ft diameter by 2 ft deep was observed on the northeast corner of the pier just downstream of the timber debris. Heavy timber debris accumulation consisting of logs up to 2 ft diameter were observed on the upstream nose extending up to a 10 ft radius around the upstream nose from channel bottom to 2 ft about the waterline. Refer to Figure 7 in Exhibit 1 for detailed inspection notes of Pier 2. Refer to Photographs 11 and 12 in Exhibit 2 for views of Pier 2.

### 2.2.3 *Pier 3*

The channel bottom material around the pier consisted of timber debris with twigs and silt overly with up to 6 in. probe rod penetration. The submerged portions of the pier were smooth and south with no defects noted. Moderate timber debris accumulation consisting of logs up to 1 ft diameter were observed on the upstream nose extending along the north face from the channel bottom to 2 ft about the waterline. Refer to Figure 8 in Exhibit 1 for detailed inspection notes of Pier 3. Refer to Photographs 13 and 14 in Exhibit 2 for views of Pier 3.

### 2.2.4 *Pier 4*

The channel bottom material around the pier consisted of timber debris with twigs and silt overly with up to 6 in. probe rod penetration. The submerged portions of the pier were smooth and south with no defects noted. Light timber debris accumulation consisting of branches up to 6 in. diameter were observed on the upstream nose extending up to a 5 ft radius around the upstream nose from the channel bottom to 2 ft about the waterline.



## UNDERWATER INSPECTION

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)  
Seneca County, OH • May 2020



---

Refer to Figure 9 in Exhibit 1 for detailed inspection notes of Pier 4. Refer to Photographs 15 through 17 in Exhibit 2 for views of Pier 4 and typical concrete condition at the waterline.

### 3.0 EVALUATION AND RECOMMENDATIONS

Overall, the submerged substructure units of Structure No. 7402910 (SEN-224-1207) were in good condition below water. A comparison of the soundings recorded during the previous inspection on June 24, 2015 and the soundings taken during this inspection revealed no significant change in the channel bottom profile in the vicinity of the structure. The minor scour depressions observed at Piers 1 through 4 are not a concern at this time given that the bottom of the footing is embedded in the channel bottom. The channel bottom configuration should continue to be closely monitored during future underwater inspections to verify that the scour depressions at Piers 1 through 4 are not increasing and that all footings remain adequately embedded in the channel bottom.

The timber debris accumulations at Piers 1 through 4 is obstructing channel flow, is the cause of scour, and should be removed at this time. Removal of the timber debris will reduce excessive lateral loads on the pier, limit further debris accumulation, and reduce the likelihood of channel bottom degradation resulting from obstructed flow.

It is recommended that the submerged substructure units of Structure No. 7402910 (SEN-224-1207) be next inspected underwater at an interval not to exceed 60 months, no later than May 28, 2025.

Respectfully Submitted,  
COLLINS ENGINEERS, INC.

A handwritten signature in black ink, appearing to read "Joshua Johnson".

Joshua Johnson, P.E.  
Project Manager

Originated by:  
Kevin Mitchell, E.I.T.

**UNDERWATER INSPECTION**


US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)

Seneca County, OH • May 2020

---



**EXHIBIT 1 – FIGURES**



**COLLINS ENGINEERS**

124 Venture Court, Ste 10  
Lexington, KY 40511  
Phone: 859-367-0097  
Fax: 859-367-0140



Ohio Department of  
Transportation, District 2  
317 East Poe Rd.  
Bowling Green, OH 45601  
Phone: 419-353-8131

US-224 OVER SANDUSKY RIVER  
STRUCTURE NO. 7402910  
(SEN-224-1207)  
LOCATION MAP  
SENECA COUNTY, OHIO

INSPECTED BY:  
MOR


CEI PROJECT:  
55-12239.00

DRAWN BY:  
BLV

DATE:  
28 MAY 2020

CHECKED BY:  
JMJ

SHEET NO:  
**1**



SOUNDING PLAN

GENERAL NOTES:

1. Piers 1, 2, 3, and 4 were inspected underwater. Substructure units are labeled according to previous report.
2. At the time of inspection on May 28, 2020, the waterline was located approximately 7.5 ft below Top of Cap at downstream nose of Pier 2 (EL. +742.3 ft). This corresponds with a waterline elevation of +734.8 ft.
3. Soundings indicate the water depth at the time of inspection and are measured in feet.
4. Soundings were taken parallel to the bridge at the upstream and downstream fascias, at 10 ft intervals between the substructure units, and at 10 ft intervals in-line with the piers upstream and downstream up to 50 ft.

LEGEND

- 2.7 Sounding Depth from Waterline (ft)
- Timber Debris

**COLLINS ENGINEERS**  
 124 Venture Court, Ste 10  
 Lexington, KY 40511  
 Phone: 859-367-0097  
 Fax: 859-367-0140



Ohio Department of Transportation, District 2  
 317 East Poe Rd.  
 Bowling Green, OH 43601  
 Phone: 419-353-8131

US-224 OVER SANDUSKY RIVER  
 STRUCTURE NO. 7402910 (SEN-224-1207)  
 SOUNDING PLAN  
 SENECA COUNTY, OHIO

CEI PROJECT  
 55-12239.00  
 INSPECTED BY:  
 MOR  
 DRAWN BY:  
 BLV  
 CHECKED BY:  
 JMJ  
 DATE:  
 MAY 2020  
 SHEET NO:  
 2

UPSTREAM FASCIA LOOKING DOWNSTREAM	
Location	Y(ft)*
A1	5.6
1/4	7.9
1/2	12.5
3/4	12.6
P1	12.7
1/4	12.8
1/2	12.9
3/4	13.0
P2	13.1
1/4	13.2
1/2	13.3
3/4	13.4
P3	13.5
1/4	13.6
1/2	13.7
3/4	13.8
P4	13.9
1/4	14.0
1/2	14.1
3/4	8.3
A2	4.5

\*Profile taken from top of deck to channel bottom



LEGEND

- Approximate Channel Bottom - May 2020
- - - Approximate Channel Bottom - June 2015
- - - Approximate Channel Bottom - June 2010 (No Data)
- Timber Debris
- Water Surface
- +450 Elevation (ft)

Note:

Footing elevations unknown due to unavailable design drawings.


**COLLINS ENGINEERS**  
124 Venture Court, Ste 10  
Lexington, KY 40511  
Phone: 859-367-0097  
Fax: 859-367-0140

Ohio Department of Transportation, District 2  
317 East Poe Rd.  
Bowling Green, OH 45601  
Phone: 419-353-8131

US-224 OVER SANDUSKY RIVER  
STRUCTURE NO. 7402910 (SEN-224-1207)  
CROSS SECTIONS - UPSTREAM  
SENECA COUNTY, OHIO

CEI PROJECT  
55-12239.00  
INSPECTED BY:  
MOR  
DRAWN BY:  
BLV  
CHECKED BY:  
JMJ  
DATE:  
MAY 2020  
SHEET NO:  
**3**





CHANNEL CROSS SECTION  
 STRUCTURE CENTERLINE  
 (LOOKING DOWNSTREAM)


LEGEND

- Approximate Channel Bottom - May 2020
- - - Approximate Channel Bottom - June 2015
- - - Approximate Channel Bottom - June 2010 (No Data)
- Timber Debris
- Water Surface
- +450 Elevation (ft)


Note:  
 Footing elevations unknown due to unavailable design drawings.

UPSTREAM FASCIA LOOKING DOWNSTREAM	
Location	Y(ft)*
A1	5.7
1/4	7.8
1/2	12.5
3/4	12.6
P1	12.7
1/4	12.8
1/2	12.9
3/4	13.0
P2	13.1
1/4	13.2
1/2	13.3
3/4	13.4
P3	13.5
1/4	13.6
1/2	13.7
3/4	13.8
P4	13.9
1/4	14.0
1/2	14.1
3/4	9.4
A2	5.9

\*Profile taken from top of deck to channel bottom



CHANNEL CROSS SECTION  
DOWNSTREAM FASCIA  
(LOOKING DOWNSTREAM)



CHANNEL CROSS SECTION  
50 FT DOWNSTREAM  
(LOOKING DOWNSTREAM)

LEGEND

- Approximate Channel Bottom - May 2020
- - - Approximate Channel Bottom - June 2015
- - - Approximate Channel Bottom - June 2010 (No Data)
- Timber Debris
- Water Surface
- +450 Elevation (ft)

Note:


Footing elevations unknown due to unavailable design drawings.

**COLLINS ENGINEERS**  
124 Venture Court, Ste 10  
Lexington, KY 40511  
Phone: 859-367-0097  
Fax: 859-367-0140


Ohio Department of Transportation, District 2  
317 East Poe Rd.  
Bowling Green, OH 45601  
Phone: 419-353-8131

US-224 OVER SANDUSKY RIVER  
STRUCTURE NO. 7402910 (SEN-224-1207)  
CROSS SECTIONS - DOWNSTREAM  
SENECA COUNTY, OHIO


CEI PROJECT  
55-12239.00  
INSPECTED BY:  
MOR  
DRAWN BY:  
BLV  
CHECKED BY:  
JMJ  
DATE:  
MAY 2020  
SHEET NO:  
**5**




WEST ELEVATION  
(LOOKING EAST)



EAST ELEVATION  
(LOOKING WEST)



PLAN



INSPECTION NOTES:

- ① The channel bottom material consisted of timber debris with silt overlay with approximately 6 in. probe rod penetration.
- ② The submerged portions of the pier were sound and smooth with no defects observed.
- ③ A scour depression measuring approximately 10 ft diameter by 2 ft deep was observed on the southwest corner of the pier just downstream of the timber debris.
- ④ Severe timber debris consisting of logs up to 2 ft diameter were observed on the upstream nose extending up to 15 ft radius around the upstream nose from channel bottom to 4 ft above the waterline.

LEGEND

- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom – May 2020
- ⊗ Timber Debris
- ▽ Water Surface
- ⊙ Scour Depression


**COLLINS ENGINEERS**  
 124 Venture Court, Ste 10  
 Lexington, KY 40511  
 Phone: 859-367-0097  
 Fax: 859-367-0140




Ohio Department of Transportation, District 2  
 317 East Poe Rd.  
 Bowling Green, OH 45601  
 Phone: 419-353-8131

US-224 OVER SANDUSKY RIVER  
 STRUCTURE NO. 7402910 (SEN-224-1207)  
 PIER 1  
 SENECA COUNTY, OHIO


CEI PROJECT  
 55-12239.00  
 INSPECTED BY:  
 MOR  
 DRAWN BY:  
 BLV  
 CHECKED BY:  
 JMJ  
 DATE:  
 MAY 2020  
 SHEET NO:  
 6



WEST ELEVATION  
(LOOKING EAST)



EAST ELEVATION  
(LOOKING WEST)



PLAN

INSPECTION NOTES:

- ① The channel bottom material consisted of timber debris with silt overlay with approximately 6 in. probe rod penetration.
- ② The submerged portions of the pier were sound and smooth with no defects observed.
- ③ A scour depression measuring approximately 10 ft diameter by 2 ft deep was observed on the northeast corner of the pier just downstream of the timber debris.
- ④ Heavy timber debris consisting of logs up to 2 ft diameter were observed on the upstream nose extending up to 10 ft radius around the upstream nose and along the north face from channel bottom to 2 ft above the waterline.

LEGEND


- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom - May 2020
- ⌘ Timber Debris
- ▽ Water Surface
- ⊙ Scour Depression

**COLLINS ENGINEERS**  
 124 Venture Court, Ste 10  
 Lexington, KY 40511  
 Phone: 859-367-0097  
 Fax: 859-367-0140


Ohio Department of Transportation, District 2  
 317 East Poe Rd.  
 Bowling Green, OH 43601  
 Phone: 419-353-8131

US-224 OVER SANDUSKY RIVER  
 STRUCTURE NO. 7402910 (SEN-224-1207)  
 PIER 2  
 SENECA COUNTY, OHIO


CEI PROJECT  
 55-12239.00  
 INSPECTED BY:  
 MOR  
 DRAWN BY:  
 BLV  
 CHECKED BY:  
 JMJ  
 DATE:  
 MAY 2020  
 SHEET NO:  
 7



WEST ELEVATION  
(LOOKING EAST)



EAST ELEVATION  
(LOOKING WEST)



PLAN

INSPECTION NOTES:

- ① The channel bottom material consisted of timber debris with silt overlay with approximately 6 in. probe rod penetration.
- ② The submerged portions of the pier were sound and smooth with no defects observed.
- ③ Moderate timber debris consisting of logs up to 1 ft diameter were observed on the upstream nose extending along the north face from channel bottom to 2 ft above the waterline.

LEGEND

- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom – May 2020
- ⌘ Timber Debris
- ▽ Water Surface
- ⊙ Scour Depression


**COLLINS ENGINEERS**  
 124 Venture Court, Ste 10  
 Lexington, KY 40511  
 Phone: 859-367-0097  
 Fax: 859-367-0140

Ohio Department of Transportation, District 2  
 317 East Poe Rd.  
 Bowling Green, OH 43601  
 Phone: 419-353-8131


US-224 OVER SANDUSKY RIVER  
 STRUCTURE NO. 7402910 (SEN-224-1207)  
 PIER 3  
 SENECA COUNTY, OHIO

CEI PROJECT  
 55-12239.00  
 INSPECTED BY:  
 MOR  
 DRAWN BY:  
 BLV  
 CHECKED BY:  
 JMJ  
 DATE:  
 MAY 2020  
 SHEET NO:  
 8






WEST ELEVATION  
(LOOKING EAST)



EAST ELEVATION  
(LOOKING WEST)



PLAN

INSPECTION NOTES:

- ① The channel bottom material consisted of timber debris with silt overlay with approximately 6 in. probe rod penetration.
- ② The submerged portions of the pier were sound and smooth with no defects observed.
- ③ Light timber debris consisting of branches up to 6 in. diameter were observed on the upstream nose extending up to a 5 ft radius from channel bottom to the waterline.

LEGEND

- 2.7 Sounding Depth from Waterline (ft)
- Approximate Channel Bottom - May 2020
- ⌘ Timber Debris
- ▽ Water Surface
- ⊙ Scour Depression

**COLLINS ENGINEERS**  
 124 Venture Court, Ste 10  
 Lexington, KY 40511  
 Phone: 859-367-0097  
 Fax: 859-367-0140

Ohio Department of Transportation, District 2  
 317 East Poe Rd.  
 Bowling Green, OH 45601  
 Phone: 419-353-8131

US-224 OVER SANDUSKY RIVER  
 STRUCTURE NO. 7402910 (SEN-224-1207)  
 PIER 4  
 SENECA COUNTY, OHIO

CEI PROJECT  
 55-12239.00  
 INSPECTED BY:  
 MOR  
 DRAWN BY:  
 BLV  
 CHECKED BY:  
 JMJ  
 DATE:  
 MAY 2020  
 SHEET NO:  
 9

**UNDERWATER INSPECTION**

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)

Seneca County, OH • May 2020

---



**EXHIBIT 2 – INSPECTION PHOTOGRAPHS**

**UNDERWATER INSPECTION**

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)

Seneca County, OH • May 2020



Photograph No. 1: Overall View of Structure No. 7402910 (SEN-224-1207), Looking North.



Photograph No. 2: Overall View of Structure No. 7402910 (SEN-224-1207), Looking South.



**UNDERWATER INSPECTION**

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)

Seneca County, OH • May 2020



Photograph No. 3: View of the West Embankment Upstream of the Structure, Looking Southwest.



Photograph No. 4: View of the West Embankment at the Structure, Looking West.



**UNDERWATER INSPECTION**

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)

Seneca County, OH • May 2020



Photograph No. 5: View of the West Embankment Downstream of the Structure, Looking Northwest.



Photograph No. 6: View of the East Embankment Upstream of the Structure, Looking Southeast.



**UNDERWATER INSPECTION**

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)

Seneca County, OH • May 2020



Photograph No. 7: View of the East Embankment at the Structure, Looking East.



Photograph No. 8: View of the East Embankment Downstream of the Structure, Looking Northeast.



**UNDERWATER INSPECTION**

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)  
Seneca County, OH • May 2020



Photograph No. 9: View of the East Face of Pier 1, Looking Southwest.



Photograph No. 10: View of the West Face of Pier 1, Looking Northeast.



**UNDERWATER INSPECTION**

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)

Seneca County, OH • May 2020



Photograph No. 11: View of the West Face of Pier 2, Looking Southwest.



Photograph No. 12: View of the East Face of Pier 2, Looking Northeast.



**UNDERWATER INSPECTION**

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)  
Seneca County, OH • May 2020



Photograph No. 13: View of the East Face of Pier 3, Looking Southwest.



Photograph No. 14: View of the West Face of Pier 3, Looking Northeast.



**UNDERWATER INSPECTION**

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)

Seneca County, OH • May 2020



Photograph No. 15: View of the East Face of Pier 4, Looking Southwest.



Photograph No. 16: View of the West Face of Pier 4, Looking Northeast.

**UNDERWATER INSPECTION**

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)

Seneca County, OH • May 2020



Photograph No. 17: View of the Typical Concrete Condition at the Waterline, Looking West.



**UNDERWATER INSPECTION**

US-224 over Sandusky River • Structure No. 7402910 (SEN-224-1207)

Seneca County, OH • May 2020

---



**EXHIBIT 3 – UNDERWATER DIVE INSPECTION PROCEDURE  
CHECKLIST**

**Underwater Dive Inspection Procedure Checklist**

Acceptable written procedures communicate to the next dive team what is necessary to ensure a safe and successful inspection. Each bridge requiring underwater dive techniques must have a unique written inspection procedure. The prior inspection report does not suffice for the required procedures. It is valuable to review the last inspection notes, but they do not serve the same purpose as a stand-alone inspection procedure.

This document shall be completed for all underwater dive inspections. This document shall be reviewed prior to performing the field work and it shall be updated when necessary.

**I. Bridge Identification**

a. Agency with Inspection Responsibility:           ODOT DISTRICT 2          

Dive Frequency:           60           months

SFN:   7402910   Bridge Number (County-Route-SLM-SD):   SEN-224-1207  

Superstructure Type Main Span Type:           STEEL BEAM          

Approach Span:           REINFORCED CONCRETE          

Substructure Type Abutment Type:           REINFORCED CONCRETE          

Pier Type:           REINFORCED CONCRETE          

Total Pier Count:                           4                          

Total Pier Count in water:                           4                          

Foundations:                           UNKNOWN                          

Feature Intersected                           SANDUSKY RIVER

**b. Photographs**

Endview



Elevation



Underside

**II. Office and Field Assessment**

Prior to the inspection, obtain and review copies of the previous underwater inspection reports, routine inspection reports, scour and hydraulic information, and design plans in preparation of the inspection.

Divers should pay particular attention given to any observed areas of deterioration, the channel conditions and factors that may accelerate material deterioration. Changes shall be noted in the inspection procedure. Site conditions should be reviewed prior to diving.

a. Channel Conditions

- Waterway features
- Rapid stream flows,
- Significant debris accumulation
- Constricted waterway openings
- Soft or unstable streambeds
- Meandering channels
- Other which may promote scour and undermining of substructure elements
- Navigable Waterway
- Flow Controls

b. Anticipated Water conditions which

may affect the inspection

- Cold Water (Apprx. Temp\_\_\_)
- Black water
- Rapid stream flows
- Near military facility
- Tribal fishing
- Water quality
- History of Log jams

c. Identify factors that may accelerate the deterioration of the bridge elements:

- Highly corrosive water
- Unprotected steel members
- Other

Risk Factor Narrative:

III. Contacts Prior to Work

District 2 Bridge Engineer: David Geckle, P.E.

Email: [david.geckle@dot.ohio.gov](mailto:david.geckle@dot.ohio.gov) – Phone: 419-373-4377

Point of contact for immediate action such as closing the bridge due to findings

Contact Bridge Owner 14 (number) days before the proposed underwater inspection.

Special contracting and scheduling procedures prior to inspection, include recommended lead time

Entity	Contact Name and Title	Contact Phone	Lead Time
Coast Guard			
Property Owner			
Access Equipment			
Lake or River draw-down			
Canal dry time			
Tree removal			
Other:			
Other:			



IV. **Dive Team Shall Include the Following:**

Dive Team Narrative:

The dive team consisted of one Team Leader (NBIS, P.E., ADCI) and two Team Members (NBIS, UW, ADCI)

*Example: The Bridge shall be investigated using a three-member dive team: one supervisor to monitor rack box and take notes, one diver, and one tender/standby diver. There shall be one NBIS Team Leader onsite at all times.*

V. **Site Information**

Navigable waterway:	Y / <u>N</u>	Anticipated current	<u>1</u> ft
If Yes, waterway river point	<u>N/A</u>	Scour Critical (item 113):	<u>8</u>
Anticipated water visibility depth	<u>&lt;1</u> ft	POA in place:	Y/ <u>N</u>
Anticipated Dive depth	<u>8</u> ft	Scour Monitoring devices present:	Y/ <u>N</u>

Verify the Scope of Services when work is contracted for the procedure for underwater elements that are not in water during an inspection.

Site Information Narrative:

The underwater inspection consists of a visual and tactile examination of the accessible surfaces of the substructure items in water. Additional items should reference the scope of services in the contract.

For reference the following items are in water:

Item	Number of Units	Level of Inspection (1, 2 or 3) with Commentary
Piers and Number of Columns	4	100% LEVEL I 10% LEVEL II
Abutment	N/A	
Culvert	N/A	
Scour Countermeasures	N/A	
Fenders or Dolphins	N/A	

Photographs should be taken, if water clarity permits, for typical conditions, conditions that have changed since last inspection and significant or noteworthy deficiencies. The type of channel bottom material, the presence or extent of scour, the presence or extent of riprap, the presence or extent of drift and debris, and the location of any foundation exposure or undermining shall be quantified. Include depth, length, height and location of deficiencies.

VI. Equipment and Field Logistics

a. The inspection should be conducted

using:

Chest waders

Hip waders

Diving equipment

SCUBA (Note that ADCI Consensus Standards require communication systems be employed for both SCUBA and Surface-Supplied (whether air or mixed-gas) dive modes)

SCUBA with communication

Surface Supplied with

communication

b. The channel bottom should be sounded

utilizing

Digital fathometer

Telescoping survey rod

acoustic imaging

c. During the inspection, the divers should

work from

Shore

Boat

Either

The note taker should work alongside the dive team.

d. Access to the waterway should be obtained from the shore (north bank, southwest quadrant, driveway 30 yards north etc.)

WEST SHORELINE (DAYS IN PARKING LOT)

e. The maximum depth of the channel is typically measured \_\_\_\_\_ feet from

\_\_\_\_\_

AT THE UPSTREAM NOSE OF PIER 3

Reference Datum: Top of Cap at the

Downstream Nose of Pier 2

Soundings should be dictated by the scope of work. When not detailed in the scope they should be repeated from the previous soundings. If neither exist then they need to be taken in a grid pattern between substructure units 100' upstream and 100' downstream.

**VII. Inspection Procedure History**

Created: COLLINS ENGINEERS, INC. Date: 9/25/2020

Updated By: \_\_\_\_\_ Date: \_\_\_\_\_

Updated By: \_\_\_\_\_ Date: \_\_\_\_\_

Updated By: \_\_\_\_\_ Date: \_\_\_\_\_

Updated By: \_\_\_\_\_ Date: \_\_\_\_\_

Updated By: \_\_\_\_\_ Date: \_\_\_\_\_

**VIII. Other Narrative Not Included In Previous Sections**