

**GUE-70-0994R
3001385**

**Identification and Inspection
of Fatigue Cracks
in the Built-up Welded Beams**

Re-inspection

**10-4 and 10-6-2011
By: Albert Abel
Bridge Specialist II**

BRIDGE DATA

TYPE: Single Span Composite welded built-up steel beam.
SPAN: 96'-6" c/c bearings
Substructure: Full height concrete abutments on spread footings
Roadway: Varies 80'-5" average f/f rails
Deck: 9.25" concrete
Wearing Surface: .75" monolithic concrete and 1.75" SDC (placed 1990)
Skew: 3deg. 19 min. 19sec. right forward
Alignment: 2 deg curve and spiral
Design Loading: CF-2000(57)
Minimum Vertical Clearance: 16'-3" on I-77NB
Year Built: 1965 Proj. 312(63)

This structure carries east bound I-70 and ramps H and F over north bound I-77 and ramps F and D for a total of 4 lanes of traffic on the bridge and 4 lanes of traffic under. In 1990 new bridge rails, expansion joints, approach slabs and a SDC overlay were placed.

On June 27, 2000 during the annual inspection of the structure what appeared to be cracks were noticed in the webs of beams 4 and 5 near mid span at the top flange welds over the X bracing. The next day a close up inspection using Dye Penetrant was used to confirm the existence of the cracks.

After consultation between D-5 and the Office of Structural Engineering, it was decided that an in-depth inspection of suspected crack locations be performed to locate all existing cracks. After all the cracks are located the ends of the cracks would be drilled to try and stop any further propagation of the cracks. This work was performed by the D-5 Bridge Inspectors starting November 6, 2000 and was completed November 17, 2000. The drilled cracks will be monitored on an annual cycle to determine if the drilling has stopped the cracks from growing. A total of 10 cracks were found in 2000. The cracks varied in length from 1" to 3.25".

In August of 2007 a re-inspection of the cracks was done using dye penetrant to look for growth of the existing cracks and to find any newly formed cracks.

RE-INSPECTION

October 4 and 6, 2011

By: Albert Abel
Matt Beedy(in bucket truck)
Jeff Watson

FOR CRACK LOCATIONS SEE SKETCH BELOW


Legend: B = beam, C = Intermediate crossframe from rear abutment

- B1,C5 1.5" long crack on the right interior face of beam but no crack on the exterior side of the beam, no change.
- B3,C4 The crack grew 1.75" longer rear of drilled hole and is now a total of 2.25"
- B4,C3 1" crack, no change.
- B4,C5 The crack grew 5.5" longer past the drilled holes and is now 8.5" long.
- B4,C6 3.25" long crack, no change.
- B5,C4 Possible crack, no change.
- B5,C5 1.5" crack, no change.
- B5,C6 New 0.5" crack in crossframe weld.
- B5,C7 1" long crack, no change.
- B6,C4 2" long crack, no change.
- B7,C4 1" long crack, no change.
- B7,C7 2.5" long crack, no change.
- B7,C8 1.5" long crack, no change.
- B8,C4 1.75" long crack, no change.
- B9,C4 The crack grew 5.5" longer past drilled holes and in now a total of 7.5" long.
- B9,C5 Crack showing on the interior side of beam only, has grew 2" longer and is now a total of 6" long.
- B9,C6 The crack grew 2" longer and is now a total of 5" long.

ACK LOCATION SKETCH

A. A. A.
 J. J. J.
 M. M. M.


10-64 & 10-65, 2001



1102.01 + 10.01

2 1/2" CRACK NARROW 200'
BUT MUST HAVE FIXED 1500'
NO CRACK 10-6-2011


QVE-70-0994 R 3001385



10-44-10-6, 2011

SON
JERRY

↑ FWD ↑



INTERMEDIATE
CROSSFRAMES

BEAM 2 3 4 5 6 7 8 9
CUE-70-0994 R 3001385

**GUE-70-0994R
3001385**

**Identification and Inspection
of Fatigue Cracks
in the Built-up Welded Beams**

**11-28-2000
By: Albert Abel
Bridge Specialist II**

BRIDGE DATA

TYPE: Single Span Composite welded built-up steel beam.

SPAN: 96'-6" c/c bearings

Substructure: Full height concrete abutments on spread footings

Roadway: Varies 80'-5" average f/f rails

Deck: 9.25" concrete

Wearing Surface: .75" monolithic concrete and 1.75" SDC (placed 1990)

Skew: 3deg. 19 min. 19sec. right forward

Alignment: 2 deg curve and spiral

Design Loading: CF-2000(57)


Minimum Vertical Clearance: 16'-3" on I-77NB

Year Built: 1965 Proj. 312(63)

This structure carries east bound I-70 and ramps H and F over north bound I-77 and ramps F and D for a total of 4 lanes of traffic on the bridge and 4 lanes of traffic under. In 1990 new bridge rails, expansion joints, approach slabs and a SDC overlay were placed.



On June 27, 2000 during the annual inspection of the structure what appeared to be cracks were noticed in the webs of beams 4 and 5 near mid span at the top flange welds over the X bracing. The next day a close up inspection using Dye Penetrant was used to confirm the existence of the cracks.

After consultation between D-5 and the Office of Structural Engineering, it was decided that an *in*-depth inspection of suspected crack locations be performed to locate all existing cracks. After all the cracks are located the ends of the cracks would be drilled to try and stop any further propagation of the cracks. This work was performed by the D-5 Bridge Inspectors starting November 6, 2000 and was completed November 17, 2000. The drilled cracks will be monitored on an annual cycle to determine if the drilling has stopped the cracks from growing. A total of 10 cracks were found. The cracks varied in length from 1" to 3.25".




- #1. 1.5" long crack, .75" hole drilled at ends.
- #2. 3" long crack, .75" hole drilled at ends.
- #3. 3.25" long crack, .75" holes drilled at ends.
- #4. 1.5" long crack, .75" holes drilled at ends.
- #5. 2" long crack, .75" holes drilled at ends.
- #6. 1" long crack, .75" holes drilled at ends.
- #7. 1" long crack detected on right side of the beam, this crack was not drilled..
- #8. 1.75" long crack, .75" holes drilled at ends.
- #9. 2" long crack, .75" holes drilled at ends.
- #10. 2" long crack, this crack was not drilled.

TYPICAL CRACK DETAILS




VIEW A-A





CRACK LOCATION #2



CRACK LOCATION # 2



CRACK LOCATION #2 AFTER DYE PENETRANT TEST

2



11/13/2000

CRACK LOCATION #2 WITH $\frac{3}{4}$ " HOLES DRILLED



CRACK LOCATION #3



CRACK LOCATION #3 AFTER 3/4" HOLES DRILLED



CRACK LOCATION #4

BM X#6



OK

11/13/2000

TYPICAL TEST LOCATION WITH NO CRACK



Ohio Department of Transportation

inter-office communication

TO: File GUE-70-0994R, 3001385


FROM: Albert Abel, Bridge Specialist II

SUBJECT: Crack inspection

DATE: 4-20-06

NOTE TO FILE:

On 4-20-06 a re-inspection of the cracked girders was performed. Dye penetrant was used to see if any further growth of the drilled cracks had occurred. No growth of the cracks was detected.




PAGE

6-2800
3001385
GUE-70-0994R
FWD B16

8-2007
A.A.

GUE-70-0994 R



* - X-FRAME WAS TO CLOSE TO FLANGE TO CHECK - TRY NORTH FACE OF BEAMS NEXT TIME

- #1. 1.5" long crack, .75" hole drilled at ends. NO CHANGE
- #2. 3" long crack, .75" hole drilled at ends. NO CHANGE
- #3. 3.25" long crack, .75" holes drilled at ends. NO CHANGE
- #4. 1.5" long crack, .75" holes drilled at ends. NO CHANGE
- #5. 2" long crack, .75" holes drilled at ends. - POSSIBLE 1 1/2" CRACK PAST FWD HOLE RT SIDE OF WEB (NOT SURE)
- #6. 1" long crack, .75" holes drilled at ends. - 3/8" NEW CRACKS PAST HOLES
- #7. 1" long crack detected on right side of the beam, this crack was not drilled.. NOW 2 1/2" LONG
- #8. 1.75" long crack, .75" holes drilled at ends. NO CHANGE
- #9. 2" long crack, .75" holes drilled at ends. NO CHANGE
- #10. 2" long crack, this crack was not drilled. - NOW 4" LONG

GUE-70-0994R
3001385

**Identification and Inspection
of Fatigue Cracks
in the Built-up Welded Beams**

Re-inspection

8-29-2007
By: Albert Abel
Bridge Specialist II

740-253-0434

NB 77 VIDER LB 70

BRIDGE DATA

TYPE: Single Span Composite welded built-up steel beam.

SPAN: 96'-6" c/c bearings

Substructure: Full height concrete abutments on spread footings

Roadway: Varies 80'-5" average f/f rails

Deck: 9.25" concrete

Wearing Surface: .75" monolithic concrete and 1.75" SDC (placed 1990)

Skew: 3deg. 19 min. 19sec. right forward

Alignment: 2 deg curve and spiral

Design Loading: CF-2000(57)

Minimum Vertical Clearance: 16'-3" on I-77NB

Year Built: 1965 Proj. 312(63)

This structure carries east bound I-70 and ramps H and F over north bound I-77 and ramps F and D for a total of 4 lanes of traffic on the bridge and 4 lanes of traffic under. In 1990 new bridge rails, expansion joints, approach slabs and a SDC overlay were placed.

On June 27, 2000 during the annual inspection of the structure what appeared to be cracks were noticed in the webs of beams 4 and 5 near mid span at the top flange welds over the X bracing. The next day a close up inspection using Dye Penetrant was used to confirm the existence of the cracks.

After consultation between D-5 and the Office of Structural Engineering, it was decided that an in-depth inspection of suspected crack locations be performed to locate all existing cracks. After all the cracks are located the ends of the cracks would be drilled to try and stop any further propagation of the cracks. This work was performed by the D-5 Bridge Inspectors starting November 6, 2000 and was completed November 17, 2000. The drilled cracks will be monitored on an annual cycle to determine if the drilling has stopped the cracks from growing. A total of 10 cracks were found. The cracks varied in length from 1" to 3.25".

RE-INSPECTION

8-14 and 8-23- 2007

A re-inspection of the cracks was done using dye penetrant to look for growth of the existing cracks and to find any newly formed cracks.

Existing crack #5 had a possible .25" crack past the forward drill hole on the right side of the web. The dye indication was very faint and I'm not sure if this is truly cracked.


Existing crack #6 had possible .375" cracks past both forward and rear drill holes. Here again the dye indication was very faint and I'm not sure of the existence of further cracking.

Existing crack #7 has grown from 1" to 2.5" in length.

Existing crack # 10 has grown from 2" to 4" in length.

New cracks that were found:

- A New 2.5" long crack
- B New 1" long crack
- C Possible new crack forming, dye indication was faint.
- D New 1" long crack
- E New 1.5" crack
- F New 3" long crack



EXISTING CRACKS (2000)

- #1. 1.5" long crack, .75" hole drilled at ends. (no change)
- #2. 3" long crack, .75" hole drilled at ends. (no change)
- #3. 3.25" long crack, .75" holes drilled at ends. (no change)
- #4. 1.5" long crack, .75" holes drilled at ends. (no change)
- #5. 2" long crack, .75" holes drilled at ends. (possible .25" crack past forward drill hole on right side of web)
- #6. 1" long crack, .75" holes drilled at ends. (possible .375" cracks past both forward and rear drill holes)
- #7. 1" long crack detected on right side of the beam, this crack was not drilled. (crack has grown to 2.5" in length.)
- #8. 1.75" long crack, .75" holes drilled at ends. (no change)
- #9. 2" long crack, .75" holes drilled at ends. (no change)
- #10. 2" long crack, this crack was not drilled. (crack has grown to 4" in length)

NEW CRACKS (2007)

- A. New 2.5" long crack
- B. New 1" long crack
- C. Possible new crack forming, dye indication was faint.
- D. New 1" long crack
- E. New 1.5" crack
- F. New 3" long crack




B 9 NORTH
INT. # 10

08/14/2007



B9 North #5
INT. #5
EXISTING 2"
NOW 4"

08/14/2007



08/14/2007

B7 SOUTH
8TH INTER

08/14/2007



BT SOUTH
7th INTER
X

08/14/2007



B5 NORTH
7TH INTER

08/14/2007



Ohio Department of Transportation

inter-office communication

TO: File GUE-70-0994R, 3001385

FROM: Albert Abel, Bridge Specialist II

SUBJECT: Crack inspection

DATE: 4-20-06

NOTE TO FILE:

On 4-20-06 a re-inspection of the cracked girders was performed. Dye penetrant was used to see if any further growth of the drilled cracks had occurred. No growth of the cracks was detected.


11/13/2000



3001385


606-70-0994R

11/13/2000



BM4
 $X=6$

6/28/2000




11/13/2000




11/13/2000



11/13/2000




11/13/2000



11/13/2000



11/13/2000



6/28/2000

BM 4
x 5



6/28/2000

$\phi = X$

BMW

6/28/2000

BM 4
+ 5

11/13/2000



↑

FWD

↑

9

8

7

6

5


4

3

2

1

QUE-70-0994 R 3001385



1 2 3 4 5 6 7 8 9
CUE-70-0994R 3001385

TRAFFIC ORDER

TYPE OF ORDER:

ORDER #

MAINTENANCE (Repair or replace sign or signal)

☒ WORK (New sign or signal install, or paint crew)

COUNTY: COS 16 FAL 23 GUE 30 KNO 42 LIC 45 MUS 60 PER 64

WRITTEN BY John Ryan DATE 7/29/13 TIME 1:36 PM

ROUTE CR 347 VILLAGE

DIRECTION: N S E W TOWNSHIP Jackson

SLM OR APPROXIMATE LOCATION Intersection of CR 347 (Oakwood Rd) and IR 4325 (Hope Ave)

PROBLEM: (Use up to 4 sign codes) RESET REPLACE OTHER

Reset sign per attached drawing.

Quantity Sign No. Description

Signs to be Ordered:

UNABLE TO COMPLETE WORK BECAUSE

(A322502350) 8-15-13 2:10 pm Done

Date Work Completed 08-19-13 Crew J.L.


Time Work Completed



OHIO DEPARTMENT OF TRANSPORTATION
DISTRICT 5 CONSTRUCTION

PROJECT NO. _____ INITIALS: _____
REF. NO. _____ ITEM NO. _____
SUBJECT: _____
LOCATION: _____
DATE: _____

CALCULATION SHEET



TRAFFIC ORDER

TYPE OF ORDER:

ORDER #

MAINTENANCE (Repair or replace sign or signal)

☒ WORK (New sign or signal install, or paint crew)

COUNTY: COS 16
 GUE 30
 KMC 42
 LIC 45
 MUS 60
 PER 64

WRITTEN BY John Ryan DATE 7/29/13 TIME 1:17 PM

ROUTE C.R. 35 (Byersville Rd) VILLAGE

DIRECTION: N S E W TOWNSHIP Cambridge

SIM OR APPROXIMATE LOCATION Intersection of U.S. 40 and CR 35

PROBLEM: (Use up to 4 sign codes) ☒ RESET ☐ REPLACE ☐ OTHER

Reset sign per attached drawing.

Quantity Sign No. Description

(Signs to be Ordered:)

UNABLE TO COMPLETE WORK BECAUSE

08-15-13 2:10 pm

A 322502317



Date Work Completed 8-19-13

Crew J.L.


Time Work Completed



OHIO DEPARTMENT OF TRANSPORTATION
DISTRICT 5 CONSTRUCTION

PROJECT NO. _____ INITIALS: _____
REF. NO. _____ ITEM NO. _____
SUBJECT: _____
LOCATION: _____
DATE: _____

CALCULATION SHEET



NO TRUCKS
OVER 10' 11"
HIGH

2.2MI

Your Coffee.
Your Way.
99¢

10/08/2009