

STATE OF OHIO DEPARTMENT OF TRANSPORTATION
BRIDGE INSPECTION REPORT

BR-86 REV 02-95

4	3	0	1	7	1	4
---	---	---	---	---	---	---

Bridge Number **LAK 00002 1656 R** PAINESVILLE
CO ROUTE UNIT

Date Built **07/01/1964**

District **12** Bridge Type **STEEL/BEAM/CONTINUOUS**

Type Service **1 15 GRAND RIVER**

LAK

DECK		Out/Out 36.9	1	THCK = 1.2		2
1. Floor	1-REINF CONCRT (PRESTRSD	8	1	2. Wearing Surface	3-LATEX MODIFIED CONCRET	41
		N-NONE		W.S. Date = 07/01/1989		
3. Curbs, Sidewalks, Walkways	N-NONE	9		4. Median		42
5. Railing	C-32" DEFLECTOR-TYPE PAR	10	1	6. Drainage	3-SCUPPERS & DWNSPTS	43
7. Expansion Joints	2-SLIDING METAL PLATE AN	11	3	8. Summary		44
SUPERSTRUCTURE		MAX.SPAN=100	1			1
9. Alignment		12	1	10. Beams/Girders/Slab	3-WELDED BUILT-UP STEEL	45
11. Diaphragms or Crossframes	TOT.LGTH=265	13	1	12. Joists/Stringers		46
13. Floor Beams		14		14. Floor Beam Connections		47
15. Verticals		15		16. Diagonals		48
17. End Posts		16		18. Top Chord		49
19. Lower Chord		17		20. Lower Lateral Bracing		50
21. Top Lateral Bracing		18		22. Sway Bracing		51
23. Portals		19		24. Bearing Devices	2-ROCKERS N-NONE	52
25. Arch		20		26. Arch Columns or Hangers		53
27. Spandrel Walls		21		28. Protective Coating System	TYPE = 0-OTHER DATE = 01/01/1992	54
29. Pins/Hangers/Hinges		22		30. Fatigue Prone Connections		55
31. Live Load Response		23	S	32. Summary		56
SUBSTRUCTURE		2-CONCRETE	1	PIERS=2 SPANS = 3		1
33. Abutments	2-CONCRETE	24	1	34. Abutment Seats		57
35. Piers	TYPE = 2-CONCRETE	25	1	36. Pier Seats		58
37. Backwalls		26	3	38. Wingwalls	ABUTMENT:=STEEL H / STEEL H	59
39. Fenders and Dolphins		27		40. Scour	5-STABLE: SCOUR WITHIN L	60
41. Slope Protection	3-RIP RAP (ROCK)	28	1	42. Summary		62
				DIVE DT=09/24/2007		
CULVERTS						
43. General		29		44. Alignment		63
45. Shape		30		46. Seams		64
47. Headwalls or Endwalls		31		48. Scour		65
49.		32		50. Summary		66
CHANNEL				5-RIP RAP (DUMPED ROCK OR ROCK)		1
51. Alignment		33	1	52. Protection		67
53. Waterway Adequacy		34	3	54. Summary		68
APPROACHES						
55. Pavement	2-BITUMINOUS	35	1	56. Approach Slabs		69
57. Guardrail	1-STEEL BEAM	36	1	58. Relief Joints		70
59. Embankment	BRDG.WIDTH=30.0	37	1	60. Summary		71
				PCT.LEGAL=150		
GENERAL				ROUTINE.RESP: 1-OHIO TRAN DEPT		
61. Navigation Lights		38		62. Warning Signs	MAINT.RESP: 1-OHIO TRAN DEPT	72
63. Sign Supports	MVC ON=9999 UND=0000	39		64. Utilities		73
65. Vertical Clearance		40	N	66. General Appraisal & Operational Status		74
				COND STAT		6 A

67. INSPECTED BY

68. REVIEWED BY

SIGNED

7	2	3	3	6
---	---	---	---	---

76 PE

M	W	B
---	---	---

78 INITIALS

SIGNED

--	--	--	--	--

81 PE

--	--	--

83 INITIALS

DOT 2852

DECK AREA 9,784

Date

1	1	1	0	1	0
---	---	---	---	---	---

86

91

1	0	0	0	1	N	N	N
---	---	---	---	---	---	---	---

92

69 Survey

99

Date

--	--	--	--	--	--

100

105

STATE OF OHIO DEPARTMENT OF TRANSPORTATION
BRIDGE INSPECTION REPORT

BR-86 REV 02-95

4	3	0	1	7	1	4
---	---	---	---	---	---	---

1 Structure File Number 7

Bridge Number **LAK** **00002** **1656** **R**
 CO ROUTE UNIT

Date Built 07/01/1964

District **12** Bridge Type **STEEL/BEAM/CONTINUOUS**

Type Service **1 15**

GRAND RIVER

Deck FL: TRANSVERSE CRACKS. 30 SF OF DELAMINATIONS. 10 SF OF
 Deck SPALLS (MOSTLY HAUNCH). <1% DETERIORATED.
 Deck WS: CRACKS. A FEW DELAMINATIONS. 1-5% DETERIORATED.
 Deck RAILINGS: VERTICAL CRACKS.
 Deck DRAINAGE: WATER SPRAYS FROM DOWNSPOUTS WHICH ARE 3.5" BELOW
 Deck BOTTOM FLANGES ONTO BEAMS.
 Deck EXJTS: TOP FLANGE OF RIGHT GIRDER IS 1/4" FROM FINISH
 Deck BACKWALL AT 80 DEGREES F.
 Superstructure ALIGNMENT: LOWER FLANGE OF RIGHT FASCIA BEAM IS WARPED
 Superstructure IN SPAN 1.
 Superstructure BEAMS: AREAS OF RUSTING SECTION LOSS (HEAVY AT BEAM ENDS).
 Superstructure XFRAMES: RUSTING SECTION LOSS TO ENDFRAMES.
 Superstructure PCS: GIRDERS ARE RUSTING NEAR LOWER ENDS OF DOWNSPOUTS PCS
 Superstructure FAILING AT BEAM ENDS. 5-10% DETERIORATED.
 Substructure BACKWALLS: DELAMINATIONS. CRACKS MOSTLY NEAR TOPS. SCALING
 Substructure AT FINISH.
 Substructure WINGWALLS: SCALING. A FEW CRACKS AND SPALLS.
 Substructure SCOUR: ENTIRE TOP SURFACE AND AS MUCH AS 24" OF VERTICAL
 Substructure FACE (SOUTHEAST CORNER) OF PIER #2 ARE EXPOSED TO
 Substructure FLOWING STREAM WATER.
 Substructure NOTE: LAST DIVE INSPECTION IN 2007.
 Channel WATERWAY ADEQUACY: LARGE LOGS SNAGGED ON UPSTREAM NOSE OF
 Channel PIER 2. BRANCHES SNAGGED ON UPSTREAM NOSE
 Channel OF PIER 1. BRANCHES SNAGGED IN
 Channel CROSSFRAMES AND CHANNEL DEBRIS WEDGED
 Channel ALONG START ABUTMENT. COLLISION DAMAGE TO
 Channel RIGHT FASCIA BEAM, SEE ALIGNMENT.
 Approaches PAVEMENT: REAR, 3' JOINT HEADER SUNK 3/4" IN PASSING LANE