

Inspector: Miller,Jason
 Inspection Date: 06/21/2023

Structure Number: 1812971
 Facility Carried: SOUTHWOOD DRIVE

Ohio Bridge Inspection Summary Report

CUY-00480-1216 (1812971)

2: District 09246 - BROOKLYN (CUY county)
 District 12

5A: Inventory Route 1 02085

21: Major Maint A/B 01 - State Highway Agency /
 225 Routine Main A/B 04 - City or Municipal Highway /
 Agency
 221 Inspection A/B 01 - State Highway Agency /
 220: Inv. Location DISTRICT 12

7: Facility On SOUTHWOOD DRIVE
 6: Feature Ints IR 480
 9: Location 1.39 MI. W. OF JCT. US-42
 Lat, Lon 41.424299 , -81.751098

Condition

58: Deck **6 - Satisfactory Condition**
 58.01 Wearing Surface 7 - Good (1% distress)
 58.02 Joint 4- Poor (heavy leaking, offset)
59: Superstructure **6 - Satisfactory Condition**
 59.01 Paint & PCS 2 - Critical PCS (30-40% corr.)
60: Substructure **5 - Fair Condition**
61: Channel **N**
61.01 Scour **N - Not Applicable**
62: Culverts **N - Not Applicable**

Structure Type

43: Bridge Type 4 - Steel continuous
 02 - Stringer/Multi-beam or Girder
 N- Not Applicable
 45: Spans Main / Approach 2 / 0
 107: Deck Type 1 - Concrete Cast-in-Place
 408: Composite Deck N - Non-composite Construction
 414A Joint Type 1 3 - Compression Seal
 414B: Joint Type 2 N - None
 108A: Wearing Surface 1 - Monolithic Concrete
 (concurrently placed with structural
 deck)
 N- Not Applicable

67.01 GA **5**

Appraisal

Sufficiency Rating 70.9 SD/FO 0 - ND
 36: Rail, Tr, Gd, Term Std N N 1 0
 72: Approach Alignment 8 - Equal to present desirable criteria
 113: Scour Critical N - Not over waterway
 71: Waterway Adequacy N - Not Applicable

422: WS Date 07/01/1985
 423: WS Thick (in) 1.2
 482: Protective Coating 5 - Paint System OZEU
 483: PCS Date 01/01/1991
 453: Bearing Type 1 4 - Elastomeric (Plain)
 455: Bearing Type 2 N - None
 528: Foundn: Abut Fwd 4 - Spread Footing (on soil)
 533: Foundn: Abut Rear 4 - Spread Footing (on Soil)
 536: Foundn: Pier 1 4 - Spread Footing (on soil)
 539: Foundn: Pier 2 0 - Other

Geometric

48: Max Span Length (ft) 128.0
 49: Structure Length (ft) 261.0
 52: Deck Width, Out-To-Out (ft) 38.3
 424: Deck Area (sf) 9996.3
 32: Appr Roadway Width (ft) 39.0
 51: Road Width, Curb-Curb (ft) 26.0
 50A: Curb/SW Width: Left (ft) 5
 50A: Curb/SW Width: Right (ft) 5
 34: Skew (deg) 21
 33: Bridge Median 0 - No median
 54B: Min Vert Underclearance (ft) 16.12
 336A: Min Vert Clrnce IR Cardinal (ft) 99
 336B: Min V Clr IR Non-Cardinal (ft) 0
 578: Culvert Length (ft) 0

Age and Service

27: Year Built/ 106 Rehab 1985 / 0000
 42A: Service On 1 - Highway
 42B: Service Under 1 - Highway, with or w/out
 pedestrian
 28A: Lanes on 02
 28B: Lanes Under 08
 19: Bypass Length 1
 29: ADT 1000
 109: % Trucks (%) 0

Load Posting

41: Op/Post/Closed A - Open
 70: Posting 5 - Equal to or above legal loads
 70.01: Date
 70.02: Sign Type
 734: Percent Legal (%) 150
 704: Analysis Date 07/01/1986
 63: Analysis Method 6 - Load Factor (LF) rating reported by
 rating factor (RF) method using MS18
 loading.

Inspections

	Months	
90: Routine Insp.	12	06/21/2023
92A: FCM Insp.	N	0
92B: Dive Insp.	N	0
92C: Special Insp.	N	0
92D: UBIT Insp.	N	0
92E: Drone Insp.	N	0

Inspector Miller,Jason

Inspector: Miller,Jason
Inspection Date: 06/21/2023

Structure Number: 1812971
Facility Carried: SOUTHWOOD DRIVE

Inspector: Miller, Jason
 Inspection Date: 06/21/2023

Structure Number: 1812971
 Facility Carried: SOUTHWOOD DRIVE

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
12-Reinforced Concrete Deck	3 - Mod.	9983	sq. ft.	8833	1020	130	0
	CS2- Transverse cracks, some are leaching. Areas of moderate pattern map cracking. CS3- Spalls and delaminated areas. Areas of exposed rebar with section loss.						
805-Wearing Surface - Monolithic Concrete		6786	sq. ft.	5626	1150	10	0
	CS2- Shallow spalls, mainly along expansion joints. A few moderate transverse cracks. Scaling to tie lines throughout. CS3- Spalls along forward expansion joint.						
107-Steel Open Girder/Beam	3 - Mod.	1280	ft.	605	600	75	0
	CS2- Surface rust. CS3- Rusting section loss, worse at beam ends. Sheeting to some lower flanges over traffic.						
515-Steel Protective Coating		16765	sq. ft.	0	10065	4200	2500
	CS2- Surface dulling throughout. CS3- Rust. Peeling & blistering paint. CS4- Paint failing at beam ends & along lower flanges and webs throughout.						
205-Reinforced Concrete Column	3 - Mod.	3	each	0	0	2	1
	CS3- C1 has a spall with 4 rebar exposed with section loss. Wide cracks, delamination, and scaling. C2 has wide cracks, delaminations. CS4- C3 has large spall with at least 11 consecutive rebar exposed with section loss. Wide cracks and delamination surrounding spalled area.						
521-Concrete Protective Coating		340	sq. ft.	340	0	0	0
215-Reinforced Concrete Abutment	3 - Mod.	146	ft.	146	0	0	0
	Repaired at 2023 inspection.						
521-Concrete Protective Coating		464	sq. ft.	464	0	0	0
234-Reinforced Concrete Pier Cap	3 - Mod.	39	ft.	0	15	24	0
	CS2- Moderate width diagonal cracks to both cantilevers. CS3- Wide cracks and delaminations to all bays.						
521-Concrete Protective Coating		636	sq. ft.	636	0	0	0
302-Compression Joint Seal	3 - Mod.	72	ft.	0	0	0	72
	CS2- Gouges to armor. Surface rust to armor. Shallow header spalls. CS3- Deep header spalls. Section loss to armor at left corner of forward joint. Torn seal at left corner of forward joint. CS4- Asphalt patches to headers. Both joints fully closed, no movement.						
310-Elastomeric Bearing	3 - Mod.	10	each	0	10	0	0
	CS2- Corner of forward bearing #1 exposed. Transverse & longitudinal movement to elastomeric pads: as much as 2" to forward bearings 1 & 2 and 1.5" to rear bearing 1. A few pads peeling up at abutment seats. Bulging to a few pad sections.						
313-Fixed Bearing	3 - Mod.	5	each	5	0	0	0

Inspector: Miller,Jason
 Inspection Date: 06/21/2023

Structure Number: 1812971
 Facility Carried: SOUTHWOOD DRIVE

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
321-Reinforced Concrete Approach Slab	3 - Mod.	1300	sq. ft.	1040	208	0	52
	CS2- Sound patchwork, mainly to forward slab. Some moderate width cracks to original slab and patchwork. Some spots of scaling. CS4- Deep spalling along expansion joints for width of roadway, 3"-6" wide and 4"-5" deep along both slabs near both joint headers, asphalt patches in these areas.						
331-Reinforced Concrete Bridge Railing	3 - Mod.	512	ft.	427	85	0	0
	CS2- Moderate width cracks, mainly under fence post anchors. About 5sf of sound patchwork.						
521-Concrete Protective Coating		3072	sq. ft.	3072	0	0	0
	Rail has rust staining from fence hardware. Severed lower fence posts at rear-left and forward-right.						
815-Drainage	3 - Mod.	2	each	2	0	0	0
830-Abutment Backwall	3 - Mod.	52	ft.	52	0	0	0
	Patched at 2023 inspection.						
521-Concrete Protective Coating		208	sq. ft.	208	0	0	0

Inspector: Miller,Jason

Structure Number: 1812971

Inspection Date: 06/21/2023

Facility Carried: SOUTHWOOD DRIVE

ODOT District: District 12

CUY-00480-1216_(1812971)

Date Built: 07/01/1985

Major Maint: 01 - State Highway Agency

Facility Carried: SOUTHWOOD DRIVE

Traffic On: 1 - Highway

Rehab Date:

Routine Maint: 04 - City or Municipal Highway Agency

Feature Inters: IR 480

Traffic Under: 1 - Highway, with or w/out pedestrian

Insp. Resp A: 01 - State Highway Agency

FIPS Code: 09246 - BROOKLYN (CUY county)

Location: DISTRICT 12

1.39 MI. W. OF JCT. US-42

Insp Resp B:

Inspector

Miller,Jason

Inspection Date 06/21/2023

Reviewer Seif,Youssef

Inspector Comments - Deck and Approach

Deck

Floor/Slab

Spalls over traffic:

480 EB: Highspeed Berm and Lane 1, Bay 1. Lanes 3 and 4, Bay 2. Highspeed berm, Bay 4.

480 WB: Highspeed Berm, Bay 1. Lane 4, Bays 3 and 4. Lowspeed Berm, Bays 2,3, and 4.

Curbs/Sidewalk

A few transverse cracks. Small spall to left curb . Shallow spalls to sidewalks at joints.

Approach

Approach Wearing Surface

Approach pavement new at Rear in 2023.

Approach Embankment

Bridge has moved west at forward and east & down at rear as compared to approach parapets and sidewalk curbs (no recent movement).

Approach Guardrail

Only concrete approach rails. Rust severed horizontal fence railing at forward right.

Signs

No bridge end markers.

Sign Supports

3 sign clips missing over WB lane #4. Sign still secure.

Inspector Comments - General Appraisal

Superstructure

Diaphragm/X-Frames

Rear horizontal endframe in Bay 4 is nearly rust severed. Through hole to Forward Bay 1 endframe. Forward Bay 4 endframe is rust severed. Rear bay 1 horizontal end frame has section loss and through hole.

Utilities

Inspector: Miller,Jason

Structure Number: 1812971

Inspection Date: 06/21/2023

Facility Carried: SOUTHWOOD DRIVE

A few broken xframe brackets in bay 4.

Substructure

Culvert

Inspector Comments - Waterway

Waterway Adequacy

Channel

Scour Critical