

Ohio Bridge Inspection Summary Report

CUY-00480-17.080 (1810005)

2: District 12 09274 - BROOKLYN HEIGHTS (CUY county)
 21: Major Maint A/B 01 - State Highway Agency /
 225 Routine Main A/B 01 - State Highway Agency /
 221 Inspection A/B 01 - State Highway Agency /
 220: Inv. Location DISTRICT 12

5A: Inventory Route 1 00480
 7: Facility On IR 480
 6: Feature Ints Creek
 9: Location .29 mi E of Lancaster

Condition

58: Deck **N - Not Applicable**
 58.01 Wearing Surface N - Not Applicable
 58.02 Joint N- Not Applicable
59: Superstructure **N - Not Applicable**
 59.01 Paint & PCS N - Not Applicable
60: Substructure **N - Not Applicable**
61: Channel **6**
61.01 Scour **7 - Good**
62: Culverts **5 - Moderate to major deterioration**
67.01 GA **5**

Structure Type

43: Bridge Type 3 - Steel
 19 - Culvert (includes frame culverts)
 N- Not Applicable
 45: Spans Main / Approach 1 / 0
 107: Deck Type N - Not Applicable
 408: Composite Deck
 414A Joint Type 1 N - None
 414B: Joint Type 2 3 - Compression Seal
 108A: Wearing Surface N - NA
 N- Not Applicable

Appraisal

Sufficiency Rating 59.0 SD/FO 0 - ND
 36: Rail, Tr, Gd, Term Std N N 1 N
 72: Approach Alignment 8 - Equal to present desirable criteria
 113: Scour Critical 6 - Not yet evaluated for scour
 71: Waterway Adequacy 9 - Bridge Above Flood Water Elevations

422: WS Date
 423: WS Thick (in) 0
 482: Protective Coating N - None or Not Applicable
 483: PCS Date
 453: Bearing Type 1 N - None
 455: Bearing Type 2 N - None
 528: Foundn: Abut Fwd N - None (Such as most Culverts)
 533: Foundn: Abut Rear N - None (such as most Culverts)
 536: Foundn: Pier 1 N - None (Such as most Culverts)
 539: Foundn: Pier 2 N - None (Such as most Culverts)

Geometric

48: Max Span Length (ft) 11.3
 49: Structure Length (ft) 11.3
 52: Deck Width, Out-To-Out (ft) 0.0
 424: Deck Area (sf) 2994.5
 32: Appr Roadway Width (ft) 265.0
 51: Road Width, Curb-Curb (ft) 0.0
 50A: Curb/SW Width: Left (ft) 0
 50A: Curb/SW Width: Right (ft) 0
 34: Skew (deg) 46
 33: Bridge Median 1 - Open median
 54B: Min Vert Underclearance (ft) 0
 336A: Min Vert Clrnce IR Cardinal (ft) 99
 336B: Min V Clr IR Non-Cardinal (ft) 0
 578: Culvert Length (ft) 522

Age and Service

27: Year Built/ 106 Rehab 1977 / 0000
 42A: Service On 1 - Highway
 42B: Service Under 5 - Waterway
 28A: Lanes on 10
 28B: Lanes Under 00
 19: Bypass Length 6
 29: ADT 146531
 109: % Trucks (%) 5

Load Posting

41: Op/Post/Closed A - Open
 70: Posting 5 - Equal to or above legal loads
 70.01: Date
 70.02: Sign Type
 734: Percent Legal (%) 150
 704: Analysis Date
 63: Analysis Method 5 - No rating analysis or evaluation performed

Inspections

90: Routine Insp. *Months* 12 07/28/2021
 92A: FCM Insp. N
 92B: Dive Insp.
 92C: Special Insp.
 92D: UBIT Insp.
 92E: Drone Insp.
 Inspector Gerstenslager,Michael

Inspector: Michael Gerstenslager

Structure Number: 1810005

Inspection Date: 07/28/2021

Facility Carried: IR 480

Bridge Inspection Report

Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
240 - Steel Culvert	3 - Mod.	522	ft.	0	451	16	55
	<p>Areas of rusting through holes as large as 1.5' to invert throughout (CS 4). 16" rusting through hole at 5:00 at outlet (CS 4). Four rusting through holes as large as 4" at 5:00 seam 350' from outlet (CS 4). Pin hole size rusting through holes scattered throughout that leak water and have rust colored efflorescence (CS 4).</p> <p>9.5' section of tears as long as 3.5" along 9:00 seam approximately 75' from inlet (CS 3). Damage / tear at 12:00, 100' from outlet (CS 3). 6' section of panel 350' from outlet has missing and cocked fasteners (CS 3).</p> <p>Rusting section loss along invert throughout, heavier at inlet (CS 2). A few missing fasteners throughout (CS 2). Areas of leaking water with efflorescence at some seams (CS 2).</p>						
835 - Culvert End Treatment	3 - Mod.	1	each	0	1	0	0
	<p>Left half of outlet headwall is crumbling and tips away from culvert pipe (CS 2). Right half has large area of concrete deterioration (CS 2).</p>						
845 - Roadway Over Structure	3 - Mod.	2	each	0	2	0	0
	<p>Cracks (CS 2).</p>						

ODOT District: 12

CUY-00480-17.080_(1810005)

Date Built: 07/01/1977

Major Maint: 01 - State Highway Agency

Facility Carried: IR 480

Traffic On: 1 - Highway

Rehab Date:

Routine Maint: 01 - State Highway Agency

Feature Inters: Creek

Traffic Under: 5 - Waterway

Insp: 01 - State Highway Agency

FIPS Code: 09274 - BROOKLYN HEIGHTS (CUY county)

Location: DISTRICT 12

.29 mi E of Lancaster

Resp A:

Insp

Resp B:

Inspector

Gerstenslager, Michael

Inspection Date 07/28/2021

Reviewer Seif, Youssef

Inspector Comments - Deck and Approach

Deck

Approach

Approach Wearing Surface (EA)

Cracks.

Inspector Comments - General Appraisal

Superstructure

Substructure

Culvert

Culvert Shape

Slight elliptical shape at outlet.

Culvert Scour (EA)

Undermining of outlet channel protection.

Inspector Comments - Waterway

Waterway Adequacy

Channel

Channel Protection

Outlet channel protection is thru cracked as wide as 1.5" in two locations (concrete is in three pieces but still in place).

Channel Hydraulic Opening

Minor debris blocks <1%

Scour Critical