

Inspector: Persanyi, Andrea
Inspection Date: 10/24/2022

Structure Number: 2800608
Facility Carried: SR 86

Bridge Inspection Report

loading.

Inspector: Persanyi,Andrea
Inspection Date: 10/24/2022

Structure Number: 2800608
Facility Carried: SR 86

Bridge Inspection Report

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
38-Reinforced Concrete Slab	3 - Mod.	490	sq. ft.	345	60	85	0
CS2- Cracks, some leaching. CS3- Leached cracks with stalactites. Delams & large spalls with rusting rebar exposed, some extending underneath WB edge line.							
510-Wearing Surfaces		302	sq. ft.	0	262	40	0
CS2- Asphalt wearing surface older than 5 years. Several longitudinal cracks. Other minor cracks. CS3- Two full width cracks (up to 3/4") in asphalt near bridge limits.							
215-Reinforced Concrete Abutment	3 - Mod.	62	ft.	47	15	0	0
CS2- A few leached cracks. Efflorescence. Minor delams. Scaling at waterline.							
330-Metal Bridge Railing	3 - Mod.	32	ft.	0	19	10	3
CS2- Surface rust to entire length of both rails. CS3- Rusting section loss to rail and hardware. CS4- A few rusted thru holes to some rail hardware.							
815-Drainage	3 - Mod.	2	each	2	0	0	0
840-Approach Slab: Termination or Joint	3 - Mod.	58	ft.	0	58	0	0
CS2- Two full width cracks (as wide as 1/2") in asphalt near bridge limits.							

Inspector: Persanyi,Andrea
Inspection Date: 10/24/2022

Structure Number: 2800608
Facility Carried: SR 86

Bridge Inspection Report

ODOT District: District 12

GEA-00086-0787 (2800608)

Date Built: 07/01/1930

Major Maint: 01 - State Highway Agency

Facility Carried: SR 86

Traffic On: 1 - Highway

Rehab Date:

Routine Maint: 01 - State Highway Agency

Feature Inters: PHELPS CRK 2.5 MI E. 528

Traffic Under: 5 - Waterway

Insp. 01 - State Highway Agency

FIPS Code: 36946 - HUNTSBURG TWP (GEA county)

Location: DISTRICT 12

0.73 S ASHTABULA CNTY LNE

Resp A:

Insp

Resp B:

Inspector

Persanyi,Andrea

Inspection Date 10/24/2022

Reviewer Seif,Youssef

Inspector Comments - Deck and Approach

Deck

Approach

Approach Wearing Surface

A few cracks, some as wide as 3/4".

Approach Embankment

Erosion at forward-left & both right wingwalls (see guardrail comments).

Approach Guardrail

Erosion has exposed as much as 12" of the concrete encasement of forward-left guardrail post #2.

Signs

Bridge marker at forward left missing.

Inspector Comments - General Appraisal

Superstructure

-

Substructure

Wingwalls

Small spalls.

Culvert

Inspector Comments - Waterway

Waterway Adequacy

Inspector: Persanyi, Andrea
Inspection Date: 10/24/2022

Structure Number: 2800608
Facility Carried: SR 86

Bridge Inspection Report

Channel

Scour Critical

Inspector: Andrea Persanyi
Inspection Date: 10/24/2022

Structure Number: 2800608
Facility Carried: SR 86

Bridge Inspection Report

Pictures