

Inspector: Miller,Jason

Inspection Date: 10/23/2023

Structure Number: 4305345

Facility Carried: WHITE RD

### Ohio Bridge Inspection Summary Report

### LAK-00271-0001 (4305345)

2: District 85512 - WILLOUGHBY HILLS (LAK county)  
ict  
12

5A: Inventory Route 1 00539

21: Major Maint A/B 01 - State Highway Agency /

7: Facility On WHITE RD

225 Routine Main A/B 04 - City or Municipal Highway Agency /

6: Feature Ints IR-271&271X (LAK-271-.01

221 Inspection A/B 01 - State Highway Agency /

9: Location .1 MI N CUY CNTY ON I-271

220: Inv. Location DISTRICT 12

Lat, Lon 41.570429746795256 ,-81.44794840269535

#### Condition

**58: Deck** **5 - Fair Condition**  
 58.01 Wearing Surface 6 - Satisfactory (1-10% distress)  
 58.02 Joint 6- Satisfactory (isolated leaking)

**59: Superstructure** **6 - Satisfactory Condition**  
 59.01 Paint & PCS 4 - Poor PCS (15-20% corr.)

**60: Substructure** **5 - Fair Condition**

**61: Channel** **N**  
**61.01 Scour** **N - Not Applicable**

**62: Culverts** **N - Not Applicable**

**67.01 GA** **5**

#### Structure Type

43: Bridge Type 4 - Steel continuous  
 02 - Stringer/Multi-beam or Girder  
 N- Not Applicable

45: Spans Main / Approach 6 / 0

107: Deck Type 1 - Concrete Cast-in-Place

408: Composite Deck N - Non-composite Construction

414A Joint Type 1 8 - Elastomeric Strip Seal

414B: Joint Type 2 N - None

108A: Wearing Surface 3 - Latex Concrete or similar additive  
 N- Not Applicable

#### Appraisal

Sufficiency Rating 67.0 SD/FO 2 - FO

36: Rail, Tr, Gd, Term Std 1 1 1 1

72: Approach Alignment 8 - Equal to present desirable criteria

113: Scour Critical N - Not over waterway

71: Waterway Adequacy N - Not Applicable

422: WS Date 01/01/1977

423: WS Thick (in) 1.125

482: Protective Coating 7 - Metalized (Alum/Zinc)

483: PCS Date 01/01/1988

453: Bearing Type 1 2 - Rockers & Bolsters

455: Bearing Type 2 N - None

528: Foundn: Abut Fwd 1 - Steel H Piles (Other size)

533: Foundn: Abut Rear 1 - Steel H Piles (Other Size)

536: Foundn: Pier 1 4 - Spread Footing (on soil)

539: Foundn: Pier 2 0 - Other

#### Geometric

48: Max Span Length (ft) 74.0

49: Structure Length (ft) 402.0

52: Deck Width, Out-To-Out (ft) 30.8

424: Deck Area (sf) 12381.6

32: Appr Roadway Width (ft) 34.0

51: Road Width, Curb-Curb (ft) 24.0

50A: Curb/SW Width: Left (ft) 2.2

50A: Curb/SW Width: Right (ft) 2.2

34: Skew (deg) 16

33: Bridge Median 0 - No median

54B: Min Vert Underclearance (ft) 15.84

336A: Min Vert Clrnce IR Cardinal (ft) 99

336B: Min V Clr IR Non-Cardinal (ft) 0

578: Culvert Length (ft) 0

#### Age and Service

27: Year Built/ 106 Rehab 1963 / 0000

42A: Service On 5 - Highway-pedestrian

42B: Service Under 1 - Highway, with or w/out pedestrian

28A: Lanes on 02

28B: Lanes Under 06

19: Bypass Length 0

29: ADT 4185

109: % Trucks (%) 5

#### Load Posting

41: Op/Post/Closed A - Open

70: Posting 5 - Equal to or above legal loads

70.01: Date

70.02: Sign Type

734: Percent Legal (%) 150

704: Analysis Date 07/01/1973

63: Analysis Method 6 - Load Factor (LF) rating reported by rating factor (RF) method using MS18 loading.

#### Inspections

	Months	
90: Routine Insp.	12	10/23/2023
92A: FCM Insp.	N	0
92B: Dive Insp.	N	0
92C: Special Insp.	N	0
92D: UBIT Insp.	N	0
92E: Drone Insp.	N	0

Inspector Miller,Jason

Inspector: Miller,Jason  
 Inspection Date: 10/23/2023

Structure Number: 4305345  
 Facility Carried: WHITE RD

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
<b>12-Reinforced Concrete Deck</b>	3 - Mod.	12362	sq. ft.	9762	2000	450	150
<p>Timber sub-decked over traffic.</p> <p>CS2- Leaching cracks. Epoxy injected areas. Lightly mottled areas.</p> <p>CS3- Large heavily mottled areas. Many delams and spalls (based on what is visible).</p> <p>CS4- Spalls with 4+ exposed rebar.</p>							
510-Wearing Surfaces		9648	sq. ft.	6748	2500	400	0
<p>CS2- Many transverse cracks, spaced ~4'. Shallow spall in EB lane at rear expansion joint.</p> <p>CS3 - Some wide transverse cracks.</p>							
<b>107-Steel Open Girder/Beam</b>	3 - Mod.	1592	ft.	562	950	80	0
<p>CS2 - Surface rust, mainly at lower flanges.</p> <p>CS3- Areas of section loss to fascia beams, mainly at lower flange, web connections, and abutments.</p>							
515-Steel Protective Coating		13944	sq. ft.	0	7944	4000	2000
<p>CS 2 - Chalking, faded.</p> <p>CS 3 - Rust.</p> <p>CS 4 - Peeling paint, rusting.</p> <p>Note: beam ends painted 9/05 (OZEU) are re-rusting.</p>							
<b>205-Reinforced Concrete Column</b>	3 - Mod.	15	each	5	3	6	1
<p>2 of 15 columns fiber wrapped.</p> <p>CS2- P1C2- Delminating fiber wrap. P4C1, P5C1- Cracking and delams.</p> <p>CS3- P3C1- 3, P4C2, and P5C2- Wide cracks and delams. P5C3, Failing fiber wrap with spall through fiber wrap.</p> <p>CS4- P2C2, Large spall with 4+ rebar exposed.</p>							
521-Concrete Protective Coating		1695	sq. ft.	1695	0	0	0
<b>215-Reinforced Concrete Abutment</b>	3 - Mod.	56	ft.	44	10	2	0
<p>CS2- Cracks, some leached</p> <p>CS3- Concrete deterioration and spalls below some weep holes.</p>							
521-Concrete Protective Coating		168	sq. ft.	168	0	0	0
<b>234-Reinforced Concrete Pier Cap</b>	3 - Mod.	125	ft.	123	2	0	0
<p>CS2- A few cracks.</p>							
521-Concrete Protective Coating		1125	sq. ft.	1125	0	0	0
<b>300-Strip Seal Expansion Joint</b>	3 - Mod.	56	ft.	0	46	10	0
<p>CS2- Dirt &amp; debris in joints. Cracks to headers.</p> <p>CS3- Tears in both seals. Spalls and wide cracks to rear header.</p>							

Inspector: Miller, Jason  
 Inspection Date: 10/23/2023

Structure Number: 4305345  
 Facility Carried: WHITE RD

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
<b>311-Movable Bearing</b>	3 - Mod.	24	each	4	16	4	0
CS2- Surface rusting. CS3- Rear rocker 1 & forward rocker 4 engulfed in dirt & debris. Pack rust to some bearings.							
<b>313-Fixed Bearing</b>	3 - Mod.	4	each	0	4	0	0
CS2- Surface rusting.							
<b>321-Reinforced Concrete Approach Slab</b>	3 - Mod.	1400	sq. ft.	760	400	240	0
Both paved over with asphalt. CS2- Cracking. Asphalt patches. CS3- Wide cracking and breakup to asphalt throughout slabs.							
<b>330-Metal Bridge Railing</b>	3 - Mod.	796	ft.	786	0	10	0
CS3- One aluminum post bracket cracked to left rail over grass area between NB mainline & express lanes. A few locations of anchor bolts missing from base plates.							
<b>331-Reinforced Concrete Bridge Railing</b>	3 - Mod.	796	ft.	521	180	95	0
CS2- Cracks, some leaching. CS3- Many spalls, some with exposed rebar, to inside & outside of rails. Wide cracks and delams to inside & outside of rails. Areas of deteriorated concrete.							
<b>521-Concrete Protective Coating</b>		3980	sq. ft.	3830	0	0	150
CS4- Not effective.							
<b>815-Drainage</b>	3 - Mod.	8	each	4	4	0	0
CS2- Partially plugged scuppers. Several downspouts have rusted thru holes just above lower flanges. Broken welds to 1st two downspout supports from rear abutment & the last downspout support near forward abutment on left fascia.							
<b>830-Abutment Backwall</b>	3 - Mod.	56	ft.	27	10	15	4
CS2- Cracks. CS3- Delams. A few other spalls CS4- Large spalls with exposed cheese plate & rebar in bays 1 & 3 at both abutments.							

**Inspector:** Miller,Jason

**Structure Number:** 4305345

**Inspection Date:** 10/23/2023

**Facility Carried:** WHITE RD

ODOT District: District 12

**LAK-00271-0001\_(4305345)**

Date Built: 07/01/1963

Major Maint: 01 - State Highway Agency

Facility Carried: WHITE RD

Traffic On: 5 - Highway-pedestrian

Rehab Date:

Routine Maint: 04 - City or Municipal Highway Agency

Feature Inters: IR-271&271X (LAK-271-.01

Traffic Under: 1 - Highway, with or w/out pedestrian

Insp. Resp A: 01 - State Highway Agency

FIPS Code: 85512 - WILLOUGHBY HILLS (LAK county)

Location: DISTRICT 12

.1 MI N CUY CNTY ON I-271

Insp Resp B:

Inspector

Miller,Jason

Inspection Date 10/23/2023

Reviewer Seif,Youssef

## **Inspector Comments - Deck and Approach**

### **Deck**

#### **Curbs/Sidewalk**

Cracks, a few large delams. Spall to rear-right corner & to left curb between rear scuppers 1 & 2. Large area of concrete deterioration at forward-right.

### **Approach**

#### **Approach Wearing Surface**

Cracks. Areas of asphalt breaking up. Asphalt patches.

#### **Approach Slab**

Shallow void to forward-right slab along curb as deep as 8" x 48" long.

#### **Approach Embankment**

Minor erosion between rear-right guardrail posts 2 & 3.

#### **Approach Guardrail**

Post rot. Collision damage to rear-left. Partial exposure of concrete encasement of rear-right post 2. A few spacers missing at forward.

#### **Signs**

No bridge end markers.

## **Inspector Comments - General Appraisal**

### **Superstructure**

#### **Diaphragm/X-Frames**

Endframe rusting section loss. Rusted thru holes to forward endframe 1. Horizontal angle of first x-frame from rear abutment in bay 2 is bent up 2".

#### **Fatigue**

Welded cover plates at piers.

### **Substructure**

**Inspector:** Miller,Jason

**Structure Number:** 4305345

**Inspection Date:** 10/23/2023

**Facility Carried:** WHITE RD

**Slope Protection**

As much as 4" of forward abutment footing exposed.

**Culvert**

**Inspector Comments - Waterway**

**Waterway Adequacy**

**Channel**

**Scour Critical**

**Inspector:** Jason Miller

**Structure Number:** 4305345

**Inspection Date:** 10/23/2023

**Facility Carried:** WHITE RD

**Bridge Inspection Report**

**Pictures**