

CUY-90-14.90

PID 77332/85531


# **APPENDIX TC-09**

# **B&N Local Route Study** (Reference Document)

State of Ohio
Department of Transportation
Jolene M. Molitoris, Director

Innerbelt Bridge
Construction Contract Group 1 (CCG1)

Revision Date: November 10, 2009



CUY-90-15.24 PID No. 83680

# LOCAL ALTERNATE ROUTES STUDY





## Introduction

The Department requested that several local routes be investigated as part of the maintenance of traffic for the two-phase construction of the Central Viaduct Bridge. These were:

West 25<sup>th</sup> Street (US42) from I-90 to Lorain Avenue (SR10) Lorain Avenue (SR 10) from West 25<sup>th</sup> Street (US42) to Ontario Street (SR14) Broadway Avenue (SR14) from I-77 to Carnegie Avenue (SR10) West Boulevard from I-90 to SR2

Subsequently the following routes were added to the investigation:

Carnegie Avenue between Ontario Street and East 30th Street East 9th Street between Broadway Avenue and Carnegie Avenue East 14th Street between Broadway Avenue and Carnegie Avenue East 22nd Street between Orange Avenue and Carnegie Avenue East 30th Street between Broadway Avenue and Woodland Avenue Woodland Avenue between East 30th Street and East 22nd Street Orange Avenue between East 9th Street and E 30th Street.

The investigation included the preparation of base mapping for the routes showing lane and turning movement information, a field inventory of the routes for pavement and traffic signal conditions as well as items such as bus stops or parking restrictions that might impact the anticipated increase in traffic. Modeling of the traffic and the determination of available capacity along the routes was not part of the assignment.

To facilitate the investigation, a field review was held with representatives from the City of Cleveland and the Department on August 27<sup>th</sup> to review the routes and the traffic control facilities that are currently in place. Input was obtained regarding existing peak traffic conditions, the impacts from anticipated additional traffic detouring from I-90 and potential improvements that might be implemented.

This report has been organized to review and discuss the information obtained during the field review and subsequent field inventory for each of the routes. Base mapping with inventory information and recommendation call outs follow the narrative section. A series of photographs are also included to facilitate the reader's understanding of the routes. The narrative concludes with global recommendations and construction cost information.



## West 25<sup>th</sup> Street (US42) from I-90 to Lorain Avenue (SR10) and Lorain Avenue (SR 10) from West 25<sup>th</sup> Street (US42) to Ontario Street (SR14) (see Sheets 3-7 of 27)

West 25<sup>th</sup> Street (US 42) is classified as a 4-lane urban minor arterial. It services the area of Ohio City and also servers as an alternate route into downtown Cleveland. Lorain (SR 10) is classified as an urban minor arterial and for the most part is four lanes. Lorain serves as a connection between downtown and Ohio City as well as an alternative route to downtown. In general the pavement condition was good in this corridor with minimal cracking. The traffic signals on this corridor are in fair to poor condition. The recommendations of improvements for this road to be used as a local detour route for the Central Viaduct bridge reconstruction project are as follows:

#### Corridor Recommendations

The corridor from I-90 to Lorain Avenue will need to be in a traffic responsive coordinated traffic signal system to maximize the capacity. To accomplish this, each signal will need to be upgraded to insure that proper detection is provided and all signal equipment is compatible. For estimating purposes it is assumed that each signal in the corridor will be replaced and interconnected with aerial standard twisted pair interconnect cable.

## **Local Improvements**

I-90 Eastbound Exit Ramp at West 25<sup>th</sup>

Change ramp lane usage at intersection to dual lefts with a thru-right lane

West 25<sup>th</sup> at I-90 Westbound On-Ramp

Replace damaged guardrail in southwest quadrant of intersection

West 25<sup>th</sup> at Barber

Prohibit West 25<sup>th</sup> northbound left turns from 7 – 9 am

Prohibit West 25<sup>th</sup> southbound left turns from 3 – 6 pm

West 25<sup>th</sup> at Potter Court

Replace damaged catch basin

Eliminate traffic signal and convert Potter Court to one-way eastbound. There is limited traffic using Potter Court and it appears the only reason for the traffic signal is the sight distance restriction (building) in the northeast quadrant. If the traffic signal can not be removed then a new signal must be constructed. For estimating purposes it is assumed the signal will be replaced.

West 25<sup>th</sup> at Columbus

Resurface pavement within the intersection

## West 25<sup>th</sup> at Monroe

Prohibit West 25<sup>th</sup> Street northbound left turns from 7 – 9 am

## West 25<sup>th</sup> at Gehring

It is anticipated that detouring traffic will use Gehring as a short cut to Lorain.

Increase northbound right turn radius to accommodate a free flow right turn. This essentially removes that the traffic calming currently installed at the intersection which will need to be removed once the detour is no longer needed.

Convert southbound Gehring to dual left-turn lanes with a thru-right lane. To accomplish this and to improve the overall operation at the intersection, Chatham Avenue will need to be restricted to one-way westbound.

#### Gehring at Abby

Operate the traffic signal in flash mode until the detour is no longer needed.

## Gehring at Lorain

Prohibit northbound left turns from Gehring and change the lane usage northbound to a right-turn lane and thruright lane.

## Lorain at Commercial and Ontario, Carnegie, and Broadway

Resurface the intersection area from the Ontario spur to Carnegie since as the pavement condition is poor with heavy cracking.

Resurface the Ontario Spur at the intersection of Lorain as the pavement condition is poor with rutting and cracking.

Resurface the Ontario southbound both north and south of the intersection as the pavement condition is poor with heavy rutting and cracking.

Reconstruct the traffic signals at Lorain and Commercial

Reconstruct the traffic signal on Lorain/Carnegie at Ontario/Broadway

Both traffic signals should be equipped with emergency vehicle preemption for emergence vehicles at the Commercial Road fire station. With the additional traffic at the intersection, the intersections will likely become more congested and limit the ability of the emergency vehicles to proceed through these intersections. The preemption should be designed such that the only movements that receive the right-of-way are northbound Commercial and eastbound Lorain. This would allow the intersection to clear-out, enabling better access for the emergency vehicles.

Commercial Road fire station trucks will need to be equipped with preemption emitters.

Video detection would be the preferred detection method at these intersections.

## Items for Further Study

The intersection of Lorain and Gehring should be further analyzed to determine if one of the westbound Lorain lanes could be converted to a left-turn lane, thus creating dual left-turn lanes onto Gehring. This determination would be verified based on capacity analysis.



## **Broadway Avenue from I-77 to Carnegie Avenue**

(see Sheets 8-12 of 27)

Broadway is classified as an urban principal arterial. The operation of Broadway will be an import aspect to a successful detour. It services downtown Cleveland and has access to both I-77 (two points of access) and I-490. The roadway south of Orange Avenue is four lanes. Multiple lanes exist north of Orange Avenue. It has multiple bus stops and either has no parking or no parking during peak periods in the study area.

## Corridor Recommendations

Resurface the corridor from I-77 to the Orange Avenue/East 9<sup>th</sup> intersection.

## **Local Improvements**

## Broadway to Dille

Construct new traffic signal with pedestrian push buttons and vehicle detection on Dille.

## Broadway at East 37<sup>th</sup> and Rockefeller

Replace damaged guardrail in the northwest quadrant of the intersection. The damaged guardrail is an indication that the turn radius is too small. However, the existing structure is too close to the road to increase the size of the radius. Any increase in turn radius would likely result in the need to acquire the structure.

Add video detection to the existing traffic signal. The northbound left turn lane has a protected phase and no detection as it is on a bridge. Adding detection to this movement will increase the overall capacity of the intersection. Standard induction loops do not work well in the bridges as the steel in the bridge affects their performance. The best alternative for detection is video.

## Broadway at East 34<sup>th</sup>

Install temporary signal. This has been proven effective on other projects that used Broadway as a detour.

## Broadway at East 30<sup>th</sup>

Install detection for East 30<sup>th</sup>. Detection for vehicles is important to ensure the phases are not called for unnecessarily, thus reducing the overall capacity of the intersection.

## Broadway at Rockefeller and Post Office

Install detection for post office driveway. Detection for vehicles is extremely important in ensuring that the phases are not called for unnecessarily, thus reducing the overall capacity of the intersection. Add guardrail to protect the failing wall adjacent to the Rockefeller Bridge.

Items for Further Study



## West Boulevard from I-90 to SR2

(see Sheets 13-17 of 27)

West Boulevard is classified as a minor arterial in the study area. It is for the majority of the study area a 4-lane roadway with a short section of 3-lane starting just south of Baltic and ending at SR 2. Bus stops are prevalent throughout the study area and where on-street parking is permitted, it is prohibited during morning and evening peak hours.

## Corridor Recommendations

None.

## **Local Improvements**

## West Boulevard at I-90 Eastbound Off-Ramp

Change lane usage on off-ramp to a left-turn lane and a right-left turn lane.

Replace push buttons. Broken push buttons decrease the capacity of the signal because the signal is placed in pedestrian recall. If the signal is in pedestrian recall, the side street green is called automatically whether there is a vehicle present or not, thus reducing the throughput of the major street.

## West Boulevard between Western Avenue and Madison

Resurface southbound curb lane (~Sta 15+85 to ~Sta 32+75). The curb lane exhibits cracking and is in poor condition.

Resurface entire roadway from the curve near one-way spur from Madison to the intersection of Madison.

The pavement is in poor condition with heavy cracking in the northbound curb lane.

#### West Boulevard at Madison

Construct new traffic signal with vehicle detection and pedestrian push buttons. Existing signal will give right-of-way to legs with no traffic.

Prohibit West Boulevard northbound left-turns from 7 – 9 am

Prohibit West Boulevard southbound left turns from 3 – 6 pm

#### West Boulevard between Madison and Detroit

Resurface the road as the pavement condition is poor with heavy cracking and potholes.

## West Boulevard at Detroit (westerly intersection)

Construct new traffic signal with vehicle detection and pedestrian push buttons.

Change northbound lane usage to allow for a double right.

See Items for Further Study for discussion on westbound dual left.

## West Boulevard at Detroit (easterly intersection)

Construct new signal based on result for recommended additional study.

## West Boulevard from Detroit (easterly intersection) to Baltic

Resurface southbound curb lane. The pavement is in poor condition with heavy cracking and ride ability is poor.

Note: West Boulevard is primarily a 4-lane roadway until the railroad bridge south of Baltic where it narrows to three lanes. The only way to accommodate two lanes in each direction would be to either create a reversible lane or choose a direction (northbound preferred) and dedicate a third lane to the other direction.

#### West Boulevard at Baltic

Prohibit West Boulevard northbound left turns from 7 – 9 am

Prohibit West Boulevard southbound left turns from 3 – 6 pm

Possible new signal dependent on how the 3-lane section is used (see note above).

## West Boulevard from Baltic to Clifton

Resurface southbound curb lane. The pavement is in poor condition with heavy cracking and ride ability is poor.

See note above for discussion on lane usage in this 3-lane section.

## West Boulevard at Clifton and West Boulevard at SR 2

Possible new signal dependent on how 3-lane section is used (see note above).

## Items for Further Study

The intersection of West Boulevard and Detroit (westerly intersection) should be analyzed to determine if one of the westbound lanes could be converted to a left-turn lane, thus creating dual left-turn lanes from the westbound. This determination will need to be based on a capacity analysis.

The intersection of West Boulevard and Detroit (easterly intersection) should be analyzed to determine how best to accommodate an eastbound dual left. It could be accomplished by either making the inside eastbound thru-lane a dedicated left-turn lane or by making it a thru-left lane. In the latter case, the eastbound and westbound phases would need to be split (not operate together) and the pedestrian crossing for Detroit would be eliminated for the duration of the project.



## Carnegie Avenue from Lorain Avenue to East 30<sup>th</sup>

(see Sheets 18-20/27)

Carnegie is classified as an urban principal arterial. Carnegie is a 6-lane roadway to the west of East 22<sup>nd</sup> and a 5-lane roadway to the east of East 22<sup>nd</sup>. The operation of Carnegie will be an important aspect to the overall detoured traffic. Carnegie services multiple areas of Cleveland including the Gateway district and Cleveland State University. There are no bus stops on Carnegie and the only area where parking is allowed during peak hours is between East 9<sup>th</sup> and East 14<sup>th</sup>.

## Corridor Recommendations

None.

## Local Improvements

Carnegie from Ontario to East 9<sup>th</sup>

Resurface roadway as the pavement is in fair to poor condition with rutting noted in the westbound left turn lane at Ontario.

## Carnegie at East 9<sup>th</sup>

Resurface intersection area

Install new pushbuttons and video detection. Detection for both pedestrians and vehicles is extremely important to ensure that the phases are not called unnecessarily thus reducing the overall capacity of the intersection.

## Carnegie at East 14<sup>th</sup>

Replace push buttons. Broken push buttons decrease the capacity of the signal by placing the signal in pedestrian recall. If the signal is in pedestrian recall, the side street green is called automatically whether there is a vehicle present or not thus reducing the throughput of the major street.

## Carnegie at East 18<sup>th</sup>

Replace loops and resurface the southbound approach on East 18<sup>th</sup>. The pavement was in poor condition with heavy cracking.

## Carnegie from I-90 eastbound off ramp to East 28<sup>th</sup>

Eliminate midblock crosswalk traffic signal. Pedestrians can cross Carnegie at East 30<sup>th</sup> Street. Unnecessary stops on Carnegie should be eliminated to increase the overall capacity of the corridor.

## Items for Further Study

Explore the possibility of eliminating parking during peak hours between East 9<sup>th</sup> and East 14<sup>th</sup>, should further analysis show that the additional lane is necessary.



## East 9th Street and from Carnegie Avenue to Broadway Avenue

(see Sheet 21 of 27)

East 9<sup>th</sup> is classified as an urban principal arterial and is a 4-lane roadway with the limits of this study. It is a vital north/south street for traffic entering and leaving the city. Its access to I-90 westbound will be removed during construction however it will still maintain its access to I-77 southbound via an on-ramp or through the use of Broadway. The westbound I-90 access can be re-established via Broadway and I-490. There are no bus stops or on-street parking within the study limits.

## Corridor Recommendations

Resurface the roadway from Broadway to Carnegie. The pavement is in fair to poor condition with heavy cracking southbound.

## **Local Improvements**

East 9<sup>th</sup> at Carnegie

See discussion in the Carnegie evaluation.

## Items for Further Study

None.

## East 14<sup>th</sup> Street from Carnegie Avenue to Broadway Avenue

East 14<sup>th</sup> is classified as an urban collector. It is primarily a bifurcated roadway between the I-90 westbound on-ramp and Orange. East 14<sup>th</sup> performs the same function as East 9<sup>th</sup> is this area which is to distribute/collect vehicles from the interstate system and connect them to downtown Cleveland. There are no bus stops or onstreet parking on this section of East 14th.

## Corridor Recommendations

None.

## Local Improvements

East 14<sup>th</sup> from Carnegie to the East 9<sup>th</sup> Street exit ramp from I-77 northbound. Resurface the roadway as the pavement is in poor condition.

East 14<sup>th</sup> from Orange to Broadway Resurface the roadway as the pavement is in poor condition.

## Items for Further Study



## East 22<sup>nd</sup> Street from Carnegie Avenue to Orange Avenue

(see Sheets 19 and 23 of 27)

East 22<sup>nd</sup> is classified as an urban minor arterial. It is a 6-lane roadway in the study section and it services St. Vincent Charity Hospital, Cuyahoga Community College, and the U.S. post office. On-street parking is present during the peak periods on sections of the roadway which also has multiple bus stops.

## Corridor Recommendations

None.

## **Local Improvements**

East 22<sup>nd</sup> and Cedar Intersection

Resurface the intersection due to poor pavement condition. Also, include Cedar from the intersection to Carnegie Avenue.

East 22<sup>nd</sup> from Community College Avenue to Orange

Resurface the roadway as the pavement is in fair to poor condition with the cracking prevalent in the northbound lanes.

## Items for Further Study

Explore the possibility of eliminating parking during peak hours between Cedar and Central should further analysis show that an additional lane is necessary.

## East 30<sup>th</sup> Street from Woodland Avenue to Broadway Avenue

East 30<sup>th</sup> is classified as an urban minor arterial and is a 4-lane roadway. I-77 has on and off ramps servicing both northbound and southbound traffic on this section of the street. There is no on-street parking. A pair of bus stops is present south of the Orange intersection.

## Corridor Recommendations

None.

## **Local Improvements**

East 30<sup>th</sup> at Woodland

Resurface the southbound approach of East 30<sup>th</sup> north of the intersection as the pavement is in poor condition.

Replace push buttons. Broken push buttons decrease the capacity of the signal because the signal is placed in pedestrian recall. If the signal is in pedestrian recall the side street green is called automatically whether there is a vehicle present or not thus reducing the throughput of the major street.

East 30<sup>th</sup> at Broadway

See Broadway at East 30<sup>th</sup> (Page 3).

## Items for Further Study



## **Woodland Avenue from East 22<sup>nd</sup> Street to East 30<sup>th</sup> Street**

(see Sheet 25 of 27)

Woodland is classified as an urban minor arterial. It is a one-way westbound roadway with 3-lanes between East 22<sup>nd</sup> and the Orange Avenue spur and 6-lanes from the Orange Avenue spur to East 30<sup>th</sup>. There are no bus stops in this section of roadway and on-street parking is present in the lane adjacent to Cuyahoga Community College for the entire study section.

## Corridor Recommendations

None

## Local Improvements

Woodland from East 22<sup>nd</sup> to the Orange Avenue spur Resurface the roadway as the pavement is in fair to poor condition.

Woodland at East 30<sup>th</sup> See East 30<sup>th</sup> at Woodland (page 7)

## Items for Further Study

Explore the possibility of eliminating parking during peak hours. The need for this lane would be dependent upon the operation of the traffic signal at East 30<sup>th</sup>. Specifically does the westbound approach of Woodland at East 30<sup>th</sup> need 5-lanes of through traffic to operate effectively. If the westbound approach does not need the 5-lane then parking may remain.

## **Orange Avenue from East 9th Street to East 30th Street**

(see Sheets 26 and 27 of 27)

Orange Avenue is classified as an urban principal arterial and is a 2-way, 6-lane roadway between East 9<sup>th</sup> and the post office. After the post office it becomes 3-lanes one-way eastbound. There is no parking or bus stops on this section of Orange.

## Corridor Recommendations

None.

## Local Improvements

Orange at East 30<sup>th</sup>

Resurface the eastbound left thru lane near the intersection as the pavement is in poor condition.

## Items for Further Study



Central Viaduct Local Detour Route Study ODOT PID No. 83680

## **Global Recommendations**

Properly functioning traffic signals are the key to providing the maximum capacity on streets without adding additional lanes. As explained earlier in this report, malfunctioning or missing push buttons decrease the efficiency of signalized intersections. Throughout the field review, it was noticed that multiple intersections had pedestrian push buttons missing. In addition to these specific areas, additional push buttons were included in the cost estimate to ensure that intersections are functioning more efficiently.


The detour streets should be analyzed to determine what, if any, additional capacity is available during peak periods. This would involve obtaining peak hour traffic counts, creating a base year microsimulation traffic model, and conducting a sensitivity analysis to determine the percentage, if any, of additional traffic that this corridor could tolerate without failing in terms of level of service.

Detouring traffic will change the traffic patterns on these roadways. The traffic signals are currently timed for existing traffic conditions. Revised traffic signal timing plans should be generated as part of the analysis in determining the amount of additional traffic a roadway may accept. In cases where there is an existing or proposed closed loop traffic signal system, new system timings should be provided for the AM and PM peak periods with a separate plan for off-peak times. In cases where the signal is not in a system, three timing patterns should be developed. In this case, the patterns can be input into the controller based on the time of day.


## **Construction Cost Estimate**

The overall construction cost estimate is \$3,521,000. The detailed information can be found after the photo log.











TRAFFIC

**9** 

MAINTENANCE

0





.jects\Central Viaduct MOT\Innerbelt BM\West25thGP1.dan 9/15/2008 10:31:24 AM lis

NESTLE NFS INC.

 $\bigcirc$ 


 $\bigcirc$ 

OCAL ROUTE STUDY

NO STOPPING DURING PEAK HOURS
NO PARKING DURING NON-PEAK HOURS
27

→ PARKING DURING PEAK HOURS





## RECOMMENDATIONS:

 $\bigcirc$ 

 $\bigcirc$ 

- NEW SIGNAL WITH INTERCONNECT INCREASE NB RIGHT TURN RADIUS TO ACCOMMODATE FREE-FLOW DOUBLE RIGHT RESTRICT CHATHAM AVE. TO ONE-WAY WB ADD INTERCONNECT



TRAFFIC SIGNAL

BUS STOP

PAVEMENT RESURFACING


NEW PAVEMENT

→ NO PARKING

PARKING DURING NON-PEAK HOURS

PARKING DURING PEAK HOURS

NO STOPPING DURING PEAK HOURS NO PARKING DURING NON-PEAK HOURS



 $\bigcirc$ 

TRAFFIC TO STA. ORAIN

AL ROUTE STUDY

 $\bigcirc$ 

SE OF TRAFFIC . 27+00 TO STA. 52+00

MAINTENANCE OF TRAFFIC Lorain ave - Sta. 27+00 to Sta

LOCAL ROUTE STUDY

RECOMMENDATIONS:

 $\bigcirc$ 

 $\bigcirc$ 

 $\bigcirc$ 

STA TRAFFIC 10 52+00 OF MAINTENANCE

LORAIN

→ NO STOPPING DURING PEAK HOURS NO PARKING DURING NON-PEAK HOURS






PAVEMENT RESURFACING


→ PARKING DURING NON-PEAK HOURS

→ PARKING DURING PEAK HOURS

→ NO PARKING









 $\bigcirc$ 

 $\bigcirc$ 

RAMP TO IR-77 SB

RECOMMENDATIONS:

- NEW SIGNAL WITH PUSH BUTTONS - ADD DETECTION ON DILLE RD. APPROACH



 $\bigcirc$ 

00 0F 150÷ AVE BROADWA

175+50

LOCAL ROUTE STUDY

 $\bigcirc$ 






+50 SCAL

MAINTENANCE OF TRAFFIC / AVE - STA.175+00 TO STA.20

JTE BROADW

LOCAL ROUTE STUDY



 $\bigcirc$ 


F TRAFFIC 10+50 TO STA. 227+00 GALE

MAINTENANCE OF TRAFFIC BROADWAY AVE - STA. 200+50 TO STA

> OCAL ROUTE STUDY


LOCAL ROUTE STUDY

TRAFFIC SIGNAL














 $\bigcirc$ 

 $\bigcirc$ 



25+00

TRAFFIC TO STA.

: 0F 0+00

MAINTENANCE BLVD - STA.O

LOCAL ROUTE STUDY

 $\bigcirc$ 



TRAFFIC 10 **2** + **00** OF MAINTENANCE BLVD - STA.2

LOCAL ROUTE STUDY

TRAFFIC SIGNAL

BUS STOP


 $\bigcirc$ 

 $\bigcirc$ 

 $\bigcirc$ 

PAVEMENT RESURFACING

- → NO PARKING
- → PARKING DURING NON-PEAK HOURS
- → PARKING DURING PEAK HOURS
- NO STOPPING DURING PEAK HOURS NO PARKING DURING NON-PEAK HOURS



MATCHLINE STA. 47+00 SEE SHEET 14

RECOMMENDATIONS:

- NEW SIGNAL WITH PUSH BUTTONS ACCOMODATE NB DOUBLE-RIGHT TURN BY MAKING INSIDE LANE RIGHT/LEFT TURN

RECOMMENDATIONS:

- POSSIBLE NEW SIGNAL BASED ON PHASING ACCOMMODATE EB DOUBLE-LEFT TURN
- BY EITHER:
  - (A) MAKING MIDDLE EB LANE LEFT TURN ONLY
    (B) MAKING MIDDLE EB LANE LEFT/THRU WITH
    SPLIT PHASE OPERATION ON DETROIT
    (WOULD REQUIRE REMOVAL DETROIT
    PEDESTRIAN CROSSING)





TRAFFIC 103+00 OF.

LOCAL ROUTE STUDY




 $\bigcirc$ 

MAINTENANCE ( BLVD - STA.117

LOCAL ROUTE STUDY









 $\bigcirc$ 

NO STOPPING DURING PEAK HOURS NO PARKING DURING NON-PEAK HOURS






 $\bigcirc$ 













PAVEMENT RESURFACING


- → NO PARKING
- → PARKING DURING NON-PEAK HOURS
- → PARKING DURING PEAK HOURS
- NO STOPPING DURING PEAK HOURS NO PARKING DURING NON-PEAK HOURS

 $\bigcirc$ 

 $\bigcirc$ 




TRAFFIC SIGNAL








- → PARKING DURING NON-PEAK HOURS
- → PARKING DURING PEAK HOURS
- → NO STOPPING DURING PEAK HOURS NO PARKING DURING NON-PEAK HOURS



 $\bigcirc$ 



 $\bigcirc$ 



TRAFFIC O TO STA.

00+0

0F

MAINTENANCE 2ND ST - STA

**22ND** 

LOCAL ROUTE STUDY

 $\bigcirc$ 



TRAFFIC O TO STA 11.88


MAINTENANCE OF TRA AST 30TH ST. - STA. 0+00 T

LOCAL ROUTE STUDY

24 27

NO STOPPING DURING PEAK HOURS NO PARKING DURING NON-PEAK HOURS







 $\bigcirc$ 

 $\bigcirc$ 

MAINTENANCE OF TRAFFIC IGE AVE - STA. 0+00 TO STA. 22+50

LOCAL ROUTE STUDY

26 27


27







TRAFFIC SIGNAL





- → NO PARKING
- → PARKING DURING NON-PEAK HOURS
- → PARKING DURING PEAK HOURS
- → NO STOPPING DURING PEAK HOURS NO PARKING DURING NON-PEAK HOURS

#### GROUP 0001: Roadway

Citobi oooi. Itodaway				
0005 202E23000 PAVEMENT REMOVED	147.00	SY	\$16.08	\$2,363.76
0006 202E38000 GUARDRAIL REMOVED	60.00	FT	\$1.52	\$91.20
0007 202E58100 CATCH BASIN REMOVED	1.00	EACH	\$263.28	\$263.28
0008 203E10000 EXCAVATION	265.00	CY	\$22.87	\$6,060.55
0009 204E10000 SUBGRADE COMPACTION	530.00	SY	\$1.25	\$662.50
0010 254E01000 PAVEMENT PLANING, ASPHALT CON	113,021.00	SY	\$1.15	\$129,974.15
0011 302E46000 ASPHALT CONCRETE BASE, PG64-2	4,731.00	CY	\$80.74	\$381,980.94
0012 304E20000 AGGREGATE BASE	88.00	CY	\$45.82	\$4,032.16
0013 407E10000 TACK COAT	8,516.00	GAL	\$1.05	\$8,941.80
0014 407E14000 TACK COAT FOR INTERMEDIATE CO	5,678.00	GAL	\$1.06	\$6,018.68
0015 408E10000 PRIME COAT	45,420.00	GAL	\$1.75	\$79,485.00
0016 446E46040 ASPHALT CONCRETE INTERMEDIAT	4,731.00 E COURSE.		\$71.40	\$337,793.40
0017 446E47010 ASPHALT CONCRETE SURFACE CO	4,731.00	CY	\$74.63	\$353,074.53
0018 604E00400 CATCH BASIN, NO. 3	The state of the s	EACH	\$2,290.00	\$2,290.00
0019 606E13000 GUARDRAIL, TYPE 5	185.00	FT	\$15.39	\$2,847.15
0020 609E14000 CURB, TYPE 2-A	131.00	FT	\$8.85	\$1,159.35
0021 632E26000 PEDESTRIAN PUSHBUTTON	34.00	EACH	\$118.03	\$4,013.02
0022 632E26500 DETECTOR LOOP	9.00	EACH	\$876.26	\$7,886.34
0023 632E52600 INTERCONNECT CABLE, 6 CONDUC	4,000.00 TOR. NO. 12		\$2.00	\$8,000.00
0024 642E00090 EDGE LINE		MILE	\$509.26	\$2,770.37
0025 642E00290 CENTER LINE	2.24	MILE	\$691.22	\$1,548.33
0026 642E00390 CHANNELIZING LINE	3,106.00	FT	\$0.49	\$1,521.94
0027 642E00490 STOP LINE	1,026.00	FT	\$2.21	\$2,267.46
0028 642E00590 CROSSWALK LINE	2,230.00	FT	\$1.55	\$3,456.50
0029 642E00690 TRANSVERSE/DIAGONAL LINE	593.00	FT	\$1.81	\$1,073.33
0030 642E01290 LANE ARROW	112.00	EACH	\$45.00	\$5,040.00
0031 816E30000 VIDEO DETECTION SYSTEM	2.00	EACH	\$16,274.54	\$32,549.08
0032 632E90400 SIGNALIZATION, MISC.: signalized intersection	11.00	EACH	\$130,000.00	\$1,430,000.00

Total for Group 0001: \$2,817,164.84

#### **Estimate Local Streets**

Estimated Cost: \$2,817,164.82 Contingency: 25.00%

**Estimated Total: \$3,521,456.03** 

Local Street Upgrades
Base Date: 09/12/08
Spec Year: 08

Unit System: E

Work Type: ASPHALT

Highway Type: 446

Urban/Rural Type: URBAN CLASS

Season: SUMMER
County: CUYAHOGA
Midpoint of Latitude:
Midpoint of Longitude:

District: 12

Federal/State Project Number: 83680

Prepared by EL/JAA on 09/12/08

#### West 25Th Street from I-90 to Lorain and Lorain from West 25th to Ontario

Central Viaduct Local Detour Route Study ODOT PID No. 83680

1

Notes: None



West 25th @ Wade Looking North

3

Notes:

Damaged guardrail



West 25th @ Vega Looking West

2

Notes:

Reconfigure lanes on off-ramp/Wade



West 25th @ Wade Looking West

4

Notes:

Showing alternative entrance to I-90 west-bound



West 25th @ Barber Looking East



#### West 25Th Street from I-90 to Lorain and Lorain from West 25th to Ontario

**Central Viaduct Local Detour Route Study ODOT PID No. 83680** 

5

6

poor condition

Pavement on Columbus approach is in

Notes:

Notes:

Replace damaged catch basin (near southbound stop bar).



West 25th @ Potter Court

Looking Southeast



West 25th @ Columbus Looking Southwest from Columbus Road

Notes: None



West 25th @ Monroe Looking South

Notes:

Showing northbound right turn lane and traffic calming area



West 25th @ Gehring Looking Southwest from Gehring



#### West 25Th Street from I-90 to Lorain and Lorain from West 25th to Ontario

Central Viaduct Local Detour Route Study ODOT PID No. 83680

9

Notes:


Poor is in pavement condition on Gehring



Gehring Looking Northeast

10

Notes: None



Gehring @ Abbey Looking Northeast

11

Notes: None



Lorain @ West 20th Looking West

12

Notes: Emergency vehicle use intersection.



Lorain / Carnegie @ Ontario Broadway Commercial Looking West



#### West 25Th Street from I-90 to Lorain and Lorain from West 25th to Ontario

Central Viaduct Local Detour Route Study ODOT PID No. 83680

13

14

Rutting in southbound Ontario north of

Notes:

intersection.

Notes:

Pavement is in poor condition on Ontario Spur



Ontario Spur @ Lorain Looking South



Ontario @ Lorain Looking East (from median)

15

Notes:

Pavement is in poor condition of eastbound left –turn lane east of intersection



Lorain / Carnegie @ Ontario Broadway Commercial Looking West

16

Notes:

Signal poles and mast arms showing deteriorated condition.



Lorain / Carnegie @ Ontario Broadway Commercial Looking West



Central Viaduct Local Detour Route Study ODOT PID No. 83680

1

Notes: None



Broadway @ IR-77 NB Exit Ramp Looking South

2

Notes: None



Broadway @ IR-77 NB Exit Ramp Looking Northwest

3

Notes: None

Notes:

None



Broadway @ Dille Looking Northwest



Broadway @ IR-490 EB Exit Ramp Looking Northwest



1

### **Central Viaduct Local Detour Route Study** ODOT PID No. 83680

5

6

Notes:

None

Notes:

Tight left turn radius for trucks



Broadway @ IR-490 EB Exit Ramp Looking East



Broadway @ East 37th / Rockefeller Looking Northwest

Notes:

Need video detection for left turn lane on bridge



Broadway @ East 37th / Rockefeller Looking Southeast



Damaged guardrail

Notes:



Broadway @ East 37th / Rockefeller Looking West towards IR-490 WB Entrance Ramp



### **Central Viaduct Local Detour Route Study** ODOT PID No. 83680

9

**10** 

Notes: None

Notes:

Reinstall temporary signal during construction



Broadway @ East 34th

Notes: None

12


Looking Northwest



Broadway @ East 30th Looking Northwest

11

Notes: Add detection on USPS Drive



Broadway @ Rockefeller / USPS Looking Northwest



Broadway @ Orange / East 9th Looking North



Central Viaduct Local Detour Route Study ODOT PID No. 83680

13

Notes: None



Broadway @ Orange / East 9th Looking Northwest

14

Notes: None



Broadway @ Carnegie Looking Southeast



### **Central Viaduct Local Detour Route Study** ODOT PID No. 83680

Notes:

Reconfigure lanes on off-ramp



West @ I-90 Westbound Off-Ramp Looking West

3

Notes: None



West @ Western Looking North

2

Notes: None



West @ I-90 Westbount On-Ramp Looking West

Notes:

Pavement is in poor condition in southbound curb lane.



West between Western and Madison Looking South



### Central Viaduct Local Detour Route Study ODOT PID No. 83680

5

Notes:

Notes:

None

Pavement is in poor condition in southbound curb lane.



West between Madison and Western Looking South

8

Notes: None

Notes:

Pavement is in poor condition at intersection area (looking as northbound stop bar).



West @ Madison Looking North

West between Madison Spur and Madison Looking West



West @ Madison Looking North



### Central Viaduct Local Detour Route Study ODOT PID No. 83680

9

Notes:

Pavement is in poor condition on West



West between Madison an Detroit Looking North

Notes: Pavement is in poor condition on West

**10** 



West between Madison an Detroit Looking North

11

Notes: Change lane usage

12

Study need for dual left westbound

Notes:



West @ Detroit (Westerly Intersection)
Looking North



Detroit @ West (Westerly Intersection)
Looking West



### Central Viaduct Local Detour Route Study ODOT PID No. 83680

13

Notes:

Study lane use changes on the eastbound approach.



Detroit @ West (Westerly Intersection)
Looking East

15

Notes:

Pavement condition is poor and beginning of 3-lane section to the north.



West @ Baltic Looking North

14

Notes:

Pavement is in poor condition.



West between Detroit and Baltic Looking South

16

Notes: 3-lane section

Pavement condition is poor in southbound curb lane.




West between Baltic and Clifton Looking North



Central Viaduct Local Detour Route Study ODOT PID No. 83680

17

Notes: None



West between Clifton and SR 2 Looking North

18

Notes: None



West @ SR 2 Looking North



### Central Viaduct Local Detour Route Study ODOT PID No. 83680

1

Notes:

Pavement in westbound left-turn lane is in poor condition.



Carnegie between East 9th and Lorain Looking West

3

Notes:

None

Notes:

Pavement is in poor condition in intersection area.

BO RD?

Carnegie @ East 9th Looking East

Notes:

2

Pavement in westbound curb lane is in poor condition with poor rideability.



Carnegie between East 9th and Lorain Looking West



Carnegie @ East 9th Looking East




1

Central Viaduct Local Detour Route Study ODOT PID No. 83680

5

Notes:


On-street parking in peak hours.



Carnegie between East 9th and East 14th Looking East

6

Notes: None



Carnegie @ East 14 Looking East

7

Notes: None

Notes:



Carnegie @ East 18th Looking East



Carnegie @ East 18th
Looking West (southbound approach)



Central Viaduct Local Detour Route Study ODOT PID No. 83680

9

Notes: None



Carnegie @ East 19th Looking East

11

Notes: None



Carnegie @ East 22nd

**10** 

Notes: None



Carnegie @ East 21st

12

Notes:

Eliminate mid-block cross walk.



Carnegie between I-90 eastbound off-ramp and East 28th Looking East



Central Viaduct Local Detour Route Study ODOT PID No. 83680

13

Notes: None



Carnegie @ East 30th Looking East

14

Notes:



Carnegie @ East 30th Looking South (on East 30th)



### **Photo Log East 9th Street from Carnegie to Broadway**

**Central Viaduct** Local Detour Route Study ODOT PID No. 83680

Notes: None




3

East 9th @ Carnegie Looking South towards IR-90

2

Notes:



East 9th Looking South towards IR-90



Broadway @ East 9th Looking North



### **Photo Log East 14th Street from Broadway Avenue to Carnegie Ave**

### **Central Viaduct Local Detour Route Study** ODOT PID No. 83680

Notes:

Pavement is in poor condition.



East 14th @ Broadway Looking South

2

Notes:

Pavement is in poor condition.



East 14th @ Orange

3

Notes:



East 14th Looking South towards IR-77



Looking North

Notes: Poor pavement condition north of ramp merge.



East 14th @ IR-77 NB Exit Ramp terminal Looking South



# Photo Log East 14th Street from Carnegie to Broadway

Central Viaduct Local Detour Route Study ODOT PID No. 83680

5

Notes:



East 14th Looking South towards IR-90

# Photo Log East 22nd from Carnegie to Orange

Central Viaduct Local Detour Route Study ODOT PID No. 83680

1

Notes:

Pavement is in poor condition.



East 22nd between Carnegie and Cedar Looking East

1

Notes: None

3

Notes: Parking present during peak hours.



East 22nd between Cedar and Central Looking South



East 22nd @ Central

2

Notes:



Cedar Spur between Carnegie and East 22nd Looking Southeast



# Photo Log East 22nd from Carnegie to Orange

Central Viaduct Local Detour Route Study ODOT PID No. 83680

5

Notes: None



East 22nd @ Community College Ave.

6

Notes:



East 22nd Between Community College Ave. and Orange Looking North





East 22nd @ Orange Looking South



#### East 30th Street from Broadway Avenue to Woodland Avenue

Central Viaduct Local Detour Route Study ODOT PID No. 83680

1

Notes: None



East 30th @ Broadway Looking South

2

Notes: None



East 30th Looking South towards Broadway

3

Notes: None



East 30th @ Orange Looking North



East 30th @ Orange Looking South




#### East 30th Street from Broadway Avenue to Woodland Avenue

Central Viaduct Local Detour Route Study ODOT PID No. 83680

5

Notes: None



East 30th under IR-77 Looking North

7

Notes: Pavement is in poor condition.



East 30th Looking South towards Woodland

6

Notes: None



East 30th @ Woodland Looking South



#### **Woodland Avenue from East 22nd Street to East 30th Street**

1

Notes:

Pavement is in poor condition.



3

Woodland @ East 22nd Looking West

2

Notes:

Pavement is in poor condition.



Woodland west of Orange Spur Looking West

Central Viaduct
Local Detour Route Study

ODOT PID No. 83680



Woodland east of Orange Spur Looking West



### **Photo Log Orange Avenue from East 9th to East 30th Street**

**Central Viaduct Local Detour Route Study** ODOT PID No. 83680

2

Notes:

None

Notes: None



Orange @ East 14th

Looking East



Orange @ East 22nd Looking East

3

Notes:

None

Poor pavement condition in curb lane just before drive



Orange @ USPS Drive Looking East



Orange @ IR-77 SB Exit Ramp Merge Looking East



# Photo Log Orange Avenue from East 9th to East 30th Street

Central Viaduct Local Detour Route Study ODOT PID No. 83680

5

Notes: None



Orange @ East 30th Looking East

