

BREACH BETWEEN STREAM AND ROAD SIDE DITCH NEEDING REPAIRED

APPROX 80 LF OF REPAIR NEEDED & APPROX 200 TON TYPE B DUMP ROCK NEEDED FOR BREACH AND DAM AREA'S

DAM WITH 2 EA 24" CULVERTS WITH BACKFLOW PREVENTERS NEEDED REPLACED

APPROX-1100' OF DITCHING NEEDED /

OUTLET OF CROSS PIPE NEEDS LAST 2 SECTIONS RESET TO ORIGINAL ELEVATION TO HELP WATER FLOW TO ORIGINAL ROADSIDE DITCH