Caus - 70 - 0943A
Ramp A.
10-22-99



Gue -70-0943A



Gué-70-0943A Ramp A 10-22-99



Curtis Zigan@Production@D-05 To: Čc: '' Bcc: Lloyd Welker@StructuralEng@EngPolicy From: re: Heat Straightening Work Type Subject: Monday, October 25, 1999 at 4:22:37 pm EDT Date: Attach: Certify: Curtis LOOKED AT YOUR PICTURES AND NOT TOTALLY SURE WHAT I AM SEEING BUT TWO(2) CAUGHT MY EYE. 4325 HAS TWO HOLES AT THE WELD WHICH SOMEBODY PUT IN TO ARREST THE CRACK THAT HAD BEEN THERE BEFORE. YOU HAVE ALREADY SEEN IT BUT THE CRACK WENT BEYOND THE HOLE. 4333 MIGHT BE A DESCRIPTION OF THE PAINT BEING BAD. I WOULD GUESS YOU MIGHT REMOVE TO THE LIMITS OF THE PAINT IN THIS LOCATION. AN ALTERNATIVE FOR REPAIR MIGHT BE: MARK THE PAINT DAMAGE LOCATIONS 1. REMOVE THE PAINT 2. MAGNETIC PARTICLE THE AREA TO FIND CRACKS 3. GO AT LEAST 1 INCH TO AN 1 1/2 OUTSIDE ANY CRACK LOCATION WITH THE FINAL REMOVAL BEING RECTANGULAR LLOYD Curtis Zigan@Production@D-05 Wrote: Lloyd, John Wackerly faxed Roger Dodson a list this morning. Attached is some pictures of Gue-70-0943L. ************** Lloyd Welker@StructuralEng@EngPolicy Wrote: Curtis Gave you bad information the other day. There is a prequalification work type for contractors on heat straightening. (Item number 32 of the work types). Talked to J. Toth and he says it isn't a great qualification but there are pre qualifications so you don't necessarily have to have a list of qualified bidders unless you want to get tighter than ODOT's pre-qual.

Sorry about the wrong information the other day

czigan@production@d-05

********** Thanks ! | ***********

INTERNET e-mail: czigan@dot.state.oh.us

Curtis Zigan, P.E. District 5, ODOT


Lloyd

ODOT e-mail:

Gué-70-0943L.
10-22-99
Beam



GUE-70-6943L.




Caué-70-6943L



Gut-10-0943L





GUE-70-09431





CHE-70-0943L





Gus-70.0943L

