

LIC-13-0389_Dawes culvert current inspection**Inspection Date: 2/12/2024**

R-Level of Inspection	Inspection from ends of conduit (Non-entry)
R-Conduit Material Condition	4 - Poor
R-Conduit Alignment	7 - Good
R-Conduit Shape Rating (Leave blank if Rigid)	7 - Good
R-Seams or Joints (Leave blank if N/A)	7 - Good
R-Slab (Only rate if Shape is Slab)	
R-Abutments (Leave blank if N/A)	
R-Headwalls (Leave blank if N/A)	7 - Good
R-End Structure	
R-Channel Alignment	8 - Very Good
R-Channel Protection	8 - Very Good
R-Conduit Waterway Blockage	8 - Very Good
R-Scour	8 - Very Good
R-Pavement	7 - Good
R-Guardrail (Leave blank if N/A)	7 - Good
R-Embankment	7 - Good
R-General Appraisal	4 - Poor condition - advanced section loss, deterioration, or spalling
R-Operational Status	Open - no restriction

O-Inspection comments

Conduit segments at roadway limits are highly perforated, see photos.

R-Inspection Date

2/12/2024

O-Recommend Preventive
Maintenance

O-Recommend Inspection
Frequency (Months)