



9375 Chillicothe Road
Kirtland, OH 44094-8501

T (440) 256-6500

www.sme-usa.com

August 9, 2016

David Lastovka, P.E.
ODOT District 12 Transportation Engineer
Ohio Department of Transportation
5500 Transportation Boulevard
Garfield Heights, Ohio 44125-5396

E-mail to: Dave.Lastovka@dot.state.oh.us

Re: July 18, 19, and 20, 2016 Bi-Weekly Readings
CUY-90-15.24 Slope Monitoring
PID 96504
SME Project No. 069032.00

Dear Mr. Lastovka:

Bi-weekly instrument readings for the I-90 west slope taken on July 18, 19, and 20, 2016, are presented in this report. Bi-weekly readings currently include instruments at I/P-001-13, I/P-002-13, I/P-003-10, I/P-004-13, I/P-009-13, B-101, B-102, B-105A, B-05-02, B-05-A-03, B-05-04, B-05-A-11, P-1, P-9N, TGR I-2, and TGR I-4. Changes reported for the individual instruments are for the previous two-week period unless noted otherwise.

Piezometer Readings

P-001-13, P-002-13, P-003-10, P-009-13, B-05-A-03, B-05-04, B-05-A-11 – Pore pressure readings at these locations fluctuated by less than 0.5 feet, but show virtually no net change in total head.

P-004-13 – Piezometers at this location are still inaccessible.

B-105-A – Pore pressure readings indicate a continued increase in total head in the shallow piezometer at this location. Total head increased by about 1 foot since June 17, 2016. Virtually no change is indicated in the deep piezometer.

B-05-02 – At this location, pore pressure readings indicate an increase in total head of about 0.5 feet in both piezometers.

Inclinometer Readings

Inclinometer readings at I-001-13, I-002-13, I-009-13, B-105A, B-05-A-02, P-9N, and TGR I-4 showed virtually no movement. Displacement at the top of some slope tubes is due to construction disturbance or flexing of the inclinometer tube as readings were taken where the protective covers have not been concreted in place because of the ongoing construction activity.

I-003-10 – The inclinometer readings at this location indicate a small amount of displacement in the negative A-axis direction from 176 to 200 feet and in the negative B-axis direction from 120 to 196 feet.

I-004-13 – The inclinometer casing at this location is still inaccessible.

B-101, B-102 – Inclinometer readings at these locations indicate a reversal in the direction of movement. At B-101, the maximum displacement of about 0.2 inches in the negative A-axis direction is shown at 152 feet. A slight reversal is also indicated in the positive B-axis direction from 144 to 182 feet. At B-102, the maximum displacement of about 0.2 inches in the reverse (positive) B-axis direction is shown at 202 feet.

B-05-04 – Inclinometer readings at this location indicate slight movement in the negative A-axis direction from about 70 to 160 feet. This movement is shown to be in the reverse direction. Movement in the B-axis direction is negligible.

B-05-A-11 – Inclinometer readings at this location indicate movement in both axis directions toward the baseline.

P-1 – Inclinometer readings at this location show another reversal in the direction of displacement. The cumulative resultant displacement zone plot shows a decrease of about 0.5 inches.

TGR I-2 – This location is still inaccessible.

This concludes our report of bi-weekly instrument readings. Please call or email with any questions.

Very truly yours,

SME


Brendan P. Lieske, P.E.
Senior Staff Engineer

Alan J. Esser, P.E., D.GE
Chief Consultant

Copied to distribution list.


P-001-13 VW Piezometer Readings

Ground surface elevation = 666.4 ft




P-002-13 VW Piezometer Readings

Ground surface elevation = 675.29 ft




P-003-10 VW Piezometer Readings

Ground surface elevation = 647.9 ft




P-003-10 VW Piezometer Readings

Ground surface elevation = 647.9 ft




P-009-13 VW Piezometer Readings

Ground surface elevation = 586.6 ft




B-105A VW Piezometer Readings

Ground surface elevation = 585.6 ft




B-05-02 VW Piezometer Readings

Ground surface elevation = approx 609.0 ft




B-05-02 VW Piezometer Readings

Ground surface elevation = approx 609.0 ft




B-05-A-03 VW Piezometer Readings

Ground surface elevation = 599.9 ft




B-05-04 VW Piezometer Readings

Ground surface elevation = 600.8 ft



B-05-11/B-05-A-11 VW Piezometer Readings



Ground surface elevation = 675.1 ft (B-05-11) / 676.1 ft (B-05-A-11)



Borehole : I-001-13
Project : CUY-90-15-24
Location : Cleveland, Ohio
Northing :
Easting :
Collar :





Spiral Correction : N/A
Collar Elevation : 3.7 feet
Borehole Total Depth : 228.0 feet
A+ Groove Azimuth :
Base Reading : 2015 Mar 03 11:14
Applied Azimuth : 0.0 degrees



Borehole : I-002-13
Project : CUY-90-15-24
Location : Cleveland, Ohio
Northing :
Easting :
Collar :





Spiral Correction : N/A
Collar Elevation : 3.5 feet
Borehole Total Depth : 238.0 feet
A+ Groove Azimuth :
Base Reading : 2015 Mar 03 10:04
Applied Azimuth : 0.0 degrees



Borehole : I-003-10 [206 ft]
Project : CUY-90-15-24
Location :
Northing :
Easting :
Collar :





Spiral Correction : N/A
Collar Elevation : 3.0 feet
Borehole Total Depth : 206.0 feet
A+ Groove Azimuth :
Base Reading : 2016 Mar 08 15:42
Applied Azimuth : 0.0 degrees



Borehole : I-009-13
Project : CUY-90-15-24
Location : Cleveland, Ohio
Northing :
Easting :
Collar :





Spiral Correction : N/A
Collar Elevation : 4.5 feet
Borehole Total Depth : 158.0 feet
A+ Groove Azimuth :
Base Reading : 2015 Mar 18 15:56
Applied Azimuth : 0.0 degrees



Borehole : B-101
 Project : CUY-90-15-24
 Location : Cleveland, Ohio
 Northing : Sta. 15+06.50
 Easting : 120.7' Rt of CL
 Collar :





Spiral Correction : N/A
 Collar Elevation : 0.0 feet
 Borehole Total Depth : 190.0 feet
 A+ Groove Azimuth :
 Base Reading : 2014 Jan 22 09:01
 Applied Azimuth : 0.0 degrees



Borehole : B-101
 Project : CUY-90-15-24
 Location : Cleveland, Ohio
 Northing : Sta. 15+06.50
 Easting : 120.7' Rt of CL
 Collar :





Spiral Correction : N/A
 Collar Elevation : 0.0 feet
 Borehole Total Depth : 190.0 feet
 A+ Groove Azimuth :
 Base Reading : 2014 Jan 22 09:01
 Applied Azimuth : 0.0 degrees



Borehole : B-102
 Project : CUY-90-15-24
 Location : Cleveland, Ohio
 Northing : Sta. 15+95.34
 Easting : 134.7' Rt of CL
 Collar :





Spiral Correction : N/A
 Collar Elevation : 0.0 feet
 Borehole Total Depth : 224.0 feet
 A+ Groove Azimuth :
 Base Reading : 2014 Jan 23 08:21
 Applied Azimuth : 0.0 degrees



Borehole : B-102
 Project : CUY-90-15-24
 Location : Cleveland, Ohio
 Northing : Sta. 15+95.34
 Easting : 134.7' Rt of CL
 Collar :





Spiral Correction : N/A
 Collar Elevation : 0.0 feet
 Borehole Total Depth : 224.0 feet
 A+ Groove Azimuth :
 Base Reading : 2014 Jan 23 08:21
 Applied Azimuth : 0.0 degrees



Borehole : B-105A
Project : CUY-90-15-24
Location : Cleveland, Ohio
Northing : Sta. 19+11.38
Easting : 90.9' Rt of CL
Collar :




Spiral Correction : N/A
Collar Elevation : 3.0 feet
Borehole Total Depth : 156.0 feet
A+ Groove Azimuth :
Base Reading : 2014 Jan 15 09:19
Applied Azimuth : 0.0 degrees



CUY-90-15.24
PID 96504
SME Project#: 069032.00



B-105A



Borehole : B-05-02A
Project : CUY-90-15-24
Location : Cleveland, Ohio
Northing : 663737.939
Easting : 2190289.081
Collar :




Spiral Correction : N/A
Collar Elevation : 1.3 feet
Borehole Total Depth : 168.0 feet
A+ Groove Azimuth :
Base Reading : 2013 Dec 24 11:12
Applied Azimuth : 0.0 degrees



CUY-90-15.24
PID 63504
SME Project#: 069032.00



B-05-02



Borehole : B-05-04
Project : CUY-90-15-24
Location : Cleveland, Ohio
Northing : Sta. 133+51.67
Easting : 242.09' Rt of CL
Collar :





Spiral Correction : N/A
Collar Elevation : 2.3 feet
Borehole Total Depth : 172.0 feet
A+ Groove Azimuth :
Base Reading : 2014 Jan 22 12:30
Applied Azimuth : 0.0 degrees



Borehole : B-05-04
Project : CUY-90-15-24
Location : Cleveland, Ohio
Northing : Sta. 133+51.67
Easting : 242.09' Rt of CL
Collar :




Spiral Correction : N/A
Collar Elevation : 2.3 feet
Borehole Total Depth : 172.0 feet
A+ Groove Azimuth :
Base Reading : 2014 Jan 22 12:30
Applied Azimuth : 0.0 degrees



CUY-90-15.24
PID 96504
SME Project#: 069032.00



B-05-04



Borehole : B-05-A-11
Project : CUY-90-15-24
Location :
Northing :
Easting :
Collar :





Spiral Correction : N/A
Collar Elevation : 0.0 feet
Borehole Total Depth : 230.0 feet
A+ Groove Azimuth :
Base Reading : 2015 Mar 19 09:08
Applied Azimuth : 0.0 degrees



Borehole : B-05-A-11
Project : CUY-90-15-24
Location :
Northing :
Easting :
Collar :





Spiral Correction : N/A
Collar Elevation : 0.0 feet
Borehole Total Depth : 230.0 feet
A+ Groove Azimuth :
Base Reading : 2015 Mar 19 09:08
Applied Azimuth : 0.0 degrees



Borehole : P-1
Project : CUY-90-15-24
Location : Cleveland, Ohio
Northing :
Easting :
Collar :





Spiral Correction : N/A
Collar Elevation : 1.2 feet
Borehole Total Depth : 148.0 feet
A+ Groove Azimuth :
Base Reading : 2014 Jan 22 10:47
Applied Azimuth : 0.0 degrees



Borehole : P-1
 Project : CUY-90-15-24
 Location : Cleveland, Ohio
 Northing :
 Easting :
 Collar :




Spiral Correction : N/A
 Collar Elevation : 1.2 feet
 Borehole Total Depth : 148.0 feet
 A+ Groove Azimuth :
 Base Reading : 2014 Jan 22 10:47
 Applied Azimuth : 0.0 degrees



CUY-90-15.24
PID 96504
SME Project#: 069032.00



P-1



Borehole : P-9N
Project : CUY-90-15-24
Location : Cleveland, Ohio
Northing :
Easting :
Collar :



Spiral Correction : N/A
Collar Elevation : 1.2 feet
Borehole Total Depth : 150.0 feet
A+ Groove Azimuth :
Base Reading : 2014 Jan 16 09:28
Applied Azimuth : 0.0 degrees



Borehole : TGR I-4
 Project : CUY-90-15-24
 Location :
 Northing :
 Easting :
 Collar :



Spiral Correction : N/A
 Collar Elevation : 3.0 feet
 Borehole Total Depth : 58.0 feet
 A+ Groove Azimuth :
 Base Reading : 2015 Sep 23 10:39
 Applied Azimuth : 0.0 degrees

