

STATE OF OHIO DEPARTMENT OF TRANSPORTATION

CULVERT INSPECTION REPORT

CR-86 12-03

283221959CULVERT FILE NUMBER _____ CULVERT NUMBER GEA US 322 19.564 _____ YEAR BUILT 1955

CO ROUTE SLM ID

DISTRICT 12 SHAPE 1 MATERIAL 2 LENGTH 90MAX. HEIGHT OF COVER 0 FEATURE INT. NLATITUDE 41.53511 LONGITUDE -81.01813ENTRY CLASS D NUMBER OF CELLS 1**CULVERT**

1. General	3	2. Culvert Alignment	6
3. Shape	8	4. Seams or Joints	6
5. Slab		6. Abutments	
7. Headwalls	4	8. End Structure	

CHANNEL

9. Channel Alignment	7	10. Protection	8
11. Culvert Waterway Blockage	7	12. Scour	8

APPROACHES

13. Pavement	7	14. Guardrail	9	
15. Embankment	4			
16. Level of Inspection	X	GENERAL APPRAISAL & OPERATIONAL STATUS	3	A

RECOMMENDED REPAIR CODE(S): _____

COMMENTS:

Holes throughout barrel. Some voids behind holes. Headwall slightly rotated and cracked. Upstream channel silted in and trees lying in channel. Layers of heavy rust with scaling. Most bituminous coating is gone.

INSPECTED BY: WG DATE: 3/20/2013 REVIEWED BY: _____ DATE: _____