STATE OF OHIO DEPARTMENT OF TRANSPORTATION

CULVERT INSPECTION REPORT

CR-86 12-03

430842820									
CULVERT FILE NUMBER	CULVERT NUMBER <u>L</u>	LAK	SR 84	28.180		YEAR BUILT	99	199	_
		СО	ROUTE	SLM	ID				
DISTRICT 12 SHAPE 6 MAT		TERIAI		15		LENGTH	60		_
		. <u> </u>	JUST WEST OF DAYTON RD EAST OF Address 5973.						
LATITUDE 41.76852		I	LONGITUDE -81.0731						_
ENTRY CLASS A		N							_
CULVERT	_								
1. General		6	2. Culve	ert Alignmen	ıt				6
3. Shape			4. Seams or Joints						6
5. Slab			6. Abutments						
7. Headwalls		4	8. End Structure						
CHANNEL									
9. Channel Alignment		8	10. Protection						8
11. Culvert Waterway Blockage		8	12. Scour						6
APPROACHES		•							
13. Pavement		8	14. Guardrail 9						
15. Embankment		4							
		_	, 						
16. Level of Inspection		M	GENER	AL APPRAIS	SAL & OPI	ERATIONAL STATU	J S	6	A
RECOMMENDED REPA	IR CODE(S):								
COMMENTS:									
EMBANKMENT AND BE	FIRST 5' AT INLET FALLING GINNING TO AFFECT GUA PRMATION. INFILTRATION	ARDRA	IL. CMP	NOT UND	ER ROAD	BUT IS FAILING.		IT	
INSPECTED BY:	WG DATE: 1/12	2/2012	REVIE	EWED BY:		DATE	:		