Core Photo: X-001-0-23



Core Information					
Core	e Diameter (i	in):	3	.75	
Core	Total Length	(in):	1	17	
Layers	Core Composition & Thickness (in)			Remarks/ Condition	
	Asphalt	Concrete	Brick		
1	5.5			Good	
2		9		Good	
3	2.5			Not Recovered	
4					
Rebar Encountered	N/E				

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 6/28/2023 Taken By: LR

Core Photo: X-002-0-23



Core Information				
Core	e Diameter (i	n):	3.	75
Core	Total Length	(in):	2	13
Layers	Core Composition & Thickness (in)			Remarks/ Condition
	Asphalt	Concrete	Brick	0 011 01 01 01
1	3.5			Good
2		10.5		Poor
3		9		Good
4				
Rebar Encountered	N/E			

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 7/7/2023 Taken By: LR

Core Photo: X-003-0-23



Core Information				
Core	e Diameter (i	in):	3.	.75
Core	Total Length	(in):	20	0.5
Layers	Core Com	Core Composition & Thickness (in)		
	Asphalt	Concrete	Brick	Condition
1	2.75			Good
2		8.25		Good
3		9.5		Poor
4				
Rebar	1.0" form stake @ 17"			
Encountered		#2 rebar	@ 20.25"	

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 7/6/2023 Taken By: LR

Core Photo: X-004-0-23



Core Information					
Core	e Diameter (i	n):	3.	75	
Core	Total Length	(in):	1	6	
Layers	Core Composition & Thickness (in)			Remarks/ Condition	
	Asphalt	Concrete	Brick	0 011 01 01 01 1	
1	2.5			Good	
2		9		Good	
3	0.5			Good	
4	4			Good	
Rebar Encountered	N/E				

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 6/28/2023 Taken By: LR

Core Photo: X-005-0-23



Core Information				
Core	e Diameter (i	n):	3.	75
Core	Fotal Length	(in):	18	3.5
Layers	Core Comp	Core Composition & Thickness (in)		
	Asphalt	Concrete	Brick	
1	5			Good
2		9		Good
3	4.5			Fair
4				
Rebar Encountered	N/E			

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 6/27/2023 Taken By: LR

Core Photo: X-006-0-23



Core Information				
Core	e Diameter (i	n):	3.	75
Core	Total Length	(in):	2	1.5
Layers	Core Comp	Core Composition & Thickness (in)		
	Asphalt	Concrete	Brick	. Condition
1	3.25			Good
2		9.25		Good
3		9		Good
4				
Rebar Encountered	#2 rebar @ 16.75"			

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 7/7/2023
Taken By: LR

Core Photo: X-007-0-23



Core Information				
Core	e Diameter (i	n):	3.	75
Core	Fotal Length	(in):	2	1
Layers	Core Comp	Core Composition & Thickness (in)		
	Asphalt	Concrete	Brick	Condition
1	2.75		·	Good
2		9		Good
3	0.25		·	Good
4		9		Good
Rebar Encountered	#2 rebar @ 16"			

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 7/6/2023 Taken By: LR

Core Photo: X-008-0-23



Core Information					
Core	e Diameter (i	n):	3.	75	
Core	Fotal Length	(in):	1	.6	
Layers	Core Comp	Core Composition & Thickness (in)			
	Asphalt	Concrete	Brick	Condition	
1	3.5			Good	
2		9		Good	
3	3.5			Good	
4					
Rebar Encountered	N/E				

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 6/28/2023 Taken By: LR

Core Photo: X-009-0-23



Core Information					
Core	e Diameter (i	n):	3.	3.75	
Core	Fotal Length	(in):	1	.7	
Layers	Core Comp	Core Composition & Thickness (in)			
	Asphalt	Concrete	Brick		
1	3.75			Good	
2		8.75		Good	
3	1			Good	
4	3.5			Good	
Rebar Encountered	N/E				

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 6/27/2023 Taken By: LR

Core Photo: X-010-0-23



Core Information				
Core	e Diameter (i	n):	3.	75
Core	Fotal Length	(in):	2	22
Layers	Core Comp	Core Composition & Thickness (in)		
	Asphalt	Concrete	Brick	
1	3.5			Good
2		9.25		Good
3	0.25			Good
4		9		Good
Rebar Encountered	#2 rebar @ 17"			

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 7/10/2023 Taken By: LR

Core Photo: X-011-0-23



Core Information					
Core	e Diameter (i	in):	3.	75	
Core	Total Length	(in):	2	22	
Layers	Core Comp	Core Composition & Thickness (in)			
	Asphalt	Concrete	Brick	Condition	
1	4			Good	
2		9		Good	
3	0.25			Good	
4		8.75		Poor	
Rebar Encountered	N/E				

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 7/5/2023
Taken By: LR
Scale: N/A

Core Photo: X-012-0-23



Core Information					
Core	e Diameter (i	in):	3.	75	
Core	Fotal Length	(in):	1	7	
Layers	Core Composition & Thickness (in)			Remarks/ Condition	
	Asphalt	Concrete	Brick	Containin	
1	3			Poor	
2		10.75		Good	
3	3.25			Good	
4					
Rebar Encountered	N/E				

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 6/28/2023 Taken By: LR

Core Photo: X-013-0-23



Core Information					
Core Diameter (in): 3.75					
Core	Fotal Length	(in):	18	.25	
Layers	Core Composition & Thickness (in)			Remarks/ Condition	
	Asphalt	Concrete	Brick	0 011 01 01 01	
1	4			Good	
2		11.25		Good	
3	3			Fair	
4					
Rebar Encountered	N/E				

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 6/27/2023 Taken By: LR

Core Photo: X-014-0-23



Core Information					
Core	Core Diameter (in): 3.75				
Core	Total Length	(in):	21	.25	
Layers	Core Composition & Thickness (in)			Remarks/ Condition	
	Asphalt	Concrete	Brick		
1		12.25		Good	
2		9		Good	
3					
4					
Rebar Encountered	N/E				

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 7/11/2023 Taken By: LR

Core Photo: X-015-0-23



Core Information					
Core Diameter (in): 3.75					
Core	Total Length	(in):	1	8	
Layers	Core Composition & Thickness (in)			Remarks/ Condition	
	Asphalt	Concrete	Brick	0 011 011 011	
1	2.5			Good	
2		11.75		Good	
3	3.75			Good	
4					
Rebar Encountered	N/E				

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 6/30/2023 Taken By: LR

Core Photo: X-016-0-23



Core Information				
Core Diameter (in): 3.				75
Core	Fotal Length	(in):	1	2
Layers	Core Composition & Thickness (in)			Remarks/ Condition
	Asphalt	Concrete	Brick	
1	3.25			Good
2	5.5			Good
3	3.25			Good
4				
Rebar				
Encountered				

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 6/28/2023 Taken By: LR

Core Photo: X-017-0-23



Core Information					
Core Diameter (in): 3.75					
Core	Fotal Length	(in):	12	2.5	
Layers	Core Composition & Thickness (in)			Remarks/ Condition	
	Asphalt	Concrete	Brick		
1	7.5			Good	
2	2.5			Good	
3	2.5			Good	
4					
Rebar					
Encountered					

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949

NEAS Project No.: 23-0028

Date Cored: 6/27/2023 Taken By: LR

Core Photo: X-018-0-23



Core Information					
Core	Core Diameter (in):			.75	
Core	Total Length	(in):	1	18	
Layers	Core Composition & Thickness (in)			Remarks/ Condition	
	Asphalt	Concrete	Brick	0 011 01 01 01	
1	3.5			Good	
2	5			Poor	
3		9.5		Good	
4					
Rebar Encountered	#2 rebar @ 13"				

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 7/11/2023 Taken By: LR

Core Photo: X-019-0-23



Core Information					
Core Diameter (in): 3.75					
Core	Fotal Length	(in):	1	6	
Layers	Core Composition & Thickness (in)			Remarks/ Condition	
	Asphalt	Concrete	Brick		
1	1.75			Good	
2	5			Fair	
3	9.25			Good	
4					
Rebar					
Encountered					

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 6/30/2023 Taken By: LR

Core Photo: X-020-0-23



Core Information				
Core Diameter (in): 3.7				75
Core	Fotal Length	(in):	1	3
Layers	Core Composition & Thickness (in)			Remarks/ Condition
	Asphalt	Concrete	Brick	
1	6.5			Good
2	2			Good
3	4.5			Good
4				
Rebar				
Encountered				

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 6/29/2023 Taken By: LR

Core Photo: X-021-0-23



Core Information					
Core	.75				
Core	Fotal Length	(in):	1	12	
Layers	Core Composition & Thickness (in)			Remarks/ Condition	
	Asphalt	Concrete	Brick		
1	7			Good	
2	5			Poor	
3					
4					
Rebar					
Encountered					

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 6/26/2023 Taken By: LR

Core Photo: X-022-0-23



Core Information					
Core Diameter (in): 3.75					
Core	Fotal Length	(in):	1	8	
Layers	Core Composition & Thickness (in)			Remarks/ Condition	
	Asphalt	Concrete	Brick	Condition	
1	9			Poor	
2		9		Good	
3					
4					
Rebar Encountered	N/E				

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 7/12/2023 Taken By: LR

Core Photo: X-023-0-23



Core Information				
Core Diameter (in): 3.75				
Core	Fotal Length	(in):	17	.25
Layers	Core Composition & Thickness (in)			Remarks/ Condition
	Asphalt	Concrete	Brick	
1	8			Fair
2		9.25		Good
3				
4				
Rebar Encountered	#2 rebar @ 12.5"			

Pavement & Core Photo Log



Roadway Project

FRA-70-0.00 PID 116949 NEAS Project No.: 23-0028

Date Cored: 6/29/2023 Taken By: LR