



CONDUIT INVENTORY REPORT (CFN: 1841233)

Ohio Department Of Transportation Ellis Report

User: ahavenar

Date: 08/22/2023

CR-87 04-2022

1841233

CONDUIT FILE NUMBER

LOCATION AND ROUTE INFORMATION				
1. District		07	2. County	LOGAN
3. Route		SR 117	4. Straight line Mileage	58.186
5. Latitude		40.447822	6. Longitude	-83.806665
7. Status	A - Active	8. Installation Date	9. Special Designation	Mainline
10. Conduit Owner		S - State Department of Transportation	11. Maintenance Responsibility	S - State Department of Transportation
12. Entry Class		Class A (Non-Entry Inspection)	13. Feature Intersected	
CONDUIT				
14. Number of Cells		1	15. Broken Back	N
16. Conduit Shape		Circular	17. Conduit Material	Cast or Ductile Iron
18. Span (Inches)		36	19. Rise	
20. Length (Feet)		218	21. Metal Gauge Thickness	
22. Type of Pipe Protection		Fully Bituminous Coated	23. Skew (Degrees)	0
24. Centerline Span		36	25. Inlet End Treatment	None
26. Outlet End Treatment		None	27. Maximum Height of Cover (Feet)	3
28. Scour Critical		N	29. Height of Inlet Headwall (Feet)	3
30. Inlet Headwall to EOP Distance (Feet)		13	31. Height of Outlet Headwall (Feet)	
32. Outlet Headwall to EOP Distance (Feet)			33. Atmospheric or Physical Hazard	N
34. Abrasion Level		1	35. pH	

36. Modification Type	Section Repair	37. Year Modified	
-----------------------	----------------	-------------------	--

Inventory Comments

SHORT (36") CONCRETE BOX EXTENSION ON OUTLET RIGHT. 42' CAST UNDER ROADWAY. 12' LONG CMP EXTENSION LEFT UNDER PAVED SHOULDER TO RIGHT OF WAY. LAND OWNER EXTENDED FROM CMP WITH PLASTIC PIPE UNDER BUSINESS PARKING LOT LEFT.

Modification Comments