



(Photo Looking East)



(Photo Looking Southeast)



(Photo Looking West at Rear Abutment
and Underside of Superstructure)



Typical Steel Beam Condition



View of Typical Corrugated Metal Deck Condition



(Photo Looking West at Typical Diaphragm Condition)



(Photo Looking Southwest at Recent Steel Beam Repair)



Special Inspection Pre-Repair Image of Steel Beam End Section Loss



Existing Downstream Retaining Wall Along West Bank of Muddy Fork (Privately Owned)



(Photo Looking East)