



Deteriorating 78" Culvert in need of repair.



78" culvert is failing near outlet causing erosion under culvert and surrounding area.



Current flow in the 78" culvert is emptying through failed culvert floor and eroding headwall and surrounding area.



The 78" culvert is emptying through failed culvert floor and eroding the surrounding area.



The 78" culvert is emptying through failed culvert floor and eroding the surrounding area.



The 78" culvert is emptying through failed culvert floor and eroding the surrounding area.



The ground under the 18" culvert providing flow from the nearby catch basin has eroded causing the pipe to sink, preventing flow to the outlet.



Deteriorated roadway guardrails near the culverts are in need of repair/replacement.



Deteriorated roadway guardrail near the culverts



Failing catch basin that provides flow to the 18" culvert.