

West Approach under lower deck floor slab (SFN 1800930).
Crack Monitors installed on 05/17/07. Inspection completed on 08/29/07.



