

Element	Location	Spall Dimension	Additional Notes
North Electrical Utility Box	Sta. 25+00		Top cover of utility box is missing.
North Scuppers	Sta. 29+00		Scuppers are partially filled with debris and vegetation.
North Electrical Utility Boxes	Sta. 31+00		Top cover of utility boxes are missing, also filled with debris.
North Parapet	Sta. 32+00		Minor vehicular damage to parapet as well as sidewalk is evident.
North Parapet	Sta. 35+00	7"x3"	Spall has left exposed steel in parapet post.
North Parapet	Sta. 36+00	14"x7"x1"	Spall on top face of parapet rail.
North Parapet	Exp. Jt. 9	10"x12"	Delamination of parapet rails in two locations.
North Light Pole	Sta. 41+00		5' long by 1/4" wide crack on the south face of the light pole with exposed steel
North Parapet	Sta. 41+00	32"x9"x2"	Group of 5 spalls on south face of north parapet, Span 12 near Pier 1;
North Electrical Utility Boxes	Sta. 42+00		Multiple electrical utility boxes are missing covers and filled with debris
North Parapet	Sta. 43+60	13"x9"x1"	One spall and two delaminations present
North Electrical Utility Box	Sta. 43+00		Cover is broken leaving exposed wires.
North Electrical Utility Box	Near Joint 14		Cover is missing and box is filled with water, wires are exposed to sidewalk
North Sidewalks	Near Joint 12		Minor sidewalk deterioration with surface spalls up to 1".
North Sidewalks	Near Joint 13		Minor sidewalk deterioration with surface spalls up to 1".
North Sidewalks	Near Joint 10		Sidewalk cracking with efflorescence near scuppers and joint
North Sidewalks	Near Joint 8		Sidewalk cracking with efflorescence near scuppers and joint
Wearing Surface in Bike Lane	Near Joint 16		Cracks are present within the bounds of the bike lane.
Light Pole	Sta. 55+00	5"x1"x1/4"	2 separate 1/4" wide cracks approximately 4' long with minor spalls
South Sidewalks	Near Joint 15		Hairline cracks with efflorescence present on sidewalks.
South Sidewalks	Near Joint 14		Vegetation growth between sidewalk and parapet.
South Sidewalks	Near Joint 14		Hairline cracks with efflorescence present on sidewalks.
South Light Pole	Near Joint 14		Up to 1/2" wide crack in light pole up the north face with spall and exposed steel
South Parapet	Near Joint 13		Minor spall on underside of railing with 1/16" cracks.
South Light Pole	Near Joint 12		1/4" crack up the north face of the light pole.
South Parapet	Sta. 25+00	8"x1"x1"	Bottom railing exhibits hairline cracks and spall.
South Light Pole	Near Joint 4		Up to 1/4" vertical crack extends up the light pole.
South Wearing Surface of Curb Lane	Near Joint 5		Minor map cracking present.
South Sidewalks	Near Joint 5		Hairline cracks with efflorescence present near curb.
South Sidewalks	Sta. 33+00		Longitudinal hairline crack 30' long is present adjacent to curb with efflorescence
South Light Pole	Sta. 33+00		1/8" crack extending up the light pole.
South Light Pole	Sta. 34+00		8' tall by 6" wide spall in light pole with exposed steel.
South Sidewalks	Near Joint 9		10' long hairline crack with efflorescence is present near curb.
South Parapet	Sta. 39+00	3"x5"x1"	Minor spall on north face of railing.
South Sidewalks	Sta. 40+00		Longitudinal hairline cracks 25' long with efflorescence present
South Wearing Surface of Curb Lane	Sta. 40+00		Map cracking is present in the curb lane.
South Light Pole	Sta. 41+00		1/8" vertical crack extends up the light pole.
South Sidewalks	Near Joint 10		45' long hairline crack on the sidewalk is beginning to spall near scuppers
South Electrical Utility Box	Near Joint 10		Vegetation growth present.
South Light Pole	Sta. 44+27		3'x6" spall with exposed steel in light pole with associated 12' L by 1/4" W crack
South Wearing Surface in Bike Lane	Sta. 45+00		Worn down wearing surface in bike lane.
North Parapet	Sta. 22+19		1/16" vertical cracks present in rail posts.
North Parapet	Near Joint 1	8"x5"x4"	Minor spall in bottom rail at parapet joint.
North Parapet	Near Joint 1		Hairline cracks to bottom rail of parapet over a 25' section with rust staining
North Curb Lane	Sta. 27+00		Grooves in wearing surface of curb lane.
North Parapet	Near Joint 5		Minor pop out spalls and cracking on bottom railing of parapet
North Sidewalks	Sta. 29+00		Sidewalk exhibits minor spalls near scuppers.
North Parapet	Near Joint 6	10"x4"	Minor spalls and delaminations are present on the bottom railing of parapet