



P1: LOOKING NORTH IN SPAN #1 (SOUTH SPAN)

GEA-44-0135
SFN 2800152



P2: LOOKING EAST IN SPAN #1. NOTE 360 DEGREE REBAR EXPOSURE



P3: LOOKING NORTH AT MID-SPAN.



P5: TYPICAL EDGE SPALLING.



P4: LOOKING NORTH IN SPAN #3.



P6: Wearing surface viewed facing north from south end of deck.

GEA-44-0135
SFN 2800152



P9: FORWARD ABUTMENT UNDERMINED.



P10: FORWARD ABUTMENT SEAT LOSS UNDER NORTHWEST CORNER OF THE DECK.



P11: FORWARD ABUTMENT SEAT LOSS UNDER NORTHEAST CORNER OF THE DECK.



P12: REAR ABUTMENT UNDERMINED. A FEW AREAS OF THE UNDERMINING ARE STARTING TO GET BEHIND BACKWALL HERE.