## BRIDGE INSPECTION REPORT

2801744 **GEA 00422 0986 R** 1960 **BRIDGE NUMBER** YEAR BUILT Structure File Number 1 5 **LA DUE RES. 0.71 MI E 44** 12 322 DIST TYPE SERVICE Bridge Type out/out 41.3 Deck Area 9,085 sqft 2 INTEGRAL CONCRETE (MONOLITHIC) **DECK** 1 1 1 REINF CONCRT (PRESTRSD, PRECAST Thk 2 Wear Date 1/1/1994 1. FLOOR 2. WEARING SURFACE Left N NONE / Right N NONE 3. CURBS, SIDEWALKS AND WALKWAYS 4. MEDIAN C 32" DEFLECTOR-TYPE PARAPET (NJ SHAP 2 0 OTHER-NATURAL(OFF THE BRIDGE ENDS) 1 5. RAILING 6. DRAINAGE 3 7 3 COMPRESSION SEAL 7. EXPANSION JOINTS 8. SUMMARY **SUPERSTRUCTURE** 4 ROLLED STEEL 1 Max Spans 60 9. ALIGNMENT 10. BEAMS/GIRDERS/SLAB 2 11. DIAPHRAGMS or CROSSFRAMES 12. JOISTS/STRINGERS 13. FLOOR BEAMS 14. FIOOR BEAM CONNECTIONS 15. VERTICALS 16. DIAGONALS 17. END POSTS 18. UPPER CHORD 20. GUSSET PLATES 19. LOWER CHORD 21. LATERAL BRACING 22. SWAY BRACING 1 2 ROCKERS 23. PORTALS 24. BEARING DEVICES 25. ARCH 26. ARCH COLUMNS or HANGERS Paint Date 1/1/1987 7 5 PAINT SYSTEM OZEU 27. SPANDREL WALLS 28. PROTECTIVE COATING SYSTEM 1 29. PINS/HANGERS/HINGES 30. FATIGUE PRONE DETAIL (E, E') S 6 31. LIVE LOAD RESPONSE (E OR S) 32. SUMMARY **SUBSTRUCTURE** 6 STUB-CAPPED PILE (SINGLE ROW PILES) 2 6 STUB-CAPPED PILE (SINGLE ROW PILES) Abutment: ON PILING 33. ABUTMENTS 34. ABUTMENT SEATS **5 CAPPED COLUMN** 1 1 35. PIERS 36. PIER SEATS Piers: ON PILING 1 1 37. BACKWALLS 38. WINGWALLS Piers = 03 NN NN 1 Spans = 4 39. FENDERS and DOLPHINS 40. SCOUR (INSP TYPE - 1,2,3) 6 3 RIP RAP (DUMPED ROCK) 1 Dive Date 10/28/2009 42. SUMMARY 41. SLOPE PROTECTION **CULVERTS** N NONE/NOT APPLICABLE 43. GENERAL 44. ALIGNMENT 45. SHAPE 46. SEAMS Culvert Length 0 47. HEADWALLS or ENDWALLS 48. SCOUR (INSP TYPE - 1,2,3) 49. ABUTMENT 50. SUMMARY **CHANNEL** 1 1 2 STONE 51. ALIGNMENT 52. PROTECTION 6 (SEE CODING GUIDE) 8 1 53. HYDRAULIC OPENING 54. SUMMARY **APPROACHES** 1 2 2 BITUMINOUS 55. PAVEMENT 56. APPROACH SLABS 1 STEEL BEAM 2 57. GUARDRAIL 58. RELIEF JOINTS 1 6 Percent Legal = 150 60. SUMMARY 59. EMBANKMENT **GENERAL** 1 Maint Resp 1 OHIO TRAN DEPT 61. NAVIGATION LIGHTS 62. WARNING SIGNS Signs on = N MVC on = 9999.9 64. UTILITIES 63. SIGN SUPPORTS Under C = 0 Ν 6 Under NC = 0 66. GENERAL APPRAISAL & OPERATIONAL STATUS 65. VERTICAL CLEARANCE

Name

DATE 11/14/2013

PE Number

67. INSPECTED BY

Name KENNETH BANASZAK

SIGNED

DATE 12/23/2013

59487

PE Number

YOUSSEF SEIF

68. REVIEWED BY

SIGNED

Structure File Number 2801744 BRIDGE NUMBER GEA 00422 0986 R R ON/UNDER

DECK

FLOOR: A FEW TRANSVERSE CRACKS. AREAS OF MAP CRACKS.

FLOOR IS <1% DETERIORATED.

WS: CRACKS. WS IS <1% DETERIORATED.

RAILING: VERTICAL CRACKS. COLLISION SPALL AND

DELAMINATIONS ON LEFT RAIL. OTHER SHALLOW SPALLS.

DRAINAGE: DEBRIS WITH VEGETATION TO RIGHT BERM.

EXJTS: DECK SIDE OF REAR (WEST) JOINT IS 3/4" LOWER THEN THE APPROACH SLAB SIDE. FORWARD BACKWALL ARMOR IS GOUGED AND CRACKED WITH 6" OF MISSING ARMOR. EVIDENCE OF LEAKING SEALS, APPROX 32" OF SEAL POPPED AT FORWARD.

(DEBRIS ON BOTH ABUTMENT SEATS).

#### SUPERSTRUCTURE

BEAMS: RUSTED SECTION LOSS NEAR ABUTMENTS (MINOR TO OTHER AREAS).

XFRAMES: ENDFRAME RUSTED SECTION LOSS. CRACKS AND RUSTING THRU HOLES TO ENDFRAMES AT BOTH ABUTMENTS (BEAMS 1, 4 & 5 AT REAR AND BEAM 5 AT FORWARD).

BEARINGS: RUSTED SECTION LOSS.

PCS: FADED PAINT. 2% RUST. PCS IS 1-5% DETERIORATED.

FPD: WELDED MOMENT PLATES AT PIERS. MINOR PACK RUST IS

STARTING IN AREAS OF COVER PLATES.

### SUBSTRUCTURE

ABUTMENTS: LEACHING CRACKS. A FEW DELAMINATIONS. SPALLS WITH EXPOSED REBAR AT FORWARD LEFT. 2SF BY 3" DEEP SPALL AT REAR.

ABUTMENT SEATS: MINOR SPALLS AT BOTH.

PIERS: RUSTING SECTION LOSS OF STEEL AND SCALING OF CONCRETE AT WATERLINE.

BACKWALLS: MINOR CRACKS.

SCOUR: LAST DIVE INSPECTION IN 2009, DUE IN 2014.
SLOPE PORTECT: REAR-RIGHT ABUT CORNER HAS MINOR FOOTER

# CHANNEL

NOTE: WATER DEPTH BACK IN 2012 INSPECTION RANGED FROM 10.5' AT PIER #1 TO 12' AT PIER #3. TOP OF PIER CAPS TO WATER LINE IS 8.25'.

# APPROACHES

PAVEMENT: CRACKS. ASPHALT PATCHES.

SLABS: FULL WITCH CRACKS AT FORWARD. MINOR SPALLS AT TOP OF

BACKWALL. BOUNCE ONTO BRIDGE FROM WEST.

GUARDRAIL: MINOR COLLISION DAMAGE TO REAR-LEFT.