STATE OF OHIO DEPARTMENT OF TRANSPORTATION **BRIDGE INSPECTION FIELD REPORT**

Inventory Bridge Number: LAK 00002 11.410 Structure File Number: 4301110 Bridge Type: 3 - STEEL/2 - BEAM/2 - CONTINUOUS

Structure File Number, 4301110	mvent	огу Бі	nage i	Numb	ei. L	N 000	002 11.410 Blidg	e Type. 3-3	I CCL/2 - DI	=AIVI/2	<u> </u>	אוו ו אוי	0003	5
Sufficiency Rating: 69.6	Date Built: 7/1/19						1							
District: 12 Place Code (FIPS): MENTOR				HEI	NDRIC	KS RI	over HENDRICKS RD	rvice on: F	IIGHW	ΆΥ				
APPROACH ITEMS				ion state cr			SUBSTRUCTURE	ITEMS 1		condition state cr				
	QTY.	1	2	3	4	TR			QTY.	1	2	3	4	TR
c1. Approach Wearing Surface (EA)	2					2	c33. Abutment Walls (LF	·	70.8					1
c2. Approach Slabs (SF)	0					1	c34. Abutment Caps (LF)		0.0					
c3. Relief Joint (LF)							c35. Abut. Columns/Bents (EA)		0.0					
c4. Embankment (EA) d	4					1	c36. Pier Walls (LF)		0.0					
c5. Guardrail (EA)	0.0					1	c37. Pier Caps (LF)		106.2					1
N36. Safety Features: Tr, Gr, Tm					0\0		c38. Pier Columns/Bents	s (EA)	0.0					1
36)B <u>1</u> 36) c6. Approach Summary					6)D <u> </u>		c39. Backwalls (LF)		70.8					1
co. Approach Summary				(/			c40. Wingwalls (EA)		0.0					1
DECK ITEMS	071/		onditio			cr	c42. Scour (EA) d							
7.4.51(0).1.(05)	QTY.	1	2	3	4	TR	c43. Slope Protection (E	A) d	0.0					1
c7.1 Floor/Slab (SF)	8553.9					3	N60. Substructure Sumn	nary					(9-0)	7
c7.2 Edge of Floor/Slab (LF)		564 1						С	onditio	on stat	е	cr		
c8. Wearing Surface (SF)	6768					1	CULVERT ITEMS		QTY.	1	2	3	4	TR
c9. Curb/Sidewalk/Walkway (LF)	564.0					2	c44. General (LF)							
c10. Median (LF)							c45. Alignment (LF) d							
c11. Railing (LF)	564					1	c46. Shape (LF) d							
N36. Safety Features: Rail	36)A 1						, c47. Seams (LF) d							
c12. Drainage (EA) d	0.0					2	c48. Headwall/Endwall (l	F)						
c13. Expansion Joint (LF) d	0.0					2	c49. Scour (LF) d	,						
N58. Deck Summary					(9-0)	4	c50. Abutments (LF)							
			onditio	on stat	n state cr N62. Culvert Summary								(9-0)	N
SUPERSTRUCTURE ITEMS QTY. 1 2 3 4 TR							Noz. Culvert Summary						, ,	
c14. Alignment (EA) d	4					1	CHANNEL ITEMS	[OTV	C		on stat		cr
c15.1 Beams/Girders (LF)	0.0					2	c51. Alignment (LF) d		QTY.	П	2	3	4	TR
c15.2 Slab (SF)							c52. Protection (LF) d							
c16. Diaphragm/X-Frames (EA)	0.0					2	,							
c17. Stringers (LF)							c53. Hydraulic Opening (EA) d							$ldsymbol{ldsymbol{ldsymbol{eta}}}$
c18. Floorbeams (LF)							c54. Navigation Lights (EA) d							
c19. Truss Verticals (EA)							N61. Channel Summary	(9-0)				N		
c20. Truss Diagonals (EA)							 SIGN/UTILITY ITEN	IGN/UTILITY ITEMS condition state				е	cr	
c21. Truss Upper Chord (EA)									QTY.	1	2	3	4	TR
c22. Truss Lower Chord (EA)							c55. Signs (EA) d		0.0					1
c23. Truss Gusset Plate (EA) d							c56. Sign Supports (EA)							
c24. Lateral Bracing (EA)							c57. Utilities (LF) d	, ,						2
c25. Sway Bracing (EA)							General Appraisal						(9-0)	6
c26. Bearing Devices (EA) d	0.0					1	N41. Operating Status							Α
c27. Arch (LF)							Inspector Name	Sutak, Mike						
c28. Arch Column/Hanger (EA)							Inspection Date/Type	11/07/2018	Routine					
c29. Arch Spandrel Walls (LF)						 	PE Number							
c30. Prot. Coating System (LF) d	0.0					1	Reviewer Name	Seif, Youssef						
	0.0					<u> </u>	Review Date	12/20/2018						
c31. Pins/Hangers/Hinges (EA) d						l								

Inspection Date: 11/07/2018 Reviewed Date: 12/20/2018 Page

PE Number

59487

N59. Superstructure Summary

c32. Fatigue (LF) d

STATE OF OHIO DEPARTMENT OF TRANSPORTATION BRIDGE INSPECTION FIELD REPORT

Structure File Number: 4301110 Inventory Bridge Number: LAK 00002 11.410 Bridge Type: 3 - STEEL/2 - BEAM/2 - CONTINUOUS

Sufficiency Rating: 69.6 Date Built: 7/1/1961

District: 12 Place Code (FIPS): MENTOR HENDRICKS RD over HENDRICKS RD Type of Service on: HIGHWAY

Key: "Qty" = Quantity for Element Level inspection; "(LF)" = Linear Feet; "(SF)" = Square Feet; "(EA)" = Each or count; "CR" = 1-4 Condition Rating or average of worst span unless Summary item 9-0, then the average of entire bridge influenced by the bold boxes; "TR" = Transition Rating or weighted average of condition states; "d" = dedicated or specific chart and guidance, all others use Material specific chart/guidance; "c" = condition prefix; "N" = NBIS rating

Inspection Procedures

Comments

APPROACH

c1. Approach Wearing Surface

CRACKS ALONG REAR EXJT HEADER. ASPHALT PATCHES, CRACKS & MINOR BREAK UP ALONG FORWARD APPROACH SLAB.

c2. Approach Slabs

FULL LENGTH CRACK TO FORWARD AS WIDE AS 1/4". OTHER CRACKS.

c5. Guardrail

MINOR COLLISION DAMAGE TO FORWARD-LEFT.

DECK

c7.1 Floor/Slab

FLOOR HAS BEEN SUBDECKED. TRANSVERSE LEACHED CRACKS (MANY CRACKS HAVE MOTTLED AREAS). APPROX 200 SF OF SPALLS & 45 SF OF DELAMS. 1 FULL DEPTH REPAIR IN BAY 1. FLOOR IS 15-20% DETERIORATED.

c8. Wearing Surface

CRACKS. MAP CRACKING THRU OUT. DELAMINATONS. WS IS <1% DETERIORATED.

c9. Curb/Sidewalk/Walkway

CRACKS. SCALING. DELAMS. MINOR SPALLS.

c11. Railing

A FEW DETERIORATED NUTS TO POSTS OF TUBE RAIL. NOTE: STAINLESS STEEL ANGLES BOLTED TO TOPS OF PARAPET WALL WITH FENCE FABRIC ATTACHED.

c12. Drainage

HEAVY RUSTING SECTION LOSS WITH AREAS OF THE CURB LEG OF THE BULB ANGLE DETACHED FROM BOTH WALKS, APPROX MID SPAN. DEBRIS IN BULB ANGLE.

c13. Expansion Joint

A FEW GOUGES. SOME BREAKING UP TO REAR HEADER. RUST SECTION LOSS WITH HOLES IN JOINT ARMOR AT BOTH ENDS.

Inspection Date: 11/07/2018 Page 2 Reviewed Date: 12/20/2018

STATE OF OHIO DEPARTMENT OF TRANSPORTATION BRIDGE INSPECTION FIELD REPORT

Structure File Number: 4301110 Inventory Bridge Number: LAK 00002 11.410 Bridge Type: 3 - STEEL/2 - BEAM/2 - CONTINUOUS

Sufficiency Rating: 69.6 Date Built: 7/1/1961

District: 12 Place Code (FIPS): MENTOR HENDRICKS RD over HENDRICKS RD Type of Service on: HIGHWAY

SUPERSTRUCTURE

c15.1 Beams/Girders

RUSTING SECTION LOSS, MOSTLY AT ABUTMENTS. SCRAPE IN LOWER FLANGE OF LEFT FASCIA OVER EB LANE #2 & 1/2" DEEP GOUGE OVER EB LANE #3. SCRAPES & SMALL GOUGES TO LEFT FASCIA OVER WB LANE #2.

c16. Diaphragm/Cross Frames

ENDFRAME RUSTING SECTION LOSS. DAMAGE TO REAR ENDFRAME #2.

c26. Bearing Devices

RUSTING SECTION LOSS.

c30. Protective Coating System

1-5% RUST (AREAS REACATIVATING). FADING. PAINT RUNS. PCS IS 1-5% DETERIORATED.

c32. Fatigue

WELDED COVER PLATES AT PIERS.

SUBSTRUCTURE

c33. Abutment Walls

A FEW CRACKS.

c38. Pier Columns/Bents

P3C1=2 SF DELAMINATION. NBIS QAR 2018 12-13.

c39. Backwalls

CRACKS. A FEW SPALLS.

Inspection Date: 11/07/2018 Page 3 Reviewed Date: 12/20/2018