STATE OF OHIO DEPARTMENT OF TRANSPORTATION CULVERT INVENTORY REPORT

CULVERT FILE NUMBER

1814183

Directions: Right click and use Text or Number Filters. Use copy and paste or enter manually. Can filter on any of the fields.

LOCATION AND ROUTE INFORMATION

1. District	12	2. County	GEAUGA		
3. Route	00700	4. Straight Line Mileage	1.719		
5. Latitude	41.37216	6. Longitude	-81.14314		
7. Special Designation	M	8. Culvert Owner	S		
9. Maintenance Responsibility	S	10. Entry Class A 11. Status	A		
12. Feature Intersection	Ditch				
CULVERT					
13. Installation Date		14. Number of Cells	1		
15. Broken Back	N	16. Culvert Shape	8		
17. Culvert Material	15	18. Span (Inches)	36		
19. Rise (Inches)	36	20. Length (Feet)	35		
21. Metal Gauge Thickness 1		22. Metal Gauge Thickness 2			
23. Type of Pipe Protection	1	24. Slope of Pipe (Percent)	1.1		
25. Slope Direction		26. Skew (Degrees)	0		
27. Skew Direction		28. Inlet End Treatment	1		
29. Outlet End Treatment	1	30. Maximum Height of Cover (Feet)	2		
31. Height of Inlet Headwall (Feet)	4	32. Inlet Headwall to EOP Distance (Feet)	5		
33. Height of Outlet Headwall (Feet)	5	34. Outlet Headwall to EOP Distance (Feet)	5		
35. Drainage Area (Acres)	0	36. Drainage Discharge (CFS)	0		
37. Abrasive Conditions	N	38. Abrasion Level	1		
39. pH	7.6	40. Channel Protection (Inlet)	G		
41. Channel Protection (Outlet)	G				
INVENTORY MODIFICATIONS					
42. Modification Type		43. Year Modified			
44. Modification Material		45. Modification Size (Inches)	0		
46. Inlet Extension Year		47. Inlet Extension Shape			
48. Inlet Extension Material		49. Inlet Extension Span (Inches)	0		
50. Inlet Extension Rise (Inches)	0	51. Metal Inlet Gauge Thickness 1			
52. Metal Inlet Gauge Thickness 2		53. Inlet Extension Length (Feet)	0		
4. Outlet Extension Year		55. Outlet Extension Shape			
56. Outlet Extension Material		57. Outlet Extension Span (Inches)	0		
58. Outlet Extension Rise (Inches)	0	59. Metal Outlet Gauge Thickness 1			
60. Metal Outlet Gauge Thickness 2		61. Outlet Extension Length (Feet)			
COMMENTS SEE GEA-700-0.00 S	SHEETS 6/8 AND 8/8	Inspect Every-Five Years			
INVENTORIED BY: LM		DATE: 2016-02-10 00:00:00.00000			

INVENTORIED BY: LM DATE: 2016-02-10 00:00:00.00000

Inventory Attachments (click on hyperli

STATE OF OHIO DEPARTMENT OF TRANSPORTATION CULVERT INSPECTION REPORT

CULVERT FILE	E NUMBER	County	Route	SLM	District	The lowest highlighted field value controls			
1814183		GEA	00700	1.719	12	the General Apprasial for the Asset.			
CULVERT									
1. Level of Inspection		X	2	2. Material	4				
3. Culvert Alignment		4		4. Shape					
5. Seams or Joints		4		6. Slab	6				
7. Abutments					8. Headwalls *	7			
9. End Structure									
CHANNEL									
10. Channel Alignment		5		11. Protection	6				
12. Culvert Waterway Blockage		8		13. Scour **	6				
APPROACHES									
14. Pavement		5		15. Guardrail					
16. Embankment		6							
GENERAL APPRASIAL AND OPERATIONAL STATUS 4 A									
*Is Headwall critial to the asset? Yes Lowest Critical Rating (not including Headwall or Scour)									
**May control the rating if determined by the inspector. These items should not govern the GA if they are not determined to be critical upon the judgment of the inspector.									
COMMENTS	Dip/settlement in pavement-SB lane right wheel track. The floor/bottom of the box has abraded completely from outlet to half way into the box. 2" differential movement (drop of stones), at the outlet has caused a minimum drop in the roof stone resulting in the dip in the pavement. 2' deep scour at outlet. Minor embankment erosion-repairs performed at inlet embankment. Meandered upstream channel pointing at unprotected embankment. Open joints between stones with infiltration. Voids behind sidewalls and outlet headwall.								
INSPECTED BY	Y: MB]	DATE: 202	0-01-14			
$\underline{https://collectornew.dot.state.oh.us/arcgis/rest/services/CULVERTS/Culvert_Inventory_Viewer/MapServer/7/2621627/attachments}$									
Inventory Attachments (click on hyperli									

Exit

Print Inventory and Inspection