

STATE OF OHIO DEPARTMENT OF TRANSPORTATION

CULVERT INVENTORY REPORT

CR-87 12-03

287000763

CULVERT FILE NUMBER		1. Entry Class	A
LOCATION AND ROUTE INFORMATION			
2. District	12	3. County	GEA
4. Route	SR 700	5. Straight Line Mileage	7.608
6. Latitude	41.45611	7. Longitude	-81.13598
8. Road ID		9. Maintenance Responsibility	S
10. Feature Intersection	NONE		
CULVERT			
11. Year Built		12. Number of Cells	1
13. Shape	7	14. Material	1
15. Span (in.)	96	16. Rise (in.)	24
17. Length (ft.)	44	18. Gage (no.) / Wall Thickness (in.)	
19. Gage (no.) / Wall Thickness (in.)		20. Type of Protection	1
21. Slope of Pipe (%)		22. Skew (degrees)	
23. Inlet End Treatment	1	24. Outlet End Treatment	1
25. Maximum Height of Cover (ft.)		26. Modification Type	
27. Year Modified	9999	28. Modification Material	
29. Modification Size (in.)			
EXTENSION - INLET			
30. Year Extended		31. Shape	
32. Material		33. Span (in.)	
34. Rise (in.)		35. Gage (no.) / Wall Thickness (in.)	
36. Extension Length			
EXTENSION - OUTLET			
37. Year Extended		38. Shape	
39. Material		40. Span (in.)	
41. Rise (in.)		42. Gage (no.) / Wall Thickness (in.)	
43. Extension Length (ft.)			
HYDROLOGY / HYDRAULICS			
44. Drainage Area (acres)		45. Design Discharge (c.f.s.)	
46. Abrasive Conditions	N	47. pH	6.6
48. Channel Protection (Inlet)		49. Channel Protection (Outlet)	

COMMENTS:

GUARDRAIL NEEDED AT ENDS. The slab has exposed rebar and is spalling The headwalls has exposed rebar and is spalling. Inspect Every-Five Years

INVENTORIED BY: WE DATE: 2/4/2016