## STATE OF OHIO DEPARTMENT OF TRANSPORTATION CULVERT INVENTORY REPORT

## CULVERT FILE NUMBER

1862411

Directions: Right click and use Text or Number Filters. Use copy and paste or enter manually. Can filter on any of the fields.

LOCATION AND ROUTE INFORMATION							
1. District	12	2. County	GEAUGA				
3. Route	00086	4. Straight Line Mileage	0.376				
5. Latitude	41.65262	6. Longitude	-81.09556				
7. Special Designation	М	8. Culvert Owner	S				
9. Maintenance Responsibility	S	10. Entry Class A 11. Status	А				
12. Feature Intersection	DRAINAGE DITCH						
CULVERT							
13. Installation Date		14. Number of Cells	1				
15. Broken Back	N	16. Culvert Shape	7				
17. Culvert Material	1	18. Span (Inches)	30				
19. Rise (Inches)	20	20. Length (Feet)	28				
21. Metal Gauge Thickness 1		22. Metal Gauge Thickness 2					
23. Type of Pipe Protection	1	24. Slope of Pipe (Percent)					
25. Slope Direction		26. Skew (Degrees)	0				
27. Skew Direction		28. Inlet End Treatment	7				
29. Outlet End Treatment	1	30. Maximum Height of Cover (Feet)	1				
31. Height of Inlet Headwall (Feet)		32. Inlet Headwall to EOP Distance (Feet)					
33. Height of Outlet Headwall (Feet)	3	34. Outlet Headwall to EOP Distance (Feet)	7				
35. Drainage Area (Acres)		36. Drainage Discharge (CFS)					
37. Abrasive Conditions	Y	38. Abrasion Level	2				
39. pH		40. Channel Protection (Inlet)	Ν				
41. Channel Protection (Outlet)	N						
INVENTORY MODIFICATIONS							
42. Modification Type		43. Year Modified					
44. Modification Material		45. Modification Size (Inches)					
46. Inlet Extension Year		47. Inlet Extension Shape					
48. Inlet Extension Material		49. Inlet Extension Span (Inches)					
50. Inlet Extension Rise (Inches)		51. Metal Inlet Gauge Thickness 1					
52. Metal Inlet Gauge Thickness 2		53. Inlet Extension Length (Feet)					
54. Outlet Extension Year		55. Outlet Extension Shape					
56. Outlet Extension Material		57. Outlet Extension Span (Inches)					
58. Outlet Extension Rise (Inches)		59. Metal Outlet Gauge Thickness 1					
60. Metal Outlet Gauge Thickness 2		61. Outlet Extension Length (Feet)					
COMMENTS Concrete cap is spalling at outlet abutment. Headwall at inlet is under snow this date.Concrete cap is spalling at outlet abutment. Headwall at inlet is under snow this date.							
INVENTORIED BY: NW		DATE: 2005-06-01 00:00:00.00000					

https://collectornew.dot.state.oh.us/arcgis/rest/services/CULVERTS/Culvert\_Inventory\_Viewer/MapServer/0/1862411/attachments

## Inventory Attachments (click on hyperli

## STATE OF OHIO DEPARTMENT OF TRANSPORTATION CULVERT INSPECTION REPORT

CULVERT FILE NUMBER County	Route	SLM	District	The lowest highlighted field value controls		
1862411 GEA	00086	0.376	12	the General Apprasial for the Asset.		
CULVERT						
1. Level of Inspection	Х	2.	Material	4		
3. Culvert Alignment	6 4. Shape					
5. Seams or Joints	6 6. Slab					
7. Abutments		8. Headwalls *				
9. End Structure	8					
CHANNEL						
10. Channel Alignment	8	11	. Protection	4		
12. Culvert Waterway Blockage	8	13	3. Scour **	4		
APPROACHES						
14. Pavement	8	15	5. Guardrail			
16. Embankment	6					
GENERAL APPRASIAL AND OPERATIONAL STATUS 4 A						
*Is Headwall critial to the asset? No Lowest Critical Rating (not including 4 Headwall or Scour)						
**May control the rating if determined by the inspector. These items should not govern the GA if they are not determined to be critical upon the judgment of the inspector.						
COMMENTS 3'x5'x3" deep spall under the northbound lane. Remaining concrete behind spall is soft and punky-rusted rebar is exposed over entire spalled area. Remaining portion of ceiling under northbound lane, closer to outlet, delaminates with efflorescence-lose. 2' deep scour at outlet end. Minor embankment erosion around outlet headwall.						
INSPECTED BY: MB		D	ATE: 2020-0	1-06		
https://collectornew.dot.state.oh.us/arcgis/rest/services/CULVERTS/Culvert_Inventory_Viewer/MapServer/7/2602584/attachments						
Inventory Attachments (click on hyperli						
Print Inventory and Inspection			Exit			