

STATE OF OHIO DEPARTMENT OF TRANSPORTATION

CULVERT INVENTORY REPORT

CR-87 12-03

430842718

CULVERT FILE NUMBER		1. Entry Class	A
LOCATION AND ROUTE INFORMATION			
2. District	12	3. County	LAK
4. Route	SR 84	5. Straight Line Mileage	27.090
6. Latitude	41.76327	7. Longitude	-81.09287
8. Road ID		9. Maintenance Responsibility	S
10. Feature Intersection	Wood Rd		
CULVERT			
11. Year Built		12. Number of Cells	1
13. Shape	7	14. Material	15
15. Span (in.)	53	16. Rise (in.)	102
17. Length (ft.)	60	18. Gage (no.) / Wall Thickness (in.)	
19. Gage (no.) / Wall Thickness (in.)		20. Type of Protection	1
21. Slope of Pipe (%)		22. Skew (degrees)	
23. Inlet End Treatment	4	24. Outlet End Treatment	4
25. Maximum Height of Cover (ft.)	4	26. Modification Type	
27. Year Modified		28. Modification Material	1
29. Modification Size (in.)			
EXTENSION - INLET			
30. Year Extended		31. Shape	
32. Material		33. Span (in.)	
34. Rise (in.)		35. Gage (no.) / Wall Thickness (in.)	
36. Extension Length			
EXTENSION - OUTLET			
37. Year Extended		38. Shape	
39. Material		40. Span (in.)	
41. Rise (in.)		42. Gage (no.) / Wall Thickness (in.)	
43. Extension Length (ft.)			
HYDROLOGY / HYDRAULICS			
44. Drainage Area (acres)		45. Design Discharge (c.f.s.)	
46. Abrasive Conditions	Y	47. pH	6.8
48. Channel Protection (Inlet)	N	49. Channel Protection (Outlet)	N

COMMENTS:

Culvert is located on the east side of Wood Road.

INVENTORIED BY: _____ WG _____ DATE: 2/4/2016