STATE OF OHIO DEPARTMENT OF TRANSPORTATION CULVERT INVENTORY REPORT

CULVERT FILE NUMBER

1802284

Directions: Right click and use Text or Number Filters. Use copy and paste or enter manually. Can filter on any of the fields.

LOCATION AND ROUTE INFORMATION

1. District	12	2. County LAKE			
3. Route	00608	4. Straight Line Mileage	3.098		
5. Latitude	41.67288	6. Longitude	-81.21628		
7. Special Designation	M	8. Culvert Owner	S		
9. Maintenance Responsibility	S	10. Entry Class A 11. Status	A		
12. Feature Intersection	ALEXANDER RD.				
CULVERT					
13. Installation Date		14. Number of Cells	1		
15. Broken Back	N	16. Culvert Shape	7		
17. Culvert Material	15	18. Span (Inches)	36		
19. Rise (Inches)	36	20. Length (Feet)	48		
21. Metal Gauge Thickness 1	_	22. Metal Gauge Thickness 2			
23. Type of Pipe Protection	1	24. Slope of Pipe (Percent)			
25. Slope Direction		26. Skew (Degrees)	0		
27. Skew Direction		28. Inlet End Treatment	NN		
29. Outlet End Treatment	7	30. Maximum Height of Cover (Feet)	4		
31. Height of Inlet Headwall (Feet)		32. Inlet Headwall to EOP Distance (Feet)			
33. Height of Outlet Headwall (Feet)		34. Outlet Headwall to EOP Distance (Feet)			
35. Drainage Area (Acres)		36. Drainage Discharge (CFS)			
37. Abrasive Conditions	N	38. Abrasion Level	1		
39. pH		40. Channel Protection (Inlet)			
41. Channel Protection (Outlet)	X				
INVENTORY MODIFICATIONS					
42. Modification Type		43. Year Modified			
44. Modification Material		45. Modification Size (Inches)			
46. Inlet Extension Year		47. Inlet Extension Shape	1		
48. Inlet Extension Material	13	49. Inlet Extension Span (Inches)	18		
50. Inlet Extension Rise (Inches)	18	51. Metal Inlet Gauge Thickness 1			
52. Metal Inlet Gauge Thickness 2		53. Inlet Extension Length (Feet)			
54. Outlet Extension Year		55. Outlet Extension Shape	1		
56. Outlet Extension Material	5	57. Outlet Extension Span (Inches)	18		
58. Outlet Extension Rise (Inches)	18	59. Metal Outlet Gauge Thickness 1			
60. Metal Outlet Gauge Thickness 2		61. Outlet Extension Length (Feet)			
COMMENTS					

INVENTORIED BY: WS DATE: 2005-05-20 00:00:00.00000

Inventory Attachments (click on hyperli

STATE OF OHIO DEPARTMENT OF TRANSPORTATION CULVERT INSPECTION REPORT

CULVERT FILE NUMBER County	Route	SLM D		The lowest highlighted field value controls the General Apprasial for the Asset.			
1802284 LAK	00608	3.098	12				
CULVERT							
1. Level of Inspection X		2. Mater	ial	5			
3. Culvert Alignment 6		4. Shape					
5. Seams or Joints 5		6. Slab		4			
7. Abutments	tments		8. Headwalls *				
9. End Structure	6						
CHANNEL							
10. Channel Alignment 8		11. Prote	ection	8			
12. Culvert Waterway Blockage	8	13. Scou	r **	8			
APPROACHES							
14. Pavement	6	6 15. Guardrail					
16. Embankment	8						
GENERAL APPRASIAL AND OPERATIONAL STATUS 4 A							
*Is Headwall critial to the asset? No Lowest Critical Rating (not including Headwall or Scour) 4							
**May control the rating if determined by the inspector. These items should not govern the GA if they are not determined to be critical upon the judgment of the inspector.							
COMMENTS Cracks in roof slab near obstructing the opening				ion. Rock and debris in box culvert noles and settlement.			
INSPECTED BY: MB		DATE:	2020-01-28				
https://collectornew.dot.state.oh.us/arcgis/rest/services/CULVERTS/Culvert_Inventory_Viewer/MapServer/7/2642413/attachments Inventory Attachments (click on hyperli							

Exit

Print Inventory and Inspection