

# Ohio Bridge Inspection Summary Report

**LAK-00090-1051 (4304209)**

2: District 12 40670 - KIRTLAND HILLS (LAK county)  
 21: Major Maint A/B 01 - State Highway Agency /  
 225 Routine Main A/B 01 - State Highway Agency /  
 221 Inspection A/B 01 - State Highway Agency /  
 220: Inv. Location DISTRICT 12

5A: Inventory Route 1 M0503  
 7: Facility On HART RD  
 6: Feature Ints I-90  
 9: Location 1.2 MI E SR615  
 Lat, Lon 41.647878 , -81.320339

## Condition

**58: Deck** **7 - Good Condition**  
 58.01 Wearing Surface 7 - Good (1% distress)  
 58.02 Joint 6- Satisfactory (isolated leaking)  
**59: Superstructure** **7 - Good Condition**  
 59.01 Paint & PCS 6 - Satisfactory (5-10% corr.)  
**60: Substructure** **7 - Good Condition**  
**61: Channel** **N**  
**61.01 Scour** **N - Not Applicable**  
**62: Culverts** **N - Not Applicable**

**67.01 GA** **7**

## Appraisal

Sufficiency Rating 76.4 SD/FO 0 - ND  
 36: Rail, Tr, Gd, Term Std 1 1 1 1  
 72: Approach Alignment 8 - Equal to present desirable criteria  
 113: Scour Critical N - Not over waterway  
 71: Waterway Adequacy N - Not Applicable

## Geometric

48: Max Span Length (ft) 71.0  
 49: Structure Length (ft) 388.0  
 52: Deck Width, Out-To-Out (ft) 30.8  
 424: Deck Area (sf) 11950.4  
 32: Appr Roadway Width (ft) 24.0  
 51: Road Width, Curb-Curb (ft) 24.0  
 50A: Curb/SW Width: Left (ft) 2.1  
 50A: Curb/SW Width: Right (ft) 2.1  
 34: Skew (deg) 2  
 33: Bridge Median 0 - No median  
 54B: Min Vert Underclearance (ft) 16.34  
 336A: Min Vert Clrnce IR Cardinal (ft) 99  
 336B: Min V Clr IR Non-Cardinal (ft) 0  
 578: Culvert Length (ft) 0

## Load Posting

41: Op/Post/Closed A - Open  
 70: Posting 5 - Equal to or above legal loads  
 70.01: Date  
 70.02: Sign Type  
 734: Percent Legal (%) 105  
 704: Analysis Date 09/11/2019  
 63: Analysis Method 6 - Load Factor (LF) rating reported by rating factor (RF) method using MS18 loading.

## Structure Type

43: Bridge Type 4 - Steel continuous  
 02 - Stringer/Multi-beam or Girder  
 N- Not Applicable  
 45: Spans Main / Approach 6 / 0  
 107: Deck Type 1 - Concrete Cast-in-Place  
 408: Composite Deck N - Non-composite Construction  
 414A Joint Type 1 2 - Sliding Metal Plate Angle  
 414B: Joint Type 2 N - None  
 108A: Wearing Surface 1 - Monolithic Concrete (concurrently placed with structural deck)  
 N- Not Applicable  
 422: WS Date 06/25/2009  
 423: WS Thick (in) 1.2  
 482: Protective Coating 5 - Paint System OZEU  
 483: PCS Date 10/21/2001  
 453: Bearing Type 1 2 - Rockers & Bolsters  
 455: Bearing Type 2 N - None  
 528: Foundn: Abut Fwd 1 - Steel H Piles (Other size)  
 533: Foundn: Abut Rear 1 - Steel H Piles (Other Size)  
 536: Foundn: Pier 1 1 - Steel H Piles (Other size)  
 539: Foundn: Pier 2 1 - Steel H Piles (Other size)

## Age and Service

27: Year Built/ 106 Rehab 1962 / 0000  
 42A: Service On 1 - Highway  
 42B: Service Under 1 - Highway, with or w/out pedestrian  
 28A: Lanes on 02  
 28B: Lanes Under 04  
 19: Bypass Length 2  
 29: ADT 1433  
 109: % Trucks (%) 7

## Inspections

		Months	
90: Routine Insp.		24	08/19/2021
92A: FCM Insp.	N	0	
92B: Dive Insp.	N	0	
92C: Special Insp.	N	0	
92D: UBIT Insp.	N		
92E: Drone Insp.			

Inspector Gerstenslager, Michael

Inspector: Michael Gerstenslager

Structure Number: 4304209

Inspection Date: 08/19/2021

Facility Carried: HART RD

**Bridge Inspection Report**

**Element Inspection**

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
<b>12 - Reinforced Concrete Deck</b>	3 - Mod.	11931	sq. ft.	9551	2225	155	0
	CS2- Cracks, some leaching and rust stained. Some honeycombed areas. Epoxy injected areas.						
	CS3- Spalls, some with exposed rebar. Delams.						
805 - Wearing Surface - Monolithic Concrete		9312	sq. ft.	6767	2540	5	0
	CS2- Cracks, mostly transverse cracks. Minor delams.						
	CS3- Shallow spalls and asphalt patches.						
<b>107 - Steel Open Girder/Beam</b>	3 - Mod.	1552	ft.	1525	25	2	0
	CS2- Rusted section loss at abutments.						
	CS3- Collision damage to right fascia over EB right berm.						
515 - Steel Protective Coating		13596	sq. ft.	11511	1550	500	35
	CS2- Surface rust						
	CS3- Heavier rust, start of peeling						
	CS4- Isolated spot of bare rusted metal.						
<b>205 - Reinforced Concrete Column</b>	3 - Mod.	15	each	13	1	1	0
	CS2- P1C3- 4 SF delam						
	CS3- P5C1- 6 SF spall with exposed rebar with section loss, 2 SF delam						
<b>215 - Reinforced Concrete Abutment</b>	3 - Mod.	62	ft.	47	15	0	0
	CS2- Cracks, some with rust stains.						
<b>234 - Reinforced Concrete Pier Cap</b>	3 - Mod.	155	ft.	141	11	3	0
	CS2- Minor cracks, some rust stains.						
	CS3- Spall to P1 with exposed rebar. Spall to P2						
<b>303 - Assembly Joint with Seal</b>	3 - Mod.	62	ft.	0	21	28	13
	Note: Open joints in safety curbs.						
	CS2- Debris in joint						
	CS3- Rusting section loss to armor. A few gouges. End dam at forward and rear bay #2 is slightly banging under live traffic.						
	CS4- Rusted thru holes to both joint. Evidence of leaking FWD and rear Bays 1,2,3						
<b>311 - Movable Bearing</b>	3 - Mod.	20	each	12	8	0	0
	CS2- Abutment bearing have rust						
<b>313 - Fixed Bearing</b>	3 - Mod.	4	each	4	0	0	0

Inspector: Michael Gerstenslager

Structure Number: 4304209

Inspection Date: 08/19/2021

Facility Carried: HART RD

**Bridge Inspection Report**

**Element Inspection**

<b>321 - Reinforced Concrete Approach Slab</b>	3 - Mod.	1200	sq. ft.	550	650	0	0
CS2- Large areas of map cracks, Some with rust stains.							
<b>331 - Reinforced Concrete Bridge Railing</b>	3 - Mod.	776	ft.	626	150	0	0
CS2- Cracks, some leaching. Minor scaling to left rail. A few aluminum post anchor nuts are missing.							
<b>815 - Drainage</b>	3 - Mod.	12	each	4	8	0	0
CS2- 8 Scuppers are partially plugged.							
<b>830 - Abutment Backwall</b>	3 - Mod.	62	ft.	43	10	9	0
CS2- Cracks, some leaching. Rust stains. CS3- Spalls and delams							

ODOT District: 12

## LAK-00090-1051\_(4304209)

Date Built: 07/01/1962

Major Maint: 01 - State Highway Agency

Facility Carried: HART RD

Traffic On: 1 - Highway

Rehab Date:

Routine Maint: 01 - State Highway Agency

Feature Inters: I-90

Traffic Under: 1 - Highway, with or w/out pedestrian

Insp: 01 - State Highway Agency

FIPS Code: 40670 - KIRTLAND HILLS (LAK county)

Location: DISTRICT 12

1.2 MI E SR615

Resp A:

Insp

Resp B:

Inspector

Gerstenslager, Michael

Inspection Date 08/19/2021

Reviewer Seif, Youssef

### Inspector Comments - Deck and Approach

#### Deck

##### Floor/Slab (SF)

SOT. EB #2 Bays 2 and 3. WB #2 bay 1

##### Edge of Floor/Slab (LF)

A few cracks, some rust stains.

##### Curbs/Sidewalk (LF)

Cracks, minor spalls and delams.

#### Approach

##### Approach Wearing Surface (EA)

Sealed cracks.

##### Approach Guardrail (EA)

Minor collision damage to rear left. Broken aluminum post to forward-right. Post rot.

##### Signs (EA)

No bridge end markers.

### Inspector Comments - General Appraisal

#### Superstructure

##### Diaphragm/X-Frames (EA)

Endframe rusted section loss. Bent horizontal endframe angle in rear bay 1. Crack to endframe weld in forward bay 1. Nearly rust severed horizontal end frame angle at rear in bay 3.

##### Fatigue (LF)

Welded moment plates at piers.

#### Substructure

##### Wingwalls (EA)

Spall to forward-left wingwall.

#### Culvert

**Inspector Comments - Waterway**

**Waterway Adequacy**

**Channel**

**Scour Critical**

**Inspector:** Michael Gerstenslager

**Structure Number:** 4304209

**Inspection Date:** 08/19/2021

**Facility Carried:** HART RD

**Bridge Inspection Report**

**Pictures**