

## STATE OF OHIO DEPARTMENT OF TRANSPORTATION

**CULVERT INVENTORY REPORT**

CR-86 12-03

**280430040**

CULVERT FILE NUMBER

1. Entry Class

A

**LOCATION AND ROUTE INFORMATION**

2. District	12	3. County	GEA
4. Route	SR 43	5. Straight Line Mileage	0.398
6. Latitude	41.35217	7. Longitude	-81.38386
8. Road ID		9. Maintenance Responsibility	S
10. Feature Intersection			

**CULVERT**

11. Year Built	1931	12. Number of Cells	1
13. Shape	1	14. Material	5
15. Span (in.)	12	16. Rise (in.)	12
17. Length (ft.)	56	18. Gage (no.) / Wall Thickness (in.)	
19. Gage (no.) / Wall Thickness (in.)		20. Type of Protection	1
21. Slope of Pipe (%)	0.89	22. Skew (degrees)	
23. Inlet End Treatment	2	24. Outlet End Treatment	9
25. Maximum Height of Cover (ft.)	4	26. Modification Type	
27. Year Modified		28. Modification Material	
29. Modification Size (in.)			

**EXTENSION - INLET**

30. Year Extended	1972	31. Shape	1
32. Material	1	33. Span (in.)	12
34. Rise (in.)	12	35. Gage (no.) / Wall Thickness (in.)	
36. Extension Length	8		

**EXTENSION - OUTLET**

37. Year Extended	2002	38. Shape	1
39. Material	1	40. Span (in.)	12
41. Rise (in.)	12	42. Gage (no.) / Wall Thickness (in.)	
43. Extension Length (ft.)	16		

**HYDROLOGY / HYDRAULICS**

44. Drainage Area (acres)		45. Design Discharge (c.f.s.)	
46. Abrasive Conditions	N	47. pH	
48. Channel Protection (Inlet)	N	49. Channel Protection (Outlet)	X

**COMMENTS:**

SEE GEA-43-0.00 SHEETS 4/9 AND 8/9 FOR ORIGINAL CONSTRUCTION. SEE POR/GEA-43-24.44/0.00 SHEET 12/41 FOR INLET EXTENSION. SEE GEA-43-0.28 SHEETS 3/23 AND 8/23 FOR OUTLET EXTENSION. Needs cleaning. Log in pipe. Embankment caving in at inletOutlet is square catch basin with grate. Inspect Every-Five Years

INVENTORIED BY: LM DATE: 10/28/2009