Inspector:Gerstenslager,MichaelStructure Number:2801779Inspection Date:08/26/2022Facility Carried:USR 422

Bridge Inspection Report

Ohio Bridge Inspection Summary Report

GEA-00422-1226 (2801779)

2: DistrictDistr 77574 - TRO ict 12	OY TWP (GEA county)	5A: Inventory Route 1	00422				
21: Major Maint A/B 01	- State Highway Agency /	7: Facility On USR 422					
225 Routine Main A/B 01	- State Highway Agency /	6: Feature Ints CUY. RIV.	0.78 MI. W 700				
221 Inspection A/B 01 - State Highway Agency /		9: Location 0.78 MI W	SR700				
220: Inv. Location DISTR	ICT 12	Lat, Lon 41.386711	,-81.157806				
	Condition	Str	ructure Type				
58: Deck	9 - Excellent Condition	43: Bridge Type 4 - St	eel continuous				
58.01 Wearing Surface	9 - Excellent	02 - 9	Stringer/Multi-beam or Girder				
58.02 Joint	N- Not Applicable	N- No	ot Applicable				
59: Superstructure	9 - Excellent Condition	45: Spans Main / Approa	ach 3 / 0				
59.01 Paint & PCS	9 - Excellent	107: Deck Type	1 - Concrete Cast-in-Place				
60: Substructure	8 - Very Good Condition	408: Composite Deck Y - Composite Construction					
61: Channel	8	414A Joint Type 1 N - None					
61.01 Scour	7 - Good	414B: Joint Type 2	N - None				
62: Culverts N - Not Applicable 67.01 GA 8		108A: Wearing Surface	1 - Monolithic Concrete (concurrently placed with structural deck) Blank				
07.01 0A		422: WS Date	12/01/2021				
2 "	Appraisal	423: WS Thick (in)	1.0				
Sufficiency Rating	98.1 SD/FO 0 - ND	482: Protective Coating	9 - Paint System IZEU				
36: Rail, Tr, Gd, Term Std	1 1 1 1	183: PCS Date	01/01/1993				
72: Approach Alignment	8 - Equal to present desirable criter	a 453: Bearing Type 1	D - Integral & semi-integral				
113: Scour Critical	8 - Stable for scour conditions		abutment bearings				
71: Waterway Adequacy	8 - Bridge Above Approaches	455: Bearing Type 2					
	Geometric	528: Foundn: Abut Fwd	1 - Steel H Piles (Other size)				
48: Max Span Length (ft)	65.0	533: Foundn: Abut Rear 536: Foundn: Pier 1	1 - Steel H Piles (Other Size)				
49: Structure Length (ft)	,		1 - Steel H Piles (Other size)				
52: Deck Width, Out-To-Out	t (ft) 57.0	539: Foundn: Pier 2	N - None (Such as most Culverts)				
424: Deck Area (sf) 9918		Age	Age and Service				
32: Appr Roadway Width (ft	57.0	27: Year Built/ 106 Reha	ab 1963 / 2021				
51: Road Width, Curb-Curb	(ft) 57.0	42A: Service On	1 - Highway				
50A: Curb/SW Width: Left (f		42B: Service Under	5 - Waterway				
50A: Curb/SW Width: Right	,	28A: Lanes on	02				
34: Skew (deg)	15	28B: Lanes Under	00				
33: Bridge Median	0 - No median	19: Bypass Length	2				
54B: Min Vert Underclearan		29: ADT	13664				
336A: Min Vert Clrnce IR Ca	• •	109: % Trucks (%)	10				
336B: Min V Clr IR Non-Car	• •						
578: Culvert Length (ft)	0	Ins	pections				
	Load Posting	90: Routine Insp.	Months 12 08/26/2022				
·		92A: FCM Insp. N	0				
41: Op/Post/Closed A - Open		92B: Dive Insp. N	0				
-	or above legal loads	92C: Special Insp. N	0				
70.01: Date		92D: UBIT Insp. N	0				
70.02: Sign Type		5 55 mop. 11	v				
	400	92E: Drone Insp. N	0				
734: Percent Legal (%) 704: Analysis Date	120 06/09/2020	92E: Drone Insp. N Inspector Gerstenslag	0				

Inspector: Gerstenslager, Michael **Structure Number:** 2801779 08/26/2022 USR 422 Inspection Date: **Facility Carried:**

Bridge Inspection Report

63: Analysis Method

8 - Load and Resistance Factor Rating (LRFR) rating report by rating factor (RF) method using HL-93 loadings.

Inspector:Gerstenslager, MichaelStructure Number:2801779Inspection Date:08/26/2022Facility Carried:USR 422

Bridge Inspection Report

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
12-Reinforced Concrete Deck	3 - Mod.	9918	sq. ft.	9918	0	0	0
510-Wearing Surfaces		9918	sq. ft.	9918	0	0	0
107-Steel Open Girder/Beam	3 - Mod.	1352	ft.	1352	0	0	0
515-Steel Protective Coating		11496	sq. ft.	11496	0	0	0
215-Reinforced Concrete Abutment	3 - Mod.	161	ft.	160	0	1	0
	CS 3: 1' sealed	spall at for	ward-rig	ht.			
225-Steel Pile	3 - Mod.	26	each	26	0	0	0
	Note: Slight mis	alignment	of new p	iles.			
234-Reinforced Concrete Pier Cap	3 - Mod.	113	ft.	113	0	0	0
310-Elastomeric Bearing	3 - Mod.	16	each	16	0	0	0
312-Enclosed/Concealed Bearing	3 - Mod.	16	each	16	0	0	0
321-Reinforced Concrete Approach Slab	3 - Mod.	2850	sq. ft.	2850	0	0	0
331-Reinforced Concrete Bridge Railing	3 - Mod.	348	ft.	348	0	0	0
815-Drainage	3 - Mod.	4	each	4	0	0	0
840-Approach Slab: Termination or Joint	3 - Mod.	114	ft.	110	4	0	0
	CS 2: Minor rut	ting at both	ends in	painted me	dian.		

Inspector:Gerstenslager,MichaelStructure Number:2801779Inspection Date:08/26/2022Facility Carried:USR 422

Bridge Inspection Report

ODOT District: District 12

GEA-00422-1226 _(2801779)

 Major Maint:
 01 - State Highway Agency
 Facility Carried:
 USR 422
 Traffic On:
 1 - Highway

 Routine Maint:
 01 - State Highway Agency
 Feature Inters:
 CUY. RIV. 0.78 MI. W 700
 Traffic Under: 5 - Waterway

 FIPS Code:
 77574 - TROY TWP (GEA county)
 Location: DISTRICT 12
 0.78 MI W SR700

Inspector Gerstenslager, Michael Inspection Date 08/26/2022 Reviewer Seif, Youssef

Date Built: 07/01/2022 12/01/2021

Insp. 01 - State Highway Agency Resp A:

Insp Resp B:

Inspector Comments - Deck and Approach

Deck

Approach

Approach Wearing Surface

Inspector Comments - General Appraisal

<u>Superstructure</u>

<u>Substructure</u>

Culvert

<u>Inspector Comments - Waterway</u>

Waterway Adequacy

Channel Hydraulic Opening

Maximum water depth at P1 = 6' 7". Maximum water depth at P2 = 6'.

Channel

Scour Critical

Note: piles driven to maximum depth of 85'

Inspector:Michael GerstenslagerStructure Number:2801779Inspection Date:08/26/2022Facility Carried:USR 422

Bridge Inspection Report

Pictures