



### Defect Listing

<b>Pipe Segment Refere...</b> CSO096A0040-CSO096A...	<b>City</b> CLEVELAND	<b>Street</b> E. 26TH ST	<b>Material</b> BRICK	<b>Location C...</b> LIGHT HIGH...	<b>Sewer Use</b> COMBINED
<b>Upstream MH</b> CSO096A0040	Total Length 5	Year Laid	<b>Shape</b> CIRCULAR	Location Details	
<b>DS Manhole</b> CSO096A0038	Length surveyed 5	Year Renewed	<b>Height</b> 18	<b>Width</b> 18	Pipe Joint...

SPR 0	MPR 0	PO Number		<b>Customer</b> KS ASSOC	
SPRI 0	MPRI 0	<b>Work Order</b> G		<b>Purpose</b> ROUTINE ASSESSMENT	
QSR 0000	QMR 0000	<b>Direction</b> DOWNSTREAM	<b>Date</b> 20200203	<b>Media label</b> 001	
OPR 0	<b>Surveyed By</b> Dan_Zaffle	<b>Pre-Cleaning</b> NO PRE-CLEANING	<b>Time</b> 12:12	<b>Weather</b> DRY	
OPRI 0	<b>Certificate Number</b> U-804-1527		<b>End Time</b> 12:13	<b>Additional Info</b>	
Date Cleaned					

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Tee Connection		18			<input type="checkbox"/>	4		
<b>Remarks:</b> CSO096A0040									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
5.0 ft.	Access Point Manhole					<input type="checkbox"/>			
<b>Remarks:</b> CSO096A0038									



### Image Report 4/Page


<b>Pipe Segment Refere...</b> CSO096A0040-CSO096A...	<b>City</b> CLEVELAND	<b>Street</b> E. 26TH ST	<b>Material</b> BRICK	<b>Location C...</b> LIGHT HIGH...	<b>Sewer Use</b> COMBINED
<b>Upstream MH</b> CSO096A0040	Total Length 5	Year Laid	<b>Shape</b> CIRCULAR	Location Details	
<b>DS Manhole</b> CSO096A0038	Length surveyed 5	Year Renewed	<b>Height</b> 18	<b>Width</b> 18	Pipe Joint...



Distance: 0.0 ft.      Grade: 0  
 Condition: Access Point Tee Connection  
 Remarks: CSO096A0040



Distance: 0.0 ft.      Grade: 0  
 Condition: Water Level  
 Remarks: N/A



Distance: 5.0 ft.      Grade: 0  
 Condition: Access Point Manhole  
 Remarks: CSO096A0038