

**CULVERT INSPECTION REPORT**

CR-86 12-03

**283060190**

CULVERT FILE NUMBER 283060190 CULVERT NUMBER GEA SR 306 1.899 YEAR BUILT 1928  
 CO ROUTE SLM ID  
 DISTRICT 12 SHAPE 1 MATERIAL 5 LENGTH 51  
 MAX. HEIGHT OF COVER 9 FEATURE INT. \_\_\_\_\_  
 LATITUDE 41.37513 LONGITUDE -81.33908  
 ENTRY CLASS A NUMBER OF CELLS 1

<b>CULVERT</b>				
1. General	3	2. Culvert Alignment	4	
3. Shape		4. Seams or Joints	5	
5. Slab		6. Abutments		
7. Headwalls	0	8. End Structure		
<b>CHANNEL</b>				
9. Channel Alignment	8	10. Protection	8	
11. Culvert Waterway Blockage	8	12. Scour	3	
<b>APPROACHES</b>				
13. Pavement	6	14. Guardrail	7	
15. Embankment	4			
16. Level of Inspection	X	<b>GENERAL APPRAISAL &amp; OPERATIONAL STATUS</b>	4	A

RECOMMENDED REPAIR CODE(S): \_\_\_\_\_

## COMMENTS:

inlet and outlet blocked with debris. needs to be ditched. disjointed segments throughout pipe. last 5 segments at the outlet end are slipping down and dislocated. dip in pavement. dip in guardrail and sinking at outlet side. pavement has longitudinal pull cracks as if sliding down the hill side.

INSPECTED BY: WG DATE: 4/3/2013 REVIEWED BY: \_\_\_\_\_ DATE: \_\_\_\_\_