

CULVERT INSPECTION REPORT

CR-86 12-03

430842652

CULVERT FILE NUMBER _____ CULVERT NUMBER LAK SR 84 26.520 _____ YEAR BUILT 2006
 CO ROUTE SLM ID
 DISTRICT 12 SHAPE 1 MATERIAL 1 LENGTH 65
 MAX. HEIGHT OF COVER 0 FEATURE INT. JUST WEST OF TOWNLINE ROAD.
 LATITUDE 41.75928917 LONGITUDE -81.10275667
 ENTRY CLASS B NUMBER OF CELLS 1

CULVERT				
1. General	9	2. Culvert Alignment	9	
3. Shape		4. Seams or Joints	8	
5. Slab		6. Abutments		
7. Headwalls		8. End Structure		
CHANNEL				
9. Channel Alignment	7	10. Protection	6	
11. Culvert Waterway Blockage		12. Scour	4	
APPROACHES				
13. Pavement	9	14. Guardrail	9	
15. Embankment	4			
16. Level of Inspection	M	GENERAL APPRAISAL & OPERATIONAL STATUS	8	A

RECOMMENDED REPAIR CODE(S): _____

COMMENTS:

NO HEADWALLS. GROUTED ROCK CHANNEL PROTECTION IS SLIDING. DEEP SCOUR AT OUTLET . UPSTREAM CHANNEL HAS LARGE TREES IN IT. EMBANKMENT UNDER GUARDRAIL ERODING FROM PAVEMENT RUNOFF AND BEGINNING TO MAKE ITS WAY TOWARDS THE WB SHOULDER

INSPECTED BY: WG DATE: 1/10/2012 REVIEWED BY: _____ DATE: _____