# STATE OF OHIO DEPARTMENT OF TRANSPORTATION

BRIDGE NUMBER

BRIDGE INSPECTION REPORT

LAK 00090 0645 R 1960 YEAR BUILT

4303938				
Structure File Number				

IST 12 Bridge Type 322 TYPE SERVICE	15	CHAGRIN RIV E BR MP 192.6	
DECK out/out 56.3 Deck Area 14,930 sqlt 1 REINF CONCRT (PRESTRSD, PRECAST	1	4 DENSE CONCRETE (IOWA SYSTEM) OVERLAY D ME ADINO OLIDEA OF Thk 2 Wear Date 12/15/1995	1
1. FLOOR	-	2. WEARING SURFACE	
3. CURBS, SIDEWALKS AND WALKWAYS		4. MEDIAN Lanes on 3	
5. RAILING D 42° DEFLECTOR-TYPE PARAPET (NJ SHAP	1	6. DRAINAGE 3 SCUPPERS & DWINSPTS	1
7. EXPANSION JOINTS 2 SLIDING METAL PLATE ANGLE	1	8. SUMMARY	7
SUPERSTRUCTURE	1	3 RIVETED BUILT-UP STEEL	2
9. ALIGNMENT	1	10. BEAMS/GIRDERS/SLAB	
11. DIAPHRAGMS or CROSSFRAMES	<u> </u>	12. JOISTS/STRINGERS	
13. FLOOR BEAMS		14. FIOOR BEAM CONNECTIONS	
15. VERTICALS		16. DIAGONALS	
17. END POSTS		18. UPPER CHORD	
19. LOWER CHORD		20. GUSSET PLATES	
21. LATERAL BRACING		22. SWAY BRACING	
23. PORTALS		24. BEARING DEVICES <sup>2 ROCKERS</sup>	1
25. ARCH		26. ARCH COLUMNS or HANGERS	
27. SPANDREL WALLS		Paint Date 1/1/1982 28. PROTECTIVE COATING SYSTEM 4 PAINT SYSTEM B	7
29. PINS/HANGERS/HINGES		30. FATIGUE PRONE DETAIL (E, E')	1
	s		6
31. LIVE LOAD RESPONSE (E OR S) SUBSTRUCTURE		5 STUB GRAVITY	
33. ABUTMENTS 5 STUB GRAVITY	1	34. ABUTMENT SEATS Abutment: ON PILING 3 CANTILEVER(TEE) SOLID PANEL	1
35. PIERS	1	3 GAN ILEVER(TEE) SOLID PAREL 36. PIER SEATS Piers: NOT ON PILING	1
37. BACKWALLS	1	38. WINGWALLS	1
Piers = 02 NN NN 39. FENDERS and DOLPHINS Spans = 3		40. SCOUR (INSP TYPE - 1,2,3) 2	1
41. SLOPE PROTECTION 2 STONE (NO.1 AGGREGATE)	2	42. SUMMARY	7
CULVERTS			
43. GENERAL N NONE/NOT APPLICABLE		44. ALIGNMENT	-
45. SHAPE Culvert Length 0		46. SEAMS	
47. HEADWALLS or ENDWALLS		48. SCOUR (INSP TYPE - 1,2,3)	
49. ABUTMENT		50. SUMMARY	
CHANNEL	1	N NONE	
51. ALIGNMENT 8 SLIGHT CHANCE OVERTOPPING APPR	1	52. PROTECTION	7
53. HYDRAULIC OPENING APPROACHES		54. SUMMARY	
55. PAVEMENT 2 BITUMINOUS	1	56. APPROACH SLABS	2
57. GUARDRAIL 1 STEEL BEAM	1	58. RELIEF JOINTS	
59. EMBANKMENT	2	60. SUMMARY Percent Legal = 150	6
GENERAL 61. NAVIGATION LIGHTS		62. WARNING SIGNS	1
Signs on = N			
63. SIGN SUPPORTS Under C = 0 Under NC = 0	N	64. UTILITIES	6
			0

SIGNED

Name MICHAEL SUTAK

Name YOUSSEF SEIF

PE Number SIGNED

1 0 0 0 N N N N SURVEY

PE Number

1

FLOOR: LEACHED CRACKS. MINOR HAUNCH SPALLS. FLOOR <1% DETERIORATED. WEARING SURFACE: CRACKS. FEW SHALLOW SPALLS. WS <1% DETERIORATED. RAILING: MINOR CRACKS. DRAINAGE: AREAS OF RUSTED SECTION LOSS & FEW RUSTED

THRU HOLES TO DOWN SPOUTS. DEBRIS IN BOTH BERMS.

## SUPERSTRUCTURE

DECK

GIRDERS: RUSTED SECTION LOSS AT ABUTMENTS. & TO FASCIAS @ LOWER FLANGES. SMALL THRU HOLES TO LOWER FLANGE OF RIGHT FASCIA @ REAR. RUSTED THRU HOLE TO LEFT FASCIA BEHIND BEARING @ REAR. FLANGE ANGLES ARE STICH WELDED (2" STICH WELDS ON 12" CENTERS) TO BOTH WEB & FLANGE PLATES IN POSTIVE MOMENT AREAS. XFRAMES: ENDFRAME RUSTED SECTION LOSS. BEARINGS: AREAS OF FRETTING TO ROCKERS. BOLSTER #2 ON P1

IS MISSING 2 FASTENERS.

PCS: BEAM ENDS PAINTED IN 2002. AREAS OF PEELING PAINT. 1-5% RUST. PCS IS 1-5% DETERIORATED.

FPD: 2" STITCH WELDS ON 12" CENTERS.

### SUBSTRUCTURE

ABUTMENTS: CRACKS. MINOR DELAMS. PIERS: VERTICAL CRACKS IN CAPS OF PIERS. THRU CRACK IN CAP OF PIER #2 BELOW BAY #5. BACKWALLS: CRACKS. MINOR SPALLS & DELAMS. MINOR HONEYCOMBING. WINGWALLS: FORWARD RIGHT WINGWALL HAS CRACKS INTO CHEEKWALL. SLOPE PROTECT: TOP 4" OF REAR ABUT FOOTER ARE EXPOSED BELOW RIGHT BAY NEAR SCUPPERS. TOP 2" OF FORWARD ABUT FOOTER EXPOSED BELOW BAY #2. FORWARD SLOPE EROSION UNDER LEFT SCUPPERS. CHANNEL/SLOPE EROSION NEAR PIERS #1 & #2.

SCOUR: SOME EROSION NEAR PIERS.

### APPROACHES

PAVEMENT: CRACKS. ASPHALT PATCHES. ASPHALT BREAK UP. SLAB: BOUNCE ONTO BRIDGE. EMBANKMENT: EROSION TO FORWARD-RIGHT EMBANKMENT.

## GENERAL

NO FORWARD-LEFT TRANSITION/RAIL/ET. SNOOPER INSPECTION IN 2013. INSPECTED WITH DB IN 2013.