

Randy
Wilson/Production/D09/ODOT

02/07/2007 01:48 PM

To Tom Barnitz/Production/D09/ODOT@ODOT, John
Wetzel/Production/D09/ODOT@ODOT
cc Tom Corbin/Production/D09/ODOT@ODOT

bcc

Subject SCI-823-6.81 (Phase 1) - Stage 1 Utility Comments

Tom/John

I field reviewed the project on 1/11/07. Since the utilities on a job this size typically are at intersecting roads, I will categorize my comments in areas of the job. My comments are as follows:

Shumway Hollow Interchange/SR 335 area

- (1) The consultant seems to have shown the utility poles correctly.
- (2) The consultant seems to have shown the underground telephone line (Sprint) located within the railroad right of way correctly.
- (3) The consultant seems to have shown the underground telephone line along existing Shumway Hollow Road correctly.
- (4) The consultant seems to have shown the water line along SR 335 (south of station 11+00 and back to the airport) correctly, but the location of the water line along SR 335 from station 11+00 to the north end of the work is not shown. The consultant needs to investigate this matter and depict the water line location in this area. Also, there is a rather larger lid right of station 8+75 between the water main and the church parking lot. It is likely a water meter lid, but the consultant needs to investigate and confirm the type of utility it is for.
- (5) There is no apparent aerial telephone facilities along SR 335, but there is evidence an underground facility may exist about where the work along SR 335 ends at station 15+00. It appears this facility may go east toward the airport and then turn and run south (crossing TR 234 around station 42+00). The consultant needs to investigate this matter and depict the telephone facilities.

Swauger Valley Road area

- (1) The consultant seems to have shown the utility poles correctly. There is an additional existing power pole located approximately 100 feet left of station 442 that the consultant needs to locate and plot on the plan.
- (2) The consultant seems to have shown the water line correctly, but the facility is not shown as far south along the county road as the work limits extend to. The consultant needs to investigate this matter and depict the water line location in this area.
- (3) There is an "old looking" telephone pedestal just south of the "house to be removed" left of station 443+00. There may be underground telephone facilities in this area. The consultant needs to investigate and confirm whether or not there are any underground facilities.

SR 139 area

- (1) The consultant seems to have shown the utility poles correctly.
- (2) The consultant seems to have shown the water line correctly, but the facility is not shown as far on either side of the mainline as the work limits extend to. The consultant needs to investigate this matter and depict the water line location throughout the entire work limits.

(3) There is evidence of a gas main in this area, and it is not shown on the plan. The consultant needs to investigate this matter and depict the gas main throughout the entire work limits.

(4) There is a telephone pedestal almost on centerline at approximate station 486+25. There may be underground telephone facilities in this area. The consultant needs to investigate and confirm whether or not there are any underground facilities.

(5) Is there some detail of the proposed ditches adjacent to SR 139 where it crosses under SR 823? The existing water line shows up on the bridge detail, but a detail of the proposed ditches will be needed to determine if the water line is affected.

Lucasville - Minford Road Interchange Area

(1) The consultant seems to have shown the utility poles correctly.

(2) The consultant seems to have shown the water line correctly along County Road 28, but the facility is not shown as far on either end as the work limits extend to. In addition, there is evidence of a water line along TR 381, and it is not shown on the plan. The consultant needs to investigate these matters and depict the water line location(s) accordingly.

(3) There are no underground telephone facilities shown on the plan and profile sheets, but the cross section sheets (#434 to 449) depict a buried telephone line. There is a couple of "old looking" telephone pedestals along County Road 28. The consultant needs to investigate this matter and confirm the existence or nonexistence of this underground telephone facility.

(4) There is definite evidence of underground telephone and CATV facilities at the utility pole located at station 10+20 left of centerline. It appears both these facilities cross CR 28 and then proceed westward out of the project. The consultant needs to investigate this matter and depict the telephone and CATV facilities accordingly.

Randy E. Wilson
ODOT District 9 Utilities Coordinator
1-888-819-8501 ext. 774-9075 (Ohio only)
1-740-774-9075
E-mail: randy.wilson@dot.state.oh.us