From: Sidwell, Michelle
Sent: Wednesday, July 3, 2024 8:33 AM
To: Chudzik, Andrew; Taliaferro, Stephen
Cc: Seals, Audrey; Motschenbacher, Gaven
Subject: 2304334 PID 113521 Shaft 63

Good Morning,

We have 1 shaft remaining on this project and it is shaft 63. We have tried 3 times to dig this shaft out and place the beam and have been unsuccessful so far. We do not know what we are hitting, but it keeps kicking the drill bit over and is now bending the drill bit. We tried to pour some concrete in the shaft to get something to grip on but that didn't work either. Do you have any suggestions on next steps or will we have to do some other type of design and abandon this shaft? We have all the other ones completed and they saved this one for last so we will need an answer soon due to the drill needing to move off the project.

Thanks,

Michelle Sidwell, P.E.
Transportation Engineer
ODOT District 5
9600 Jacksontown Road SE
Jacksontown, Ohio 43030
C: 740.899.0978
michelle.sidwell@dot.ohio.gov

Ohio Department of Transportation