

118680 CUY-90 - 20.45 BARRIER SIGN STRUCTURES REPLACED KDH 4/27/2023 1/1

COLLECTOR APP <u>SUP#</u>	<u>LOCATION</u>	<u>PID</u>	INST. <u>YR</u>
SUP 0130250	90 EB @ LAKESHORE BLVD. EXIT	98836	20
SUP 0130251	90 EB @ LAKESHORE BLVD. OVERPASS	98836	20
SUP 0130258	90 EB @ E. 72nd ST.	98830	19
SUP 0130257	90 EB @ E. 72nd ST. EXIT RAMP	103167	21

4/25/2023 Decision was made to replace all overhead sign structures with new ones due to new LRFD standards and steel truss designs.

- Keith D. Hamilton, P.E.

5/3/2023 Two structures will need further review and/or special designs:

- \* I-90 WB truss at E.72nd St. Exit over pedestrian bridge ramp
- \* I-90 WB truss at MLK Exit right end frame on top of retaining wall