



CFN 1972387 DWNSTRM IB

Or, connect these inlet basins?

If the manhole at the base of the embankment could be cleaned and connection to this re-routed broken back (plastic) pipe is confirmed, can an interim connection be provided here between the outlet of the inlet basin and pipe within the mass of concrete (collar)?