
Fw: PID 116663 - HAM-275-5.25 Review Plans - Utility Coordination

From Durbin, Hunter <Hunter.Durbin@hdrinc.com>

Date Wed 2025-12-17 3:46 PM

To 10445264_Terracon-TO A-HAM-275 <10445264_Terracon-TOA-HAM-275@hdrinc.com>

See below for ODOT ITS utility coordination.

Hunter Durbin, PE

D 614.948.1562

hdrinc.com/follow-us

From: Paul.Beck@dot.ohio.gov <Paul.Beck@dot.ohio.gov>

Sent: Wednesday, December 17, 2025 3:39 PM

To: Durbin, Hunter <Hunter.Durbin@hdrinc.com>

Cc: Durham, Paul <Paul.Durham@hdrinc.com>; Braun, Lucas <Lucas.Braun@dot.ohio.gov>

Subject: RE: PID 116663 - HAM-275-5.25 Review Plans - Utility Coordination

CAUTION: [EXTERNAL] This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Hi Hunter,

No, I don't think it is necessary that we review the Stage 3 plans.

Thanks,

Paul Beck, PE

Transportation Engineer

Office of Roadway Engineering

1980 West Broad Street

Columbus, Ohio 43223

C: 614.852.8229

From: Durbin, Hunter <Hunter.Durbin@hdrinc.com>

Sent: Wednesday, December 17, 2025 3:34 PM

To: Beck, Paul <Paul.Beck@dot.ohio.gov>

Cc: Durham, Paul <Paul.Durham@hdrinc.com>; Braun, Lucas <Lucas.Braun@dot.ohio.gov>

Subject: Re: PID 116663 - HAM-275-5.25 Review Plans - Utility Coordination

You don't often get email from hunter.durbin@hdrinc.com. [Learn why this is important](#)

Paul,

Appreciate the quick response and clarification that the ITS utility has been removed and will not be in conflict.

Stage 3 plans are being submitted in April of next year. Would you still like a copy of the Stage 3 plans for ITS utility review given the removal of the only ITS utility in the project area?

Thanks,

Hunter Durbin, PE

D 614.948.1562

hdrinc.com/follow-us

From: Paul.Beck@dot.ohio.gov <Paul.Beck@dot.ohio.gov>
Sent: Wednesday, December 17, 2025 3:02 PM
To: Durbin, Hunter <Hunter.Durbin@hdrinc.com>; Drew.Janek <Drew.Janek@dot.ohio.gov>
Cc: Durham, Paul <Paul.Durham@hdrinc.com>; Braun, Lucas <Lucas.Braun@dot.ohio.gov>
Subject: RE: PID 116663 - HAM-275-5.25 Review Plans - Utility Coordination

CAUTION: [EXTERNAL] This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Hi Hunter,

This was an old advisory radio sign. You can see it in streetview from 2019. It has recently been removed. I just deactivated it in our system, so it shouldn't show up anymore.

[I-275 - Google Maps](#)

Also, Drew has moved to the Office of Safety so no need to include him on ITS questions.

Paul Beck, PE

Transportation Engineer

Office of Roadway Engineering

1980 West Broad Street

Columbus, Ohio 43223

C: 614.852.8229

From: Durbin, Hunter <Hunter.Durbin@hdrinc.com>
Sent: Wednesday, December 17, 2025 12:41 PM
To: Beck, Paul <Paul.Beck@dot.ohio.gov>; Janek, Drew <Drew.Janek@dot.ohio.gov>
Cc: Durham, Paul <Paul.Durham@hdrinc.com>; Braun, Lucas <Lucas.Braun@dot.ohio.gov>
Subject: Re: PID 116663 - HAM-275-5.25 Review Plans - Utility Coordination

Some people who received this message don't often get email from hunter.durbin@hdrinc.com. [Learn why this is important](#)

Good afternoon Drew and Paul,

I'm following up on the email below regarding ITS utility coordination for PID 116663 – HAM-275-5.25 landslide repair. Please see additional details regarding the project below.

During the initial utility coordination, an ITS cabinet was flagged near the project area. The attached screenshot from ODOT TIMS shows the project limits and the cabinet with its ID number. The cabinet is located approximately 0.34 miles south of the project limits.

Please confirm that you agree there is no conflict between the cabinet and the project.

Thank you,

Hunter Durbin, PE

D 614.948.1562

hdrinc.com/follow-us

From: Durbin, Hunter <Hunter.Durbin@hdrinc.com>

Sent: Friday, November 21, 2025 4:20 PM

To: Drew.Janek <Drew.Janek@dot.ohio.gov>

Cc: Durham, Paul <Paul.Durham@hdrinc.com>; Braun, Lucas <Lucas.Braun@dot.ohio.gov>

Subject: PID 116626 - HAM-275-5.25 Review Plans - Utility Coordination

Good afternoon,

At the link below, you will find plans as they were transmitted to the Ohio Department of Transportation, District 8 for the Stage 2 Review of the HAM-275-5.25 Landslide Repair project. The project is located approximately 5 miles east of the Ohio border along I-275 and involves the construction of a 150-foot drilled shaft retaining wall along the exterior southbound shoulder of I-275 and associated drainage and pavement repair work. There are no known underground utilities within the construction limits of the project.

Please review and confirm that your existing facilities are not located within the project area and will not be impacted. If your existing facilities are present within the project area please include line size, depth/vertical clearances and any other pertinent information necessary for HDR to determine if relocation will be necessary or if minor design changes can be accommodated to avoid conflict.

Please return any comments or information on your facilities to us by Friday, December 19th. If you have any questions, please let me know.



[PID 116663 - HAM-275-5.25 - Stage 2 Plans.pdf](#)

Thank you,

Hunter Durbin, PE

Highway Engineer

HDR

8890 Lyra Drive, Suite 100

Columbus, OH 43240

D 614.948.1562

Hunter.Durbin@hdrinc.com

hdrinc.com/follow-us

CAUTION: This is an external email and may not be safe. If the email looks suspicious, please do not click links or open attachments and forward the email to csc@ohio.gov or click the Phish Alert Button if available.