

ALIGNMENT AND PROFILE

THE WORK PROPOSED BY THIS PROJECT CONSISTS OF MICROSURFACING OF THE EXISTING PAVEMENT. THE ALIGNMENT OF THE EXISTING PAVEMENT WILL NOT BE CHANGED AND THE PROFILE OF THE PROPOSED SURFACE WILL BE SIMILAR TO THAT OF THE EXISTING PAVEMENT.

COORDINATION OF WORK:

LOG-33-15.67 (PID 101175)
LOG-CS-FY2021 (PID 113075)
D07-CHIP-FY21B (PID 109708)

THE CONTRACTOR IS ADVISED THAT ADJACENT CONSTRUCTION PROJECTS WITHIN OR NEAR THE WORK LIMITS OF THIS PLAN MAY IMPACT THE PROJECT SCHEDULE, SEQUENCE OF CONSTRUCTION AND/OR TRAFFIC CONTROL BETWEEN ADJACENT ZONES. THE CONTRACTOR IS REQUIRED TO COORDINATE ALL MAINTENANCE OF TRAFFIC OPERATIONS WITH ADJACENT CONSTRUCTION PROJECTS. COOPERATION WITH THE ENGINEER, INSPECTORS AND ALL OTHER CONTRACTORS ON OR ADJACENT TO THE PROJECT IS REQUIRED PER CMS 105.08.

**ITEM 253 - PAVEMENT REPAIR, AS PER PLAN (A)
ITEM 253 - PAVEMENT REPAIR, AS PER PLAN (B)**

PAVEMENT REPAIR SHALL BE IN ACCORDANCE WITH ITEM 253 - PAVEMENT REPAIR, WITH THE FOLLOWING ADDITIONS:

THE ENGINEER SHALL DESIGNATE THE LOCATIONS AND LIMITS OF THE AREAS TO BE REPAIRED. THE AREAS SHALL BE ROUGHLY RECTANGULAR IN SHAPE AND SAWED OR MILLED TO A NEAT LINE. THE DEPTH OF REMOVAL, AS DIRECTED BY THE ENGINEER, SHALL BE SUFFICIENT TO REMOVE ALL DETERIORATED PAVEMENT. THE ENTIRE AREA INCLUDING VERTICAL FACES SHALL BE COATED PRIOR TO PLACING THE REPLACEMENT MATERIAL PER 253.03.

PAVEMENT REPAIR (A) AREAS SHALL BE A MINIMUM OF 12.5 FEET IN WIDTH, 25 FEET IN LENGTH AND 4 INCHES IN DEPTH OR AS DIRECTED BY THE ENGINEER. THE REPLACEMENT MATERIAL SHALL BE ITEM 442, ASPHALT CONCRETE INTERMEDIATE COURSE, 9.5 MM, TYPE A, (448) AND FINISHED TO MATCH THE EXSTING PAVEMENT SURFACE. SEALING THE PERIMETER OF THE REPAIR AREA PER 253.03 IS INCLUDED IN THE PAYMENT OF ITEM 253.

PAVEMENT REPAIR (B) AREAS ALONG THE LANE AND EDGE LINES SHALL BE A MINIMUM OF 2 FEET IN WIDTH AND 4 INCHES IN DEPTH OR AS DIRECTED BY THE ENGINEER. THE REPLACEMENT MATERIAL SHALL BE ITEM 442, ASPHALT CONCRETE INTERMEDIATE COURSE, 9.5 MM TYPE A, (448), AND FINISHED TO MATCH THE EXSTING PAVEMENT SURFACE. SEALING THE PERIMETER OF THE REPAIR AREA PER 253.03 IS INCLUDED IN THE PAYMENT OF ITEM 253.

THE FOLLOWING ESTIMATED QUANTITIES HAVE BEEN CARRIED TO THE GENERAL SUMMARY TO BE USED AS DIRECTED BY THE ENGINEER.

ITEM 253 - PAVEMENT REPAIR, AS PER PLAN (A) = 1500 SQ YD
ITEM 253 - PAVEMENT REPAIR, AS PER PLAN (B) = 5500 SQ YD

PAVEMENT MARKINGS

IT SHALL BE THE RESPONSIBILITY OF THE CONTRACTOR TO DOCUMENT THE LAYOUT OF THE EXISTING PAVEMENT MARKINGS INCLUDING EXISTING LANE AND SHOULDER WIDTHS IN A LOG AND SUBMIT TO THE DEPARTMENT FOR ACCEPTANCE. THE DEPARTMENT WILL NOT ALLOW THE CONTRACTOR TO PERFORM ANY PAVEMENT WORK FUNCTIONS (MILLING, OVERLAY, ETC.) UNTIL ACCEPTANCE OF THE SUBMITTED EXISTING MARKING LOG.

MARKINGS SHALL REPLACED IN KIND EXCEPT WHERE EXISTING MARKINGS DO NOT MEET THE CURRENT STANDARD CONSTRUCTION DRAWINGS. THE CONTRACTOR SHALL COORDINATE AND CORRABORATE THE PROPOSED LAYOUT OF ALL PAVEMENT MARKINGS PER APPLICABLE STANDARD CONSTRUCTION DRAWINGS WITH ODOT.

NO PERMANENT PAVEMENT MARKINGS, RAISED PAVEMENT MARKERS, NOR RUMBLE STRIPS SHALL BE PLACED UNTIL THE ODOT PROJECT ENGINEER HAS APPROVED THE LOCATION AND/OR LAYOUT OF THE WORK ZONE PAVEMENT MARKINGS.

PAVEMENT MARKINGS ON INTERSECTING ROADWAYS

THE EDGE LINE SHALL BE CONTINUED AROUND ALL RADII TO MATCH THE EXISTING EDGE LINE OF THE INTERSECTING ROUTE. IF THE INTERSECTING ROUTE HAS A CENTER LINE MARKING, THE CENTER LINE SHALL BE RE-STRIPED OVER THE AREA OF RESURFACING.

PROTECTION OF THE MAD RIVER WATER TRAIL

THE CONTRACTOR MUST ENSURE THAT THE MAD RIVER CHANNEL IN THE VICINITY OF SLM 21.10 REMAINS OPEN TO BOAT TRAFFIC. IF NECESSARY TO PROTECT BOATERS DURING OVERHEAD WORK, THE CONTRACTOR MAY DIRECT BOATERS THROUGH SIGNAGE OR A LOOKOUT TO STEER TO A SPECIFIC SIDE OF THE CHANNEL.

PROJECT SCHEDULE

NO WORK SHALL BEGIN ON THE PROJECT UNTIL JUNE 1, 2021.

I:\Project+Data\LOG\101175_US33-1567\Design\Roadway\Sheets\101175_GN001.dgn Sheet 12/3/2020 1:45:39 PM cweiss

CALCULATED
TMK
CHECKED
CWW

GENERAL NOTES

LOG-33-15.66

3

