


D15 Receptor ID  
63.9 Sound Level without Noise Wall | Impacts in RED  
3.1 Reduction from Wall | Benefits in GREEN

- Recommended Noise Wall
- Receptor Impacted and Benefited
- Receptor NOT Impacted but Benefited
- Receptor NOT Impacted and NOT Benefited




**Figure 6b**  
**Noise Sensitive Area D**  
(NSA D)  
Type II Noise Wall Retrofit  
TRU-80 | PID 108492  
Trumbull County, Ohio






**E20 Receptor ID**  
 65.4 Sound Level without Noise Wall | Impacts in **RED**  
 4.8 Reduction from Wall | Benefits in **GREEN**

- Recommended Noise Wall
- Receptor Impacted and Benefited
- Receptor NOT Impacted but Benefited
- Receptor NOT Impacted and NOT Benefited



**Figure 8a**  
**Noise Sensitive Area E**  
 (NSA E) - West of Logan Way  
 Type II Noise Wall Retrofit  
 TRU-80 | PID 108492  
 Trumbull County, Ohio





**E50** Receptor ID  
 57.1 Sound Level without Noise Wall | Impacts in **RED**  
 4.2 Reduction from Wall | Benefits in **GREEN**

- Recommended Noise Wall
- Receptor Impacted and Benefited
- Receptor NOT Impacted but Benefited
- Receptor NOT Impacted and NOT Benefited



**Figure 8b**  
**Noise Sensitive Area E**  
 (NSA E) - East of Logan Way  
 Type II Noise Wall Retrofit  
 TRU-80 | PID 108492  
 Trumbull County, Ohio

