



Photo 1: Lack of pedestrian infrastructure along Front Street (looking south) from new bridge over Muskingum River.

Source: OMEGA



Photo 2: Unimproved shoulder with evidence of foot traffic (looking northwest towards bridge). Source: OMEGA



Photo 3: View along pathway from Philo to Duncan Falls.

Source: OMEGA



Photo 4: View towards Philo from bridge

Source: OMEGA