

Abel, Albert

From: Abel, Albert
Sent: Friday, January 11, 2013 1:09 PM
To: Zigan, Curtis
Subject: RE: Gue-77-1474L&R,Gue-40-0923
Attachments: 2013 Work order repair pavement.pdf; 2013 Work order repair pavement.pdf

Curtis,

1. No the bridge crew did not repair the tops of the backwalls on GUE-77-1474L/R but I created work orders to repair the pavement, see attached.
2. I do not know what is causing the bottom of GUE40-0923 to deform. You should look at it some time.

Albert

From: Zigan, Curtis
Sent: Monday, November 05, 2012 1:22 PM
To: Abel, Albert
Subject: Gue-77-1474L&R,Gue-40-0923

Albert,

Did the bridge Crew fix the top of the backwall/ exp. Jt. on Gue-77-1474L&R.

Gue-40-0923 is the issues with the bottom of the culvert under the road. Does it look like the city bored under the pipe.

Call me sometime.

Thanks
Curtis