



7-3-2002 L




7-3-2002 L



7-3-2002 L



7-3-2002 L



7-3-2002 L



7-3-2002 . left



17-3-2002

L




7-3-2002



7-3-2002

7-3-02



Beam # 2
GUE-70-0943L

7-3-02



Beam # 2
GUE-70-0943L


7-3-02

7-3-02




Beam # 2
GUE-70-0943L

7-3-02



Beam # 2
GUE-70-0943L



Beam # 2
GUE-70-0943L


7-3-2002

TOP FLANGE COE IMPACT

BAY #1 @ Impact 109"
 BAY #3 112"

Cross frame Tors loose @
 Beam #2 @ Impact
 Bent in Bay #1 @ Impact

GUS-70-0;
 7-3-01
 Hit
 S-1
 \$6



Plum
 out
 STIFFENER
 10500
 7.1 C

OUT
 OF
 PLUM

~~CROSS
 BRACING~~

With String on Bottom F.
 out of line 2 1/4"
 Beam Flange Bent up 1 1/4" @ 1.
 for @ R
 Impact

7-3-2002